



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 3 of 93

Rating item: C1 Air Cond & Press

Item n°	Part number / Model series	Full part numbers / Models	Description	Manufacturer	CMM / ATA chapter	Work scope Level / Component maintenance shop
Air Cooling System Components Maintenance						
1.	749A0000-series, 2056A0000-series, 2056B0000-series, 2056C0000-series	749A0000-02 749A0000-02 AMDT A 749A0000-02 AMDT B 2056A0000-02 2056A0000-02 AMDT A 2056B0000-01 2056B0000-01 AMDT A 2056C0000-01	PLENUM	Liebherr	21-52-07	Repair A/C Component maintenance shop, or [A/C CMS] below
2.	2071A0000-01	2071A0000-01	PLENUM	Liebherr	21-52-69	Repair [A/C CMS]

Rating item: C3 Comms and Nav (Communications and Navigation)

Item n°	Part number / Model series	Full part numbers / Models	Description	Manufacturer	CMM / ATA chapter	Work scope Level / Component maintenance shop
A/C Interphone's Components maintenance						
3.	1046GT2102XX	1046GT2102AY 1046GT2102F 1046GT2102G	Headset	HOLM Co	23-51-06	Overhaul [A/C CMS]
4.	89-01-series	89-01-07000, 89-01-07002 89-01-07010, 89-01-07020 89-01-07030, 89-01-07032 89-01-07035, 89-01-07040 89-01-07042, 89-01-07045 89-01-07052, 89-01-07062 89-01-07065, 89-01-07067 89-01-07112, 89-01-07117 89-01-07122, 89-01-07125 89-01-07126, 89-01-07127 89-01-07130, 89-01-07142 89-01-07147, 89-01-07152 89-01-07154, 89-01-07155 89-01-07157, 89-01-07162 89-01-07172, 89-01-07182 89-01-07185, 89-01-07187 89-01-07202, 89-01-07212 89-01-07222, 89-01-07232 89-01-07235, 89-01-07237 89-01-07240, 89-01-07250 89-01-07260, 89-01-07270 89-01-07282, 89-01-07285 89-01-07292, 89-01-07295 89-01-07332, 89-01-07335 89-01-07337, 89-01-07340 89-01-07350, 89-01-07360 89-01-07375, 89-01-07377 89-01-07390, 89-01-07405 89-01-07410, 89-01-07420 89-01-07430, 89-01-07462 89-01-07465	Telephone Handset	HOLM Co	23-73-01	Overhaul [A/C CMS]
5.	85-16-series	85-16-06343-05, 85-16-06961-05 85-16-08836-05, 85-16-09502-05 85-16-11494-05, 85-16-12022-05	Hand Held Microphone	HOLM Co	23-51-38	Overhaul [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 4 of 93

6.	64000-series	Model 5x5 PRO III Part numbers: 64000-000, 64000-100 64000-001, 64000-101 64000-002, 64000-102 64000-003, 64000-103	Headset	Telex	23-50-05	Overhaul [A/C CMS]
7.	64300-series	64300-200, 64300-205 64300-208, 64300-210 64300-212, 64300-218 64300-219, 64300-220 64300-300	Airman 750 Headset	Bosch Communications, Inc.	F.01U.311.532	Overhaul [A/C CMS]
8.	5145-series	5145-1-24, 5145-1-24A (10-62090-24) 5145-1-40, 5145-1-40A (10-62090-40) 5145-1-43, 5145-1-43A (10-62090-43) 5145-1-44, 5145-1-44A (10-62090-44) 5145-1-46, 5145-1-46A (10-62090-46) 5145-1-47, 5145-1-47A (10-62090-47) 5145-1-48, 5145-1-48A (10-62090-48) 5145-1-60, 5145-1-60A (10-62090-60) 5145-1-61, 5145-1-61A (10-62090-61) 5145-1-62A, 5145-1-62B (10-62090-62) 5145-1-63, 5145-1-63A (10-62090-63) 5145-1-65, 5145-1-65A (10-62090-65) 5145-1-70, 5145-1-70A (10-62090-70) 5145-1-71, 5145-1-71A (10-62090-71)	Audio Control Panels	Avtech tyee, Inc	23-50-15	Overhaul [A/C CMS]
9.	5145-64-series	5145-1-64, 5145-1-64 Mod A, 5145-1-64 Mod B, 10-62090-64	Audio Control Panels	Avtech tyee, Inc	23-51-23	Overhaul [A/C CMS]
10.	285W0024-series	285W0024-5SP 285W0024-7SP 285W0024-8SP 285W0024-9SP Modification ref. IPL Section of CMM 23-42-15	Cabin Attendant / Flight Deck Handset Module Assembly	BAE Systems	23-42-15	Overhaul [A/C CMS]
11.	285W0024-series	285W0024-4A 285W0024-1SP 285W0024-4SP 285W0024-10SP 285W0024-11SP 285W0024-1B 285W0024-1G 285W0024-1H 285W0024-1J 285W0024-1L 285W0024-11L 285W0024-1M 285W0024-10B 285W0024-10C 285W0024-10H 285W0024-10E	Cabin Attendant / Flight Deck Handset Module Assembly	BAE Systems	23-42-01	Overhaul [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 5 of 93

		285W0024-10G 285W0024-10L 285W0024-10J Modification ref. IPL Section CMM 23-42-01				
--	--	---	--	--	--	--

Rating item: C4 Doors – Hatches / Repair

Item n°	Part number / Model series	Full part numbers / Models	Description	Manufacturer	SRM / ATA chapter	Work scope Level / Component maintenance shop
A/C Doors – Hatches / Repair						
A/C Airbus A320						
12.	D521100010005X	D5211000100053 D5211000100054 D5211000100055 D5211000100056 D5211000100057 D5211000100058 D5211000100059	DOOR ASSY- FWD PAX	AIRBUS	521100	Repair A/C Repair Shop [A/C SRS]
13.	D52112003000XX	D52112003000AE D52112003000AG D52112003000AI	DOOR ASSY- FWD PAX	AIRBUS	521100	Repair [A/C SRS]
14.	D521100010015X	D5211000100153 D5211000100154 D5211000100155 D5211000100156 D5211000100157 D5211000100158 D5211000100159	DOOR ASSY- FWD PAX	AIRBUS	521100	Repair [A/C SRS]
15.	D521110010005X	D5211100100053 D5211100100054 D5211100100055 D5211100100056 D5211100100057 D5211100100058 D5211100100059	DOOR ASSY- AFT PAX	AIRBUS	521300	Repair [A/C SRS]
16.	D52113003000AX	D52113003000AA D52113003000AE D52113003000AG D52113003000AI	DOOR ASSY- AFT PAX	AIRBUS	521300	Repair [A/C SRS]
17.	D521110010015X	D5211100100153 D5211100100154 D5211100100155 D5211100100156 D5211100100157 D5211100100158 D5211100100159	DOOR ASSY- AFT PAX	AIRBUS	521300	Repair [A/C SRS]
18.	D52113003000AX	D52113003000AJ D52113003000AM D52113003000A0 D52113003000AS D52113003000AT D52113003000AW D52113003000AZ D52113003000BF D52113003001AJ D52113003001AM D52113003001A0 D52113003001AS D52113003001AT D52113003001AW	DOOR ASSY- AFT PAX	AIRBUS	521300	Repair [A/C SRS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 6 of 93

19.	D52113003000BX	D52113003000BI D52113003000BM D52113003001BI D52113003001BM	DOOR ASSY- AFT PAX	AIRBUS	521300	Repair [A/C SRS]
20.	D522790020XXXX	D5227900200700 D5227900200352 D5227900200353 D5227900200354 D5227900200552 D5227900200553 D5227900200554 D5227900200556 D5227900200751 D5227900200752 D5227900200753 D5227900200754 D5227900200755 D5227900200756 D5227900200757 D5227900200758 D5227900200759 D5227900200900 D5227900201100 D5227900201300 D5227900201500 D5227900201700 D5227900201900 D5227900209151 D5227900209152 D5227900209153 D5227900209159	DOOR ASSY- EMERGENCY	AIRBUS	522000	Repair [A/C SRS]
21.	D522790020XXXX	D5227900200700 D5227900200352 D5227900200353 D5227900200354 D5227900200552 D5227900200553 D5227900200600 D5227900200800 D5227900201000 D5227900201200 D5227900201400 D5227900201800 D5227900201400 D5227900201600 D5227900200900 D5227900201100 D5227900201300 D5227900201500 D5227900201900 D5227900201500 D5227900201700	DOOR ASSY- EMERGENCY EXIT	AIRBUS	522000	Repair [A/C SRS]
22.	D5284000800XXX X	D5284000800200Z D5284000800400Z D5284000800600Z D5284000800300Z D5284000800500Z D5284000800700Z	DOOR ASSY- HINGED FAIRING, MLG	AIRBUS	528000	Repair [A/C SRS]
23.	D5284000800XXX X	D5284000800900A D5284000800800A	DOOR ASSY- HINGED FAIRING	AIRBUS	528000	Repair [A/C SRS]
24.	D5285875200XXX X	D5285875200000A D5285875200100A	DOOR ASSY- HINGED FAIRING	AIRBUS	528000	Repair [A/C SRS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 7 of 93

25.	D5284000000XXX X	D5284000000400Z D5284000000500Z	FAIRING ASSY- LEG,MLG	AIRBUS	528000	Repair [A/C SRS]
26.	D5285600000XXX X	D5285600000000Z D5285600000100Z D5285600000200Z D5285600000300Z	FAIRING ASSY- LEG,MLG	AIRBUS	528000	Repair [A/C SRS]
27.	D5285601000XXX X	D5285601000000Z D5285601000100Z D5285601000200A D5285601000400A D5285601000600A D5285601000300A D5285601000500A D5285601000700A	FAIRING ASSY- LEG,MLG	AIRBUS	528000	Repair [A/C SRS]
28.	D5288XXXXXXX	D52880010000, D52880010001 D52880101000, D52880101001 D52880101002, D52880101003 D52880101004, D52880101005 D52880101006, D52880101007 D52880101008, D52880101009 D52880120000, D52880120001 D52880009000, D52880009001 D52880101000, D52880101001 D52880120000, D52880120001 D52880008000, D52880008001 D52880101000, D52880101001 D52880120000, D52880120001 D52881100000, D52881100001 D52881101000, D52881101001 D52881102000, D52881102001 D52880165000, D52880165001 D52880165002, D52880165003 D52880165004, D52880165005 D52880166000, D52880166001 D52880166002, D52880166003 D52880166004, D52880166005 D52880166008, D52880166009 D52880166010, D52880166011 D52880225000, D52880225001 D52880225002, D52880225003 D52880225004, D52880225005	MLG DOOR ASSY	AIRBUS	528114	Repair [A/C SRS]
29.	D5281011100X	D52810111000, D52810111001 D52810111002, D52810111003 D52810111004, D52810111005 D52810111006, D52810111007	DOOR ASSY- MAIN	AIRBUS	528211	Repair [A/C SRS]
A/C Boeing B737						
30.	141A6160	141A6160-1, 141A6160-2 141A6160-3, 141A6160-4 141A6160-5, 141A6160-6 141A6160-7	DOOR INSTL- ENTRY FWD	BOEING	521000	Repair [A/C SRS]
31.	141A6150	141A6150-1, 141A6150-2 141A6150-3	DOOR ASSY ENTRY FWD	BOEING	521100	Repair [A/C SRS]
32.	002A0003	002A0003-121, 002A0003-122	DOOR ASSY ENTRY FWD	BOEING	521100	Repair [A/C SRS]
33.	147A6100	147A6100-4, 147A6100-5 147A6100-6, 147A6100-13, 147A6100-14, 147A6100-16 147A6100-15, 147A6100-22 147A6100-20, 147A6100-24	DOOR INSTL- ENTRY AFT	BOEING	521300	Repair [A/C SRS]
34.	147A6116	147A6116-1, 147A6116-2	DOOR ASSY-	BOEING	521300	



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 8 of 93

		147A6116-3, 147A6116-4 147A6116-5, 147A6116-10 147A6116-11, 147A6116-12 147A6116-13, 147A6116-14 147A6116-15, 147A6116-16 147A6116-17, 147A6116-18 147A6116-19, 147A6116-20 147A6116-21, 147A6116-22 147A6116-23, 147A6116-24 147A6116-25, 147A6116-26 147A6116-27, 147A6116-28 147A6116-29, 147A6116-30 147A6116-31, 147A6116-32 147A6116-33, 147A6116-35 147A6116-36	ENTRY AFT			Repair [A/C SRS]
35.	411A2103	411A2103-3SP, 411A2103-5SP 411A2103-9B, 411A2103-11B 411A2103-13B, 411A2103-13SP	LINING INSTL- DOOR L/H	BOEING	521131	Repair [A/C SRS]
36.	411A2104	411A2104-7B, 411A2104-4B 411A2104-5C	LINING INSTL- DOOR R/H	BOEING	521131	Repair [A/C SRS]
37.	144A6500	144A6500-1, 144A6500-5 144A6500-9, 144A6500-15 144A6500-19, 144A6500-23 144A6500-27, 144A6500-2 144A6500-6, 144A6500-10 144A6500-16, 144A6500-20 144A6500-24, 144A6500-28	DOOR INSTL- AUTO OVERWING EXIT	BOEING	522000	Repair [A/C SRS]
38.	144A6505	144A6505-1, 144A6505-2 144A6505-3, 144A6505-4 144A6505-5, 144A6505-6 144A6505-7, 144A6505-8 144A6505-9, 144A6505-10 144A6505-11	DOOR ASSY- AUTO. OVERWING EXIT	BOEING	522000	Repair [A/C SRS]
39.	143A6100	143A6100-23, 143A6100-8 143A6100-12, 143A6100-36 143A6110-17, 143A6110-5 143A6110-6, 143A6110-7 143A6110-9, 143A6110-13 143A6110-21, 143A6100-23 143A6110-25, 143A6110-33 143A6110-28, 143A6110-37 143A6110-42, 143A6110-10 143A6110-14, 143A6110-18 143A6110-22, 143A6110-29 143A6110-33, 143A6110-26 143A6110-34, 143A6110-37 143A6110-38, 143A6110-42 143A6110-43, 143A6110-31 143A6110-19, 143A6110-15 143A6110-11, 143A6110-40 143A6110-45	DOOR INSTL- (CARGO COMPARTME NT FWD)	BOEING	523100	Repair [A/C SRS]
40.	146A6100	146A6100-21, 146A6100-13 146A6100-11, 146A6100-28	DOOR INSTL-AFT CARGO COMPARTMENT	BOEING	523100	Repair [A/C SRS]
41.	146A6110	146A6110-4, 146A6110-5 146A6110-6, 146A6110-7 146A6110-8, 146A6110-11 146A6110-13, 146A6110-14 146A6110-17, 146A6110-18 146A6110-21, 146A6110-22 146A6110-25, 146A6110-26 146A6110-28, 146A6100-29 146A6110-32, 146A6110-33	DOOR ASSY- AFT C/C	BOEING	523100	Repair [A/C SRS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 9 of 93

Rating item: C5 Electrical Power

Item n°	Part number / Model series	Full part numbers / Models	Description	Manufacturer	CMM / ATA chapter	Work scope Level / Component maintenance shop
A/C Main Accumulator Battery						
42.	40176-series	40176-4 (015920-000) 40176-7 (016392-000)	Aircraft Battery	SAFT	24-32-03	Overhaul [A/C CMS]
43.	2758	2758	Aircraft Battery	SAFT	24-38-51	Overhaul [A/C CMS]
44.	Type 4579 p/n 018550-000	Type 4579 p/n 018550-000	Aircraft Battery	SAFT	24-31-05	Overhaul [A/C CMS]
45.	Model 539CH-1 (024147-000, BA35-01, S282T003-1)	Model 539CH-1 (024147-000, BA35-01, S282T003-1)	Aircraft Battery	SAFT	24-31-07	Overhaul [A/C CMS]
46.	151CH-series	151CH1	Aircraft Battery	SAFT	24-33-96 Rev 3	Overhaul [A/C CMS]
47.	27578-2	27578-2	Aircraft Battery	SAFT	24-30-99	Overhaul [A/C CMS]
48.	2726CH1	(Hamilton Sundstrand P/N 5912855-01)	Aircraft Battery	SAFT	24-36-01	Repair [A/C CMS]
A/C Alt current Generator Maintenance						
49.	976J - series	976J449-1, 976J498-1 976J498-1R, 976J498-2 976J598-1	A/C Generator	Hamilton Sundstrand	24-20-77	Overhaul [A/C CMS]
Generator Control Unit						
50.	948F458 - Series	948F458-1, 948F458-2 948F458-3, 948F458-4 948F458-5	Generator Control Unit	Hamilton Sundstrand	24-20-01	Repair [A/C CMS]
51.	915F212 - Series (10-61224-3) – Boeing's specification	915F212-4 [10-61224-3] 915F212-5 [10-61224-3] 915F212-6 [10-61224-3] 915F212-7 [10-61224-3] 915F212-8 [10-61224-3]	Generator Control Unit	Hamilton Sundstrand	24-23-30	Repair [A/C CMS]
Bus Protection Panel						
52.	915F213 - Series	915F213-3 915F213-4	Bus Protection Panel	Hamilton Sundstrand	24-20-61	Repair [A/C CMS]
Emergency Power Supply Maintenance						
53.	D717 - series	D717-01-001 D717-02-001	Emergency Power Supply	Page Aerospace Limited	24-35-01	Maintenance up to and including Inspecting and Testing [A/C CMS]
A/C Emergency Accumulator Battery Maintenance						
54.	3214-30	3214-30	Battery	DIEHL	33-51-07	Repair [A/C CMS]
55.	3214-31	3214-31	Battery	DIEHL	33-51-17	Repair [A/C CMS]
Ballast Unit (A/C Lighting System's component) Maintenance						
56.	3250-70	3250-70	Ballast Unit	DIEHL	33-24-15	Repair [A/C CMS]
57.	3250-series	3250-30, 3250-80	Ballast Unit	DIEHL	33-24-16	Repair [A/C CMS]
58.	3250-series	3250-20-10, 3250-31 3250-70-10, 3250-81	Ballast Unit	DIEHL	33-24-17	Repair [A/C CMS]



59.	4197-Series	4197-10 4197-10-01, 4197-10-02 4197-10-03, 4197-10-04 4197-20 4197-20-01, 4197-20-02 4197-20-03, 4197-20-04 4197-30 4197-30-02, 4197-30-03 4197-30-04	ADVANCED INTEGRATED BALLAST UNIT (AIBU)	DIEHL Aerospace	33-24-18	Repair [A/C CMS]
-----	-------------	---	--	--------------------	----------	-------------------------

Retractable Landing Light Maintenance

60.	4315542 4191695 4331772	4315542 4191695 4331772	Retractable Landing Light	ECE- Teleflex- Syneravia	33-42-12	Testing (TASK 33-42-12-700-801-A01), Troubleshooting (TASK 33-42-12-810-801-A01), Disassembly (TASK 33-42-12-040-801-A01), Cleaning (TASK 33-42-12-100-801-A01), Inspection/Check (TASK 33-42-12-200-801-A01), Repair (TASK 33-42-12-350-801-A01), Assembly (TASK 33-42-12-400-801-A01) [A/C CMS]
-----	-------------------------------	-------------------------------	------------------------------	--------------------------------	----------	--

Taxi Light Maintenance

61.	4236564 8000282Y00	4236564 8000282Y00	TAXI LIGHT	ECE- TELEFLEX- SYNERAVIA	33-46-02	Repair [A/C CMS]
-----	-----------------------	-----------------------	------------	--------------------------------	----------	---------------------

Passenger Light Maintenance

62.	Z250H-series	Z250H2101110, Z250H2102110 Z250H2103110, Z250H2111110 Z250H2112110, Z250H2113110	Reading Light Power Unit	Airbus Industrie (S.A.S.)	33-20-10	Repair [A/C CMS]
63.	8ES00523X-SERIES	8ES005238-13, 8ES005237-13 8ES005236-13	Power Unit	Hella KGHueck & Co.	33-22-25	Repair [A/C CMS]

Rating item: C6 Equipment

Item n°	Part number / Model series	Full part numbers / Models	Description	Manufacturer	CMM / ATA chapter	Work scope Level / Component maintenance shop
A/C Cockpit / Cabin passenger seats and seats' covers maintenance						
64.	985- NW125XX	985-NW125A-3L 985-NW125J-3L 985-NW125S-3L 985-NW125AA-3L 985-NW125B-3R 985-NW125K-3R 985-NW125T-3R 985-NW125AB-3R 985-NW125C-3L 985-NW125L-3L 985-NW125U-3L 985-NW125AC-3L 985-NW125D-3R 985-NW125M-3R	Passenger Seat	B/E Aerospace Inc.	25-28-96	Repair [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 11 of 93

		985-NW125V-3R 985-NW125AD-3R 985-NW125E-3L 985-NW125N-3L 985-NW125W-3L 985-NW125JZ-3L 985-NW125F-3R 985-NW125P-3R 985-NW125X-3R 985-NW125KZ-3R 985-NW125G-3L 985-NW125Q-3L 985-NW125Y-3L 985-NW125ACZ-3L 985-NW125H-3R 985-NW125R-3R 985-NW125Z-3R 985-NW125ADZ-3R				
65.	995-NW125 – series	995-NW125A-2L 995-NW125G-2L 995-NW125N-2L 995-NW125B-2R 995-NW125H-2R 995-NW125P-2R 995-NW125C-2L 995-NW125J-2L 995-NW125Q-2L 995-NW125D-2R 995-NW125K-2R 995-NW125R-2R 995-NW125E-2L 995-NW125L-2L 995-NW125S-2L 995-NW125F-2R 995-NW125M-2R 995-NW125T-2R	PassengerSeat	B/E Aerospace Inc.	25-26-76	Repair Repair [A/C CMS]
66.	TAAI3-03 – series	TAAI3-03PE00-01 TAAI3-03CE00-01 TAAI3-03PE01-01 TAAI3-03CE01-01 TAAI3-03PE02-01 TAAI3-03CE02-01 TAAI3-03PE10-01 TAAI3-03CE10-01 TAAI3-03PE11-01 TAAI3-03CE11-01 TAAI3-03PE12-01 TAAI3-03CE12-01 TAAI3-03PE20-01 TAAI3-03CE20-01 TAAI3-03PE21-01 TAAI3-03CE21-01 TAAI3-03PE22-01 TAAI3-03CE22-01 TAAI3-03PE30-01 TAAI3-03CE30-01 TAAI3-03PE31-01 TAAI3-03CE31-01 TAAI3-03PE32-01 TAAI3-03CE32-01	CAPTAIN AND FIRST OFFICER SEAT	STELIA AEROSPACE	25-11-46	Repair [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 12 of 93

67.	TAAI2 – series	TAAI2-13PE00-01 TAAI2-13PE10-01 TAAI2-13PE20-01 TAAI2-13PE30-01 TAAI2-13CE00-01 TAAI2-13CE10-01 TAAI2-13CE20-01 TAAI2-13CE30-01 TAAI2-33PE00-01 TAAI2-33PE20-01 TAAI2-33PE01-01 TAAI2-33PE21-01 TAAI2-33PE10-01 TAAI2-33PE30-01 TAAI2-33PE11-01 TAAI2-33PE31-01 TAAI2-33CE00-01 TAAI2-33CE20-01 TAAI2-33CE01-01 TAAI2-33CE21-01 TAAI2-33CE10-01 TAAI2-33CE30-01 TAAI2-33CE11-01 TAAI2-33CE31-01	POWERED CAPTAIN AND FIRST OFFICER SEAT SEATS	STELIA AEROSPACE	25-11-37	Repair [A/C CMS]
68.	TAAI1-993000 – series	TAAI1-993000-05 TAAI1-993000-06	Captain & FO Seat Armrest, ASSY	STELIA AEROSPACE	25-11-37 25-11-46	Repair [A/C CMS]
69.	TAAI1-404000 – series	TAAI4-404000-01 TAAI4-404000-02 TAAI1-404000-03 TAAI1-404000-04	Captain & FO Seat Armrest, ASSY	STELIA AEROSPACE	25-11-37 25-11-46	Repair [A/C CMS]
70.	985-TZ102 SERIES	985-TZ102A-2L/2R; 985-TZ102A-3L/3R, 985-TZ102B-2R/3L, 985-TZ102B-3R, 985-TZ102C-2R/3L, 985-TZ102C-3R, 985-TZ102D-3L/3R, 985-TZ102E-3L/3R, 985-TZ102F-3L/3R, 985-TZ102G-3L/3R, 985-TZ102H-3L/3R, 985-TZ102J-3L/3R, 985-TZ102K-3L/3R, 985-TZ102L-3L, 985-TZ102M-3L/3R, 985-TZ102N-3L/3R, 985-TZ102P-3L, 985-TZ102Q-3R, 985-TZ102R-3L/3R, 985-TZ102S-3R, 985-TZ102T-3R	PASSENGER SEATS FOR ATA B737-800 & B757-300 AIRCRAFT	B/E AEROSPACE, SEATING PRODUCTS GROUP	25-41-56	All maintenance including overhaul [A/C CMS]
71.	12664-0 12665-0 12666-0 12667-0	12664-0 12665-0 12666-0 12667-0	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
72.	408-00-702-01 408-00-703-01 408-00-726-01 408-00-733-01 414-00-702-01 414-00-703-01 414-00-726-01 414-00-733-01	408-00-702-01 408-00-703-01 408-00-726-01 408-00-733-01 414-00-702-01 414-00-703-01 414-00-726-01 414-00-733-01	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 13 of 93

73.	1003541-001GW01 1003541-003GW01 1003541-005GW01 1003627-021GW01 1004405-007GW01 1004405-009GW01 1042503-001MW01 1042503-003MW01 1042503-003MW01 1042503-005MW01 1042503-005MW01 1042503-007MW01 1042503-009MW01 1042503-011MW01 1042503-013MW01	1003541-001GW01 1003541-003GW01 1003541-005GW01 1003627-021GW01 1004405-007GW01 1004405-009GW01 1042503-001MW01 1042503-003MW01 1042503-003MW01 1042503-005MW01 1042503-005MW01 1042503-007MW01 1042503-009MW01 1042503-011MW01 1042503-013MW01	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
74.	536-00-700-00 536-00-700-01 536-00-700-02 536-00-700-03 536-00-700-04 536-00-700-05 536-00-700-06 536-00-700-07 536-00-700-08 537-00-700-01 537-00-702-01 537-00-703-01 537-00-730-01 537-00-731-01 537-00-732-01 537-00-733-01 537-00-734-01 328-00-701-01 328-00-702-01 328-00-703-01 328-00-704-01 328-00-705-01 328-00-706-01 328-00-707-02 328-00-708-01 328-00-709-02 328-00-710-01 328-00-711-01 328-00-731-01 328-00-732-01 328-00-733-01 328-00-734-01 328-00-735-01 328-00-736-01 328-00-737-01 328-00-738-01 328-00-739-01 328-00-740-01 328-00-741-01 328-00-742-01 328-00-743-01 328-00-744-01 328-00-746-01 328-00-747-01 328-00-748-01 328-00-749-01 331-00-700-01 331-00-700-02 331-00-701-01 331-00-701-02 331-00-702-01 331-00-702-02	536-00-700-00 536-00-700-01 536-00-700-02 536-00-700-03 536-00-700-04 536-00-700-05 536-00-700-06 536-00-700-07 536-00-700-08 537-00-700-01 537-00-702-01 537-00-703-01 537-00-730-01 537-00-731-01 537-00-732-01 537-00-733-01 537-00-734-01 328-00-701-01 328-00-702-01 328-00-703-01 328-00-704-01 328-00-705-01 328-00-706-01 328-00-707-02 328-00-708-01 328-00-709-02 328-00-710-01 328-00-711-01 328-00-731-01 328-00-732-01 328-00-733-01 328-00-734-01 328-00-735-01 328-00-736-01 328-00-737-01 328-00-738-01 328-00-739-01 328-00-740-01 328-00-741-01 328-00-742-01 328-00-743-01 328-00-744-01 328-00-746-01 328-00-747-01 328-00-748-01 328-00-749-01 331-00-700-01 331-00-700-02 331-00-701-01 331-00-701-02 331-00-702-01 331-00-702-02	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 14 of 93

	331-00-703-01 331-00-703-02 331-00-704-01 331-00-704-02 331-00-730-01 331-00-730-02 331-00-731-01 331-00-731-02 331-00-732-01 331-00-732-02 331-00-733-01 331-00-733-02 331-00-734-01 331-00-734-02 331-00-735-01 331-00-735-02 331-00-736-01 331-00-736-02 331-00-737-01 331-00-737-02 331-00-738-01 331-00-738-02 331-00-739-01 331-00-739-02 331-00-740-01 331-00-740-02	331-00-703-01 331-00-703-02 331-00-704-01 331-00-704-02 331-00-730-01 331-00-730-02 331-00-731-01 331-00-731-02 331-00-732-01 331-00-732-02 331-00-733-01 331-00-733-02 331-00-734-01 331-00-734-02 331-00-735-01 331-00-735-02 331-00-736-01 331-00-736-02 331-00-737-01 331-00-737-02 331-00-738-01 331-00-738-02 331-00-739-01 331-00-739-02 331-00-740-01 331-00-740-02				
75.	48258015F081139 482590150887200 48260005H161800 48292005H161800	48258015F081139 482590150887200 48260005H161800 48292005H161800	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
76.	1003344-003	1003344-003	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
77.	358-00-700-01 358-00-701-01 358-00-702-01 358-00-732-01 358-00-736-01 358-00-739-01	358-00-700-01 358-00-701-01 358-00-702-01 358-00-732-01 358-00-736-01 358-00-739-01	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
78.	122892-09NW 122892-10NW 122999-11NW 123757-03NW 123757-04NW 128311-01NW 128311-02NW 128311-03NW 128311-04NW	122892-09NW 122892-10NW 122999-11NW 123757-03NW 123757-04NW 128311-01NW 128311-02NW 128311-03NW 128311-04NW	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
79.	856893-401A 856893-403A 856893-405A 857026-201A 857026-203A 857026-401A 857026-403A 857036-401A 857036-402A 857036-403A 857036-404A 857036-405A	856893-401A 856893-403A 856893-405A 857026-201A 857026-203A 857026-401A 857026-403A 857036-401A 857036-402A 857036-403A 857036-404A 857036-405A	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
80.	482585539010S01 482595539010S01	482585539010S01 482595539010S01	PASSENGER SEATS	Testori Aero Supply	TAS-S7- 503-ENG-	Repair [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 15 of 93

	482595549010S01 482595759010S02 482605319010S02	482595549010S01 482595759010S02 482605319010S02	LEATHER DRESS COVER SET		01	
81.	C2C44563001F08-1231 C2C44922005F08-1231 C2C44922007F08-1231 C2C44922008F08-1231	C2C44563001F08-1231 C2C44922005F08-1231 C2C44922007F08-1231 C2C44922008F08-1231	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
82.	128308-01 128308-03 128308-05 128308-07 128308-15	128308-01 128308-03 128308-05 128308-07 128308-15	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
83.	865909-403A 865909-405A 865909-409A 865911-403A 865911-405A 865911-407A 865911-417A 865911-421A	865909-403A 865909-405A 865909-409A 865911-403A 865911-405A 865911-407A 865911-417A 865911-421A	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
84.	1000935-001 1000935-003 1000935-005 1000935-007 1000935-009 1000935-011 1000935-015 1000935-017 1000935-019 1000935-021 100935-013 100935-023 1020683-005JM08 1020683-011JM08 1020683-001JM08 1020683-025JM08 1020683-021JM08 1020683-015JM08 1020683-035JM08 1020683-041JM08 1020683-031JM08 1003541-023GQ01 1003541-025GQ01 1003541-029GQ01 1003627-023GQ01 1003541-027GQ01 1003627-445GQ01 1003540-009GQ01 1003540-011GQ01	1000935-001 1000935-003 1000935-005 1000935-007 1000935-009 1000935-011 1000935-015 1000935-017 1000935-019 1000935-021 100935-013 100935-023 1020683-005JM08 1020683-011JM08 1020683-001JM08 1020683-025JM08 1020683-021JM08 1020683-015JM08 1020683-035JM08 1020683-041JM08 1020683-031JM08 1003541-023GQ01 1003541-025GQ01 1003541-029GQ01 1003627-023GQ01 1003541-027GQ01 1003627-445GQ01 1003540-009GQ01 1003540-011GQ01	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
85.	160720-3CXX 150710-11CXX 150700-01CXX 160701-3CXX 151725-14CXX 160721-3CXX 151725-06CXX 161703CXX 160730-3CXX 151793-12CXX 151725-01CXX 160700-4CXX 153727-18CXX 153727-14CXX 153727-10CXX	160720-3CXX 150710-11CXX 150700-01CXX 160701-3CXX 151725-14CXX 160721-3CXX 151725-06CXX 161703CXX 160730-3CXX 151793-12CXX 151725-01CXX 160700-4CXX 153727-18CXX 153727-14CXX 153727-10CXX	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 16 of 93

	153727-06CXX 153727-01CXX 153710-02CXX 153720-02CXX 153700-02CXX 141800-01CXX 161735-101-2CXX 152701-01CXX 152720-02CXX 152710-02CXX 152700-02CXX	153727-06CXX 153727-01CXX 153710-02CXX 153720-02CXX 153700-02CXX 141800-01CXX 161735-101-2CXX 152701-01CXX 152720-02CXX 152710-02CXX 152700-02CXX				
86.	2D7017-13A 2D7017-14A 2D7008-12A 2D7008-11A 2D7004-61A 2D7004-41A 2D7006-11A 2D7002-11A 2D7000-11A 2D7002-11ADB 2D7017-13ADB 2D7000-11ADB 2D7017-14ADB 2D7008-11ADB 2D7008-12ADB 2D7004-11ADB 2D7004-41ADB 2D7004-61ADB 2D7006-11ADB 2D7002-11DFW 2D7017-13DFW 2D700-11DFW 2D7017-14DFW 2D7008-11DFW 2D7008-12DFW 2D7004-61DFW 2D7006-11DFW	2D7017-13A 2D7017-14A 2D7008-12A 2D7008-11A 2D7004-61A 2D7004-41A 2D7006-11A 2D7002-11A 2D7000-11A 2D7002-11ADB 2D7017-13ADB 2D7000-11ADB 2D7017-14ADB 2D7008-11ADB 2D7008-12ADB 2D7004-11ADB 2D7004-41ADB 2D7004-61ADB 2D7006-11ADB 2D7002-11DFW 2D7017-13DFW 2D700-11DFW 2D7017-14DFW 2D7008-11DFW 2D7008-12DFW 2D7004-61DFW 2D7006-11DFW	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
87.	766-00-700-01 766-00-701-01 766-00-702-01 766-00-703-01 766-00-730-01 766-00-731-01 766-00-732-01 766-00-733-01 766-00-734-01 766-00-735-01 766-00-736-01 766-00-737-01 766-00-738-01 766-00-739-01 766-00-710-01 766-00-711-01	766-00-700-01 766-00-701-01 766-00-702-01 766-00-703-01 766-00-730-01 766-00-731-01 766-00-732-01 766-00-733-01 766-00-734-01 766-00-735-01 766-00-736-01 766-00-737-01 766-00-738-01 766-00-739-01 766-00-710-01 766-00-711-01	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
88.	F0475078 F0475079 F0475080 F0468084 F0475082 F0475083 F0475084 F0475081 F0468083 F0468155 F0468082 F0468081	F0475078 F0475079 F0475080 F0468084 F0475082 F0475083 F0475084 F0475081 F0468083 F0468155 F0468082 F0468081	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 17 of 93

	F0468087 F0468086 F0475273 F0475217 F0475216 F0475222 F0475221 F0475218 F0475219 F0475215 F0475220 F0468041 F0468043 F0468042 F0467698 F0468044 F0468045 F0468047 F0468046 F0467699	F0468087 F0468086 F0475273 F0475217 F0475216 F0475222 F0475221 F0475218 F0475219 F0475215 F0475220 F0468041 F0468043 F0468042 F0467698 F0468044 F0468045 F0468047 F0468046 F0467699				
89.	49649005F080947 49646015F080947 49645005F080947 49647005F080947 49720005F080947 496471050881200	49649005F080947 49646015F080947 49645005F080947 49647005F080947 49720005F080947 496471050881200	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
90.	TAS11403403 TAS11403405 TAS11403407 TAS11403423 TAS11403425 TAS12403403 TAS12403405 TAS12403409 TAS13403413 TAS13403415 TAS13403419 TAS11219 401 TAS11219 403 TAS12219 401 TAS12219 403 TAS12219 405 TAS14219 401 TAS14219 403 TAS11273 419 TAS11273 421 TAS11273 425 TAS11273 427 TAS12273 405 TAS12273 407 TAS12273 415 TAS11289 401 TAS11289 403 TAS11289 409 TAS12289 401 TAS12289 403 TAS12289 439 TAS13289401 TAS13289403 TAS13289439 TAS11293 405 TAS11293 406 TAS12293 405 TAS12293 413 TAS14293 421 TAS14293 422 TAS11293 441	TAS11403403 TAS11403405 TAS11403407 TAS11403423 TAS11403425 TAS12403403 TAS12403405 TAS12403409 TAS13403413 TAS13403415 TAS13403419 TAS11219 401 TAS11219 403 TAS12219 401 TAS12219 403 TAS12219 405 TAS14219 401 TAS14219 403 TAS11273 419 TAS11273 421 TAS11273 425 TAS11273 427 TAS12273 405 TAS12273 407 TAS12273 415 TAS11289 401 TAS11289 403 TAS11289 409 TAS12289 401 TAS12289 403 TAS12289 439 TAS13289401 TAS13289403 TAS13289439 TAS11293 405 TAS11293 406 TAS12293 405 TAS12293 413 TAS14293 421 TAS14293 422 TAS11293 441	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 18 of 93

TAS12293 441	TAS12293 441
TAS14293 445	TAS14293 445
TAS14293 446	TAS14293 446
TAS11293 451	TAS11293 451
TAS11293 453	TAS11293 453
TAS12293 451	TAS12293 451
TAS12293 453	TAS12293 453
TAS14293 451	TAS14293 451
TAS14293 453	TAS14293 453
TAS11293 403	TAS11293 403
TAS12293 403	TAS12293 403
TAS12293 413	TAS12293 413
TAS14293 425	TAS14293 425
TAS11289401	TAS11289401
TAS11289401	TAS11289401
TAS11289403	TAS11289403
TAS11289409	TAS11289409
TAS12289401	TAS12289401
TAS12289401	TAS12289401
TAS12289403	TAS12289403
TAS12289439	TAS12289439
TAS13289401	TAS13289401
TAS13289403	TAS13289403
TAS13289436	TAS13289436
TAS13289401	TAS13289401
TAS11249 401	TAS11249 401
TAS11249401	TAS11249401
TAS11249 403	TAS11249 403
TAS11249 413	TAS11249 413
TAS12249 401	TAS12249 401
TAS12249401	TAS12249401
TAS12249 403	TAS12249 403
TAS12249 411	TAS12249 411
TAS13249 401	TAS13249 401
TAS13249401	TAS13249401
TAS13249 403	TAS13249 403
TAS13249 411	TAS13249 411
TAS11214401	TAS11214401
TAS11214403	TAS11214403
TAS11214405	TAS11214405
TAS11214421	TAS11214421
TAS12214407	TAS12214407
TAS12214409	TAS12214409
TAS11346403	TAS11346403
TAS11346405	TAS11346405
TAS11346407	TAS11346407
TAS11346411	TAS11346411
TAS12346403	TAS12346403
TAS12346405	TAS12346405
TAS12346409	TAS12346409
TAS13346413	TAS13346413
TAS13346415	TAS13346415
TAS13346419	TAS13346419
TAS11352401	TAS11352401
TAS11352403	TAS11352403
TAS11352405	TAS11352405
TAS11352407	TAS11352407
TAS11352408	TAS11352408
TAS12352401	TAS12352401
TAS12352403	TAS12352403
TAS12352407	TAS12352407
TAS12352408	TAS12352408
TAS13352401	TAS13352401
TAS13352403	TAS13352403
TAS14352401	TAS14352401
TAS14352403	TAS14352403
TAS11353401	TAS11353401

**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 19 of 93

	TAS12353401 TAS12353402 TAS14353401 TAS14353402 TAS14353403 TAS11383401 TAS12383401 TAS12383402	TAS12353401 TAS12353402 TAS14353401 TAS14353402 TAS14353403 TAS11383401 TAS12383401 TAS12383402				
91.	44563001 44922008 44922007 44922005 49672006 49672005 496722003	44563001 44922008 44922007 44922005 49672006 49672005 496722003	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
92.	TAS11381430 TAS11381431 TAS11381432 TAS11381433 TAS11381434 TAS11381435 TAS11381436 TAS11381437 TAS11381438 TAS11381439 TAS12381400 TAS12381401 TAS12381402 TAS12381403 TAS13381410 TAS13381411 TAS11382401 TAS11382403 TAS11382404 TAS11382405 TAS11382407 TAS11382408 TAS11382409 TAS11382413 TAS11382415 TAS11382416 TAS12382417 TAS12382419 TAS11402430 TAS11402431 TAS11402432 TAS11402433 TAS11402434 TAS11402435 TAS12402401 TAS12402402 TAS13402410 TAS14402425 TAS11353401 TAS12353401 TAS12353402 TAS14353401 TAS14353402 TAS14353403 TAS11368401 TAS11368402 TAS12368401 TAS12368411 TAS14368401 TAS14368411 TAS14368423 TAS14368424	TAS11381430 TAS11381431 TAS11381432 TAS11381433 TAS11381434 TAS11381435 TAS11381436 TAS11381437 TAS11381438 TAS11381439 TAS12381400 TAS12381401 TAS12381402 TAS12381403 TAS13381410 TAS13381411 TAS11382401 TAS11382403 TAS11382404 TAS11382405 TAS11382407 TAS11382408 TAS11382409 TAS11382413 TAS11382415 TAS11382416 TAS12382417 TAS12382419 TAS11402430 TAS11402431 TAS11402432 TAS11402433 TAS11402434 TAS11402435 TAS12402401 TAS12402402 TAS13402410 TAS14402425 TAS11353401 TAS12353401 TAS12353402 TAS14353401 TAS14353402 TAS14353403 TAS11368401 TAS11368402 TAS12368401 TAS12368411 TAS14368401 TAS14368411 TAS14368423 TAS14368424	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 20 of 93

	TAS14368421 TAS14368422 TAS11425421 TAS11425423 TAS11425427 TAS11425463 TAS11425465 TAS11425467 TAS11425503 TAS11425507 TAS12425481 TAS12425483 TAS12425485 TAS12425487 TAS12425561 TAS12425565 TAS12425567 TAS11410401 TAS12410401 TAS14410401 TAS11411427 TAS11411467 TAS12411407	TAS14368421 TAS14368422 TAS11425421 TAS11425423 TAS11425427 TAS11425463 TAS11425465 TAS11425467 TAS11425503 TAS11425507 TAS12425481 TAS12425483 TAS12425485 TAS12425487 TAS12425561 TAS12425565 TAS12425567 TAS11410401 TAS12410401 TAS14410401 TAS11411427 TAS11411467 TAS12411407				
93.	476031078985T01 476030028985T01 476030018985T01 476030078985T01 476030088985T01 476030118985T01 476030128985T01 476032038985T01 476030138985T01 476030058985T01 476030158985T01 476031018985T01 476031018985T01 476031018985T01 476031058985T01 476030038985T01 476030098985T01 476031038985T01	476031078985T01 476030028985T01 476030018985T01 476030078985T01 476030088985T01 476030118985T01 476030128985T01 476032038985T01 476030138985T01 476030058985T01 476030158985T01 476031018985T01 476031018985T01 476031018985T01 476031058985T01 476030038985T01 476030098985T01 476031038985T01	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
94.	90082405-003 90082405-001	90082405-003 90082405-001	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
95.	375-00-709-01 375-00-708-01 375-00-707-01 375-00-706-01 375-00-700-01 375-00-704-01 375-00-705-01 375-00-701-01 375-00-702-01 375-00-731-01 375-00-732-01 375-00-733-01 375-00-734-01 375-00-735-01 375-00-736-01 375-00-737-01 375-00-738-01 375-00-739-01 375-00-741-01 375-00-761-00	375-00-709-01 375-00-708-01 375-00-707-01 375-00-706-01 375-00-700-01 375-00-704-01 375-00-705-01 375-00-701-01 375-00-702-01 375-00-731-01 375-00-732-01 375-00-733-01 375-00-734-01 375-00-735-01 375-00-736-01 375-00-737-01 375-00-738-01 375-00-739-01 375-00-741-01 375-00-761-00	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 21 of 93

	375-00-746-01 375-00-745-01 375-00-747-01 375-00-715-01 375-00-716-01 375-00-717-01 375-00-714-01 375-00-755-01 375-00-711-01 375-00-712-01 375-00-713-01	375-00-746-01 375-00-745-01 375-00-747-01 375-00-715-01 375-00-716-01 375-00-717-01 375-00-714-01 375-00-755-01 375-00-711-01 375-00-712-01 375-00-713-01				
96.	07-09-00-00P001-L00 07-09-00-00P002-L00	07-09-00-00P001-L00 07-09-00-00P002-L00	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
97.	18-00-00-00A001-L01 18-00-00-00A002-L01 18-00-00-00A003-L01 18-00-00-00A004-L01 18-00-00-00A005-L01 18-00-00-00A006-L01 18-00-00-00A007-L01 18-00-00-00A008-L01 18-00-00-00A009-L01 18-00-00-00A010-L01 18-00-00-00A011-L01	18-00-00-00A001-L01 18-00-00-00A002-L01 18-00-00-00A003-L01 18-00-00-00A004-L01 18-00-00-00A005-L01 18-00-00-00A006-L01 18-00-00-00A007-L01 18-00-00-00A008-L01 18-00-00-00A009-L01 18-00-00-00A010-L01 18-00-00-00A011-L01	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
98.	17-00-00-00A001-L01 17-00-00-00A001-L02 17-00-00-00A014-P00	17-00-00-00A001-L01 17-00-00-00A001-L02 17-00-00-00A014-P00	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
99.	E01-02-02-00A003-L04 E01-02-02-00A004-L04 E01-02-02-00A001-L07 02-02-00-00A023-P01 02-02-00-00A039-P00 02-02-00-00A038-P01 02-02-04-00A001-L02 02-02-04-00A001-L03	E01-02-02-00A003-L04 E01-02-02-00A004-L04 E01-02-02-00A001-L07 02-02-00-00A023-P01 02-02-00-00A039-P00 02-02-00-00A038-P01 02-02-04-00A001-L02 02-02-04-00A001-L03	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
100.	1003626-009AEH 1003626-011AEH 1003627-012AEH 1003627-003AEH 1003627-005AEH 1003627-023AEH 1003627-003AEH 1003627-005AEH 1003627-023AEH 1003627-005AEH 1003627-007AEH 1003627-035AEH 1003627-009AEH 1003627-009AEH 1003627-025AEH 1003627-009AEH 1003627-027AEH	1003626-009AEH 1003626-011AEH 1003627-012AEH 1003627-003AEH 1003627-005AEH 1003627-023AEH 1003627-003AEH 1003627-005AEH 1003627-023AEH 1003627-005AEH 1003627-007AEH 1003627-035AEH 1003627-009AEH 1003627-009AEH 1003627-025AEH 1003627-009AEH 1003627-027AEH	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 22 of 93

101.	847414-413A 847415-415 847414-411A 847414-419A 630343 630342 630344 847398-9A 847398-10A 847398-13B 847414-405A 847415-405 847415-419 847470-3A 847470-4A	847414-413A 847415-415 847414-411A 847414-419A 630343 630342 630344 847398-9A 847398-10A 847398-13B 847414-405A 847415-405 847415-419 847470-3A 847470-4A	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
102.	ST-122892-11NW ST-128311-01NW ST-128311-02NW ST-128311-03NW ST-128311-04NW ST-128308-01 ST-128308-03 ST-128308-05 ST-128308-07 ST120M-0001 ST120M-0002 ST120M-0003 ST120M-0004 ST120M-0005 ST120M-0007 ST120M-0008 ST163M-0001 ST163M-0003 ST163M-0004 ST163M-0005 ST163M-0006 ST163M-0009 ST228M-0001 ST228M-0002 ST228M-0003 ST228M-0004 ST228M-0005 ST228M-0006 ST228M-0007 ST228M-0008 ST228M-0009 ST228M-0010 ST228M-0011 ST228M-0012 ST228M-0013 ST248M-0001 ST248M-0002 ST248M-0003 ST248M-0004 ST248M-0005 ST248M-0006 ST248M-0007 ST248M-0008 ST248M-0009 ST248M-0010	ST-122892-11NW ST-128311-01NW ST-128311-02NW ST-128311-03NW ST-128311-04NW ST-128308-01 ST-128308-03 ST-128308-05 ST-128308-07 ST120M-0001 ST120M-0002 ST120M-0003 ST120M-0004 ST120M-0005 ST120M-0007 ST120M-0008 ST163M-0001 ST163M-0003 ST163M-0004 ST163M-0005 ST163M-0006 ST163M-0009 ST228M-0001 ST228M-0002 ST228M-0003 ST228M-0004 ST228M-0005 ST228M-0006 ST228M-0007 ST228M-0008 ST228M-0009 ST228M-0010 ST228M-0011 ST228M-0012 ST228M-0013 ST248M-0001 ST248M-0002 ST248M-0003 ST248M-0004 ST248M-0005 ST248M-0006 ST248M-0007 ST248M-0008 ST248M-0009 ST248M-0010	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
103.	TAS81097011 TAS11214 401 TAS11214 403 TAS11214 405 TAS11214 421	TAS81097011 TAS11214 401 TAS11214 403 TAS11214 405 TAS11214 421	PASSENGER SEATS LEATHER DRESS COVER	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 23 of 93

	TAS12214 407 TAS12214 409 TAS11248 461 TAS11248 462 TAS12248 461 TAS12248 462 TAS14248 471 TAS14248 472 TAS11264 401 TAS11264 403 TAS11264 405 TAS11264 421 TAS12264 407 TAS12264 409	TAS12214 407 TAS12214 409 TAS11248 461 TAS11248 462 TAS12248 461 TAS12248 462 TAS14248 471 TAS14248 472 TAS11264 401 TAS11264 403 TAS11264 405 TAS11264 421 TAS12264 407 TAS12264 409	SET			
104.	41191175-501 41191164-501	41191175-501 41191164-501	PASSENGER SEATS LEATHER DRESS COVER SET	Testori Aero Supply	TAS-S7- 503-ENG- 01	Repair [A/C CMS]
UNDERFLOOR HOLD NET SET						
105.	AC40-series	AC40-0202500, AC40-0219020 AC40-0209500, AC40-0209900 AC40-0262006, AC40-0268100 AC40-0241201, AC40-0241202 AC40-0209910, AC40-0209920 AC40-0268110, AC40-0268120 AC40-0209930, AC40-0241204 AC40-0268130 AC40-0210100 AC40-0241205, AC40-0268140 AC40-0210200, AC40-0241207 AC40-0268150, AC40-0217000 AC40-0253610, AC40-0268155 AC40-0217010, AC40-0253615 AC40-0268175, AC40-0217100 AC40-0253620, AC40-0268401 AC40-0217110, AC40-0253621 AC40-0268402, AC40-0217200 AC40-0253670, AC40-0270100 AC40-0217210, AC40-0262001 AC40-0217220, AC40-0262002 AC40-0217300, AC40-0262003 AC40-0217400, AC40-0262004 AC40-0217500, AC40-0262005	AIRBUS A318/319/320/A321 UNDERFLOOR HOLD NET SET	AmSafe Bridport	25-52-28	Repair [A/C CMS]
106.	n/a	453A1810-1, -2, -3, -4, -5, -6, -7, -8, -9, -10, -11, -12, -13, -14, -15, -32, -33, -34; 65-19328-22, -25, -26, -27; 65-19329-43, -44, -46, -47; 65-25756-22, -25, -26, -28; 65-25757-1; 65-45953-1; 65-49625-1, -501, -54; 65-49625-73; 65-49626-1, -41, -49, -501; 65-49627-1, -501, -56, -82; 65-49628-1, -40, -49, -501; 65-49629-1, -13, -501; 65-52956-1, -19; 65-52970-6, -15, -16, -17, -18, - 26; 65-53882-1, -2, -3, -4, -5, -6, - 21, -22, -23, -24, -25, -26, -33, - 34, -39, -40, -501, -502, -503, - 504, -505, -506; 65-54404-1; 65-78966-1, -2, 3, -4, -5, -6, -7, - 8, -29, -30, -31, -34, -35, -36, -	CARGO NET / STANCHION ASSEMBLY	Boeing corp.	25-50-01	Repair [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 24 of 93

		37, -38, -39, -40, -41, -42, -43, -44, -45, -46, -47, -48, -49, -50, -51, -52, -53, -54, -55, -56, -57, -58, -59, -60, -61, -66, -67; 65C34576-1,-7				
107.	170-405-SERIES; 190-405-SERIES	170-40549-401 170-40550-401 170-40551-401 170-40552-401 170-40553-401 170-40554-401 170-40574-401 170-40575-401 170-40576-401 190-40577-401	BAGGAGE COMPARTMENT CARGO NETS	AmSafe Bridport	50-22-01	Repair [A/C CMS]
108.	451N5601-SERIES, 451N5602-SERIES	451N5601-1, 451N5601-10, 451N5601-17, 451N5601-2, 451N5601-20, 451N5601-21, 451N5601-23, 451N5601-24, 451N5601-25, 451N5601-26, 451N5601-27, 451N5601-28, 451N5601-29, 451N5601-3, 451N5601-35, 451N5601-36, 451N5601-37, 451N5601-8, 451N5601-9 451N5601-10, 451N5601-11, 451N5601-12, 451N5601-17, 451N5601-2, 451N5601-20, 451N5601-21, 451N5601-22, 451N5601-26, 451N5601-27, 451N5601-29, 451N5601-3, 451N5601-30, 451N5601-31, 451N5601-32, 451N5601-33, 451N5601-34, 451N5601-35, 451N5601-36, 451N5601-41, 451N5601-43, 451N5601-44, 451N5601-49, 451N5601-7, 451N5601-8, 451N5601-9; 4451N5602-1	FORWARD AND AFT CARGO COMPARTMENT NET ASSEMBLIES	Boeing corp.	25-50-12	Repair [A/C CMS]
A/C Seats' Hydro Lock Maintenance						
109.	HV08000-series	HV08000-00, HV08000-01 HV08000-02, HV08000-03	Hydro lock	Crane Aerospace & Electronics	25-26-00	Repair [A/C CMS]
A/C Coffeemakers Maintenance						
110.	425-0001-XX	425-0001-1, 425-0001-3 425-0001-5, 425-0001-9 425-0001-13	Coffee Maker	B/E Aerospace Inc.	25-30-13	Repair [A/C CMS]
111.	425-0001-XX	425-0001-7, 425-0001-11	Coffee Maker	B/E Aerospace Inc.	25-30-27	Repair [A/C CMS]
112.	4510-XX	4510-31UF-00, 4510-31LF-00 4510-32UF-00, 4510-32LF-00 4510-33UF-00, 4510-33LF-00 4510-34UF-00, 4510-34LF-00 4510-35UF-00, 4510-35LF-00 4510-36UF-00, 4510-36LF-00 4510-37UF-00, 4510-37LF-00 4510-38UF-00, 4510-38LF-00 4510-41UF-00, 4510-41LF-00 4510-42UF-00, 4510-42LF-00 4510-43UF-00, 4510-43LF-00 4510-44UF-00, 4510-44LF-00 4510-45UF-00, 4510-45LF-00 4510-46UF-00, 4510-46LF-00 4510-47UF-00, 4510-47LF-00 4510-48UF-00, 4510-48LF-00 4510-31UG-00, 4510-31LG-00 4510-32UG-00, 4510-32LG-00 4510-33UG-00, 4510-33LG-00 4510-34UG-00, 4510-34LG-00 4510-35UG-00, 4510-35LG-00 4510-36UG-00, 4510-36LG-00	Beverage-Maker	B/E Aerospace Inc.	25-33-21	Repair [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 25 of 93

		4510-37UG-00, 4510-37LG-00 4510-38UG-00, 4510-38LG-00 4510-41UG-00, 4510-41LG-00 4510-42UG-00, 4510-42LG-00 4510-43UG-00, 4510-43LG-00 4510-44UG-00, 4510-44LG-00 4510-45UG-00, 4510-45LG-00 4510-46UG-00, 4510-46LG-00 4510-47UG-00, 4510-47LG-00 4510-48UG-00, 4510-48LG-00				
113.	11050-11 11225-3 11225-31 Model 1100	11050-11, 11225-3, 11225-31, Model 1100	Coffee-Maker	Composite Specialties Inc.	25-30-02	Repair [A/C CMS]
114.	3510-0006-01	3510-0006-01	Coffee-Maker	B/E Aerospace Inc.	25-30-26	Repair [A/C CMS]
115.	3510-0039 - series	3510-0039-01 3510-0039-03	Coffee-Maker	B/E Aerospace Inc.	25-30-45	Repair [A/C CMS]
116.	3510-0044- XX	3510-0044-05, 3510-0044-07 3510-0044-11	Coffee-Maker	B/E Aerospace Inc.	25-30-48	Repair [A/C CMS]
117.	3510-0066-01	3510-0066-01	Coffee-Maker	B/E Aerospace Inc.	25-33-02	Repair [A/C CMS]
118.	3510-0053-01	3510-0053-01	Coffee-Maker	B/E Aerospace Inc.	25-30-49	Repair [A/C CMS]
119.	3510-0072-01	3510-0072-01	Coffee-Maker	B/E Aerospace Inc.	25-33-05	Repair [A/C CMS]
120.	416-1001- series	416-1001-1, 416-1001-1P 416-1001-3, 416-1001-5 416-1001-7, 416-1001-9 416-1001-13, 416-1001-15 416-1001-17, 416-1001-19 416-1001-21, 416-1001-23 416-1001-25, 416-1001-29 416-1001-35, 416-1001-39 416-1001-41, 416-1001-45 416-1001-47, 416-1001-49	Coffee-Maker	B/E Aerospace Inc.	25-30-31	Repair [A/C CMS]
121.	416-0001- series	416-0001-1, 416-0001-1P 416-0001-3, 416-0001-5 416-0001-7, 416-0001-9 416-0001-13, 416-0001-15 416-0001-17, 416-0001-19 416-0001-21, 416-0001-23 416-0001-25, 416-0001-29 416-0001-35, 416-0001-39 416-0001-41, 416-0001-45 416-0001-47, 416-0001-49	Coffee-Maker	B/E Aerospace Inc.	25-30-09	Repair [A/C CMS]
122.	64753-001- series	64753 64753-001-003 64753-001-005	Coffee-Maker	Rumbold	25-31-82	Repair [A/C CMS]
123.	64752- series	64752 64752-001-003	Beverage-Maker	Rumbold	25-31-81	Repair [A/C CMS]
124.	471-0001- series	471-0001-1 471-0001-3 471-0001-5	Beverage maker	B/E Aerospace Inc.	25-34-33	Repair [A/C CMS]
125.	DR4180 series	4360004-80-00-18 4360004-80-00-25 4360004-80SQ18 4360004-85-00-18 4360004-87-00-18 4360004-81-00-18 4360004-86-00-18	Water Heater	B/E Aerospace Inc.	25-33-49	Repair [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 26 of 93

		4360004-88-00-18				
126.	DR40 series	72184002B 72184003B 72184004 72184006 72184008B 72184011B 72184012B 72184013B 72184017B 72184018 72184019 72184025	Water Heater	B/E Aerospace Inc.	25-33-40	Repair [A/C CMS]
127.	11225-1	11225-1;	Coffee Maker	B/E Aerospace Inc.	25-30-03	Repair [A/C CMS]
128.	62197-series	62197-001-001 62197-101-001 62197-301-001	WATER BOILER	Sell GmbH - ZODIAC ELECTRICAL INSERTS EUROPE	25-35-95	Repair [A/C CMS]
129.	940x-Series	9401-01-0000-01, -02, -03, 9401-51-0000-01	WATER BOILER	Sell GmbH ZODIAC ELECTRICAL INSERTS EUROPE	25-37-37	Repair [A/C CMS]
130.	9001-Series; 9201-Series	9001-01-0000-01; 9201-01-0000-01	BEVERAGE MAKER	Sell GmbH ZODIAC ELECTRICAL INSERTS EUROPE	25-37-40	Repair [A/C CMS]
A/C Ovens Maintenance						
131.	8203-series	8203-11-0000, 8203-11-0000A 8203-11-0000D, 8203-12-0000 8203-12-0000C, 8203-12-0000D 8203-17-0000, 8203-61-0000 8203-62-0000, 8203-63-0000C 8203-67-0000	Oven	Britax Sell GmbH & Co OHG	25-36-34	Repair [A/C CMS]
132.	620-0009-series	620-0009-1, 620-0009-3 620-0009-5, 620-0009-7 620-0009-9, 620-0009-11	Oven	B/E Aerospace Inc.	25-31-37	Repair [A/C CMS]
133.	1238-series	1238, 1238A, 1238B 1238C, 1238D, 1238E	Oven	B/E Aerospace Inc.	25-31-13	Repair [A/C CMS]
134.	8201-series	8201-01-0000, 8201-51-0000 8201-02-0000, 8201-52-0000 8201-03-0000, 8201-53-0000 8201-04-0000, 8201-54-0000 8201-07-0000	Oven	Sell	25-36-22	Repair [A/C CMS]
135.	8201-series	8201-11-0000, 8201-61-0000 8201-13-0000, 8201-63-0000 8201-14-0000, 8201-64-0000 8201-17-0000, 8201-67-0000 8201-11-0000A 8201-11-00000 8201-12-0000, 8201-12-00000	Oven	Sell	25-36-33	Repair [A/C CMS]
136.	4313100-00-6600 (TRUE p/n 4313100-00-66-00) 4313101-00-6600 (TRUE p/n 4313101-00-66-00)	4313100-00-6600 (TRUE P/N 4313100-00-66-00) 4313101-00-6600 (TRUE P/N 4313101-00-66-00)	Oven	B/E Aerospace Inc.	25-35-08	Repair [A/C CMS]
137.	4313100-01-6600 4313101-01-6600	4313100-01-6600 4313101-01-6600	Oven	B/E Aerospace Inc.	25-35-12	All maintenance and overhaul excluding section



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 27 of 93

						Subtask 25-35-12-360-004-A01 (13) Replacement of Contacts and Terminals [A/C CMS]
138.	DF700/DF775	72067000, 72067001 72067002, 72067003 72067004, 72067005 72067006, 72067100 72067101, 72067102 72067750, 72067751 72067752, 72067850	High Speed Oven	B/E Aerospace Inc.	25-32-75	Repair [A/C CMS]
139.	67262-001-series	67262-001-001 67262-001-002 67262-001-003 67262-001-004	Single Compartment Oven	Britax Sell Gmbh & Co OHG	25-35-53	Repair [A/C CMS]
140.	8303 – Series	8303-01-0000-01, 8303-04-0000-01, 8303-06-0000-01, 8303-06-0000-02; 8303-51-0000-01; 8303-54-0000-01; 8303-56-0000-01; 8303-56-0000-02.	Extended oven	Sell GmbH ZODIAC ELECTRICAL INSERTS EUROPE	25-37-42	Repair [A/C CMS]
A/C Rinse Valves Maintenance						
141.	15800-XXXX	15800-348A 15800-358	Rinse Valve	Monogram Systems	38-34-20	Repair [A/C CMS]
142.	15800-440	15800-440	Rinse Valve	Monogram Systems	38-34-30	Repair [A/C CMS]
A/C Emergency Equipment Maintenance						
143.	63600-series	63600-101, 63600-103 63600-105, 63600-111 63600-113, 63600-115 63600-117, 63600-119 63600-121, 63600-125 63600-127, 63600-129 63600-131, 63600-133 63600-135, 63600-137 63600-139, 63600-141 63600-143, 63600-145 63600-147, 63600-149 63600-153, 63600-155 63600-157, 63600-161 63600-159, 63600-165 63600-163, 63600-169 63600-167, 63600-173 63600-171, 63600-177 63600-175, 63600-181 63600-179, 63600-185 63600-183, 63600-189 63600-187, 63600-193 63600-191, 63600-197 63600-195, 63600-301 63600-199, 63600-401 63600-303, 63600-501 63600-402, 63600-505 63600-503, 63600-513 63600-511, 63600-517 63600-515, 63600-521 63600-519, 63600-525 63600-523, 63600-529 63600-527, 63600-533	Life preserver	AIR CRUISER	25-64-02	Inspecting, Testing and Repacking [A/C CMS]



		63600-531, 63600-537 63600-535, 63600-541 63600-539, 63600-545 63600-543, 63600-549 63600-547, 63600-557 63600-555, 63600-561 63600-559, 63600-565 63600-563, 63600-569 63600-567, 63600-573 63600-571, 63600-577 63600-575, 63600-581 63600-579, 63600-585 63600-583, 63600-589 63600-587, 63600-593 63600-591, 63600-597 63600-595, 63600-701 63600-599, 63600-801 63600-703, 63600-802				
Evacuation Slide Maintenance						
144.	D31516 – Series	D31516-101, D31516-103 D31516-105, D31516-107 D31516-109, D31516-111 D31516-113, D31516-115 D31516-117, D31516-119 D31516-121, D31516-311 D31516-313, D31516-315 D31516-317, D31516-415 D31516-417, D31516-519 D31516-521, D31516-523 D31516-525 D31516-615, D31516-617 D31516-619, D31516-621 D31516-623, D31516-625 D31516-715, D31516-717 D31516-719, D31516-721 D31516-723, D31516-725	A318/A319/ A320/A321 EVACUATION SLIDE WITH DECORATIVE COVER	ZODIAC AERO EVACUATION SYSTEMS	25-60-56	Repair [A/C CMS]
145.	D31517 – Series	D31517-101, D31517-103 D31517-105, D31517-107 D31517-109, D31517-111 D31517-113, D31517-115 D31517-117, D31517-119 D31517-121, D31517-311 D31517-313, D31517-315 D31517-317, D31517-415 D31517-417, D31517-519 D31517-521, D31517-523 D31517-525 D31517-615, D31517-617 D31517-619, D31517-621 D31517-623, D31517-625 D31517-715, D31517-717 D31517-719, D31517-721 D31517-723, D31517-725	A318/A319/ A320/A321 AIRCRAFT EVACUATION SLIDE WITH DECORATIVE COVER	ZODIAC AERO EVACUATION SYSTEMS	25-60-56	Repair [A/C CMS]
146.	D31865 – Series	D31865-101, D31865-102 D31865-103, D31865-104 D31865-105, D31865-106 D31865-107, D31865-108 D31865-109, D31865-110 D31865-111, D31865-112 D31865-209, D31865-210 D31865-309, D31865-310 D31865-311, D31865-312	A318/A319/A320 AIRCRAFT Dual Lane Off- Wing Ramp/Slide	ZODIAC AERO EVACUATION SYSTEMS	25-60-58	Repair [A/C CMS]
147.	D17978-series	D17978-101, D17978-103 D17978-105, D17978-107 D17978-109, D17978-111 D17978-113, D17978-115	B737 AIRCRAFT Reservoir and Valve/Regulator Assembly	ZODIAC AERO EVACUATION SYSTEMS	25-65-09	All maintenance except valve/regulator section (P/n)



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 29 of 93

		D17978-119, D17978-121 D17978-131, D17978-133 D17978-201, D17978-203 D17978-205, D17978-207 D17978-209, D17978-211 D17978-213, D17978-215 D17978-233				D18294-101, D18306-101 and 65709-1) repair and calibration [A/C CMS]
148.	D37022-series	D37022-101, D37022-103 D37022-105, D37022-205	B737-300/400/500 AIRCRAFT Reservoir and Valve/Regulator Assembly	ZODIAC AERO EVACUATION SYSTEMS	25-65-12	All maintenance except valve/regulator section (p/n D18278-107, 61199-107, 65701- 1) repair and calibration [A/C CMS]
149.	D17996-101 D37080-101	D17996-101 D37080-101	A318/A319/ A320/A321 AIRCRAFT Evacuation Systems Reservoir and Valve Assemblies	ZODIAC AERO EVACUATION SYSTEMS	25-65-17	All maintenance except valves / regulators section (p/n D18302-101, D18308-series, 65566-1, 65566-3, 68582-1) repair and calibration [A/C CMS]
150.	D18309-series	D18309-101, D18309-103 D18309-105, D18309-115 D18309-201, D18309-205 D18309-305	A318/A319/ A320/A321 AIRCRAFT Evacuation Systems Reservoir and Valve Assemblies	ZODIAC AERO EVACUATION SYSTEMS	25-65-17	All maintenance except valves / regulators section (p/n D18302-101, D18308-series, 65566-1, 65566-3, 68582-1) repair and calibration [A/C CMS]
151.	60592-series	60592-101, 60592-103 60592-201, 60592-203	A318/A319/ A320/A321 AIRCRAFT Evacuation Systems Reservoir and Valve Assemblies	ZODIAC AERO EVACUATION SYSTEMS	25-65-17	All maintenance except valves / regulators section (p/n D18302-101, D18308-series, 65566-1, 65566-3, 68582-1) repair and calibration [A/C CMS]
152.	61767-series	61767-103 61767-201 61767-203 61767-101	B737-300/400/500 Evacuation Slide Reservoir and Valve Assembly	ZODIAC AERO EVACUATION SYSTEMS	25-65-20	All maintenance except valves / regulators section (p/n D18306-101, 65709-1, 61199- 107) repair and calibration [A/C CMS]
153.	61768-series	61768-101, 61768-103 61768-201, 61768-203	B737-300/400/500 Evacuation Slide Reservoir and Valve Assembly	ZODIAC AERO EVACUATION SYSTEMS	25-65-20	All maintenance except valves / regulators section (p/n D18306-101, 65709-1, 61199- 107) repair and calibration [A/C CMS]
154.	61639- Series	61639-101, 61639-103	A321	ZODIAC	25-65-21	All maintenance



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 30 of 93

		61639-203	AIRCRAFT Reservoir And Valve/Regulator Assembly	AERO EVACUATION SYSTEMS		except valves / regulators section (p/n 61643-101, 61643-103, 65567- 1) repair and calibration [A/C CMS]
155.	D17906- Series	D17906-111, D17906-113 D17906-115, D17906-116 D17906-121, D17906-122 D17906-123, D17906-211 D17906-213, D17906-216 D17906-221, D17906-222 D17906-223	B757 Aircraft Reservoir and Valve Assembly	ZODIAC AERO EVACUATION SYSTEMS	25-65-10	All maintenance except valve / regulator section repair and calibration [A/C CMS]
156.	D60740- Series	60740-101, 60740-102 60740-105	B767 Aircraft Reservoir and Valve Assembly	ZODIAC AERO EVACUATION SYSTEMS	25-65-19	All maintenance except valve / regulator section repair and calibration [A/C CMS]
157.	D31354- Series	D31354-425, D31354-433 D31354-437, D31354-442 D31354-426, D31354-434 D31354-438, D31354-443 D31354-429, D31354-435 D31354-439, D31354-447	B737 Aircr Aft Door Lightweight Evacuation Slide	ZODIAC AERO EVACUATION SYSTEMS	25-60-54	Repair [A/C CMS]
158.	D31591-series (10-61323 – series)	D31591-448, (10-61323-448) D31591-449, (10-61323-449) D31591-450, (10-61323-450) D31591-451, (10-61323-451) D31591-452, (10-61323-452) D31591-453, (10-61323-453) D31591-454, (10-61323-454) D31591-458, (10-61323-458) D31591-459, (10-61323-459) D31591-460, (10-61323-460) D31591-461, (10-61323-461) D31591-462, (10-61323-462) D31591-463, (10-61323-463) D31591-464, (10-61323-464) D31591-474, (10-61323-474) D31591-475, (10-61323-475) D31591-476, (10-61323-476) D31591-477, (10-61323-477) D31591-478, (10-61323-478) D31591-479, (10-61323-479) D31591-480, (10-61323-480) D31591-487, (10-61323-487) D31591-488, (10-61323-488) D31591-489, (10-61323-489)	B737-300/400/500 Forward Door Lightweight Evacuation Slide	ZODIAC AERO EVACUATION SYSTEMS	25-60-59	Repair [A/C CMS]
159.	61620-468 (SCD 61323- 468)	61620-468 (SCD 61323-468)	B737-300/400/500 Forward Door Slide Evacuation System	ZODIAC AERO EVACUATION SYSTEMS	25-66-06	Repair [A/C CMS]
160.	61621-469 (10-61323- 469)	61621-469 (10-61323-469)	B737-300/400/500 Aft Door Evacuation Slide	ZODIAC AERO EVACUATION SYSTEMS	25-66-07	Repair [A/C CMS]
161.	D31354- series D31355- series	D31354-105, D31354-107, D31354-113, D31354-115, D31354-117, D31354-119, D31354-121, D31354-123, D31354-401, D31354-402,	B737-200/300 AIRCRAFT FORWARD AND AFT DOORS LIGHTWEIGHT	ZODIAC AERO EVACUATION SYSTEMS	25-60-43	Repair [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 31 of 93

		D31354-405, D31354-406, D31354-409, D31354-410, D31354-413, D31354-414, D31354-418, D31354-419, D31354-420, D31354-422, D31354-424, D31355-105, D31355-107, D31355-113, D31355-115, D31355-117, D31355-119, D31355-121, D31355-123, D31355-403, D31355-404, D31355-407, D31355-408, D31355-411, D31355-412, D31355-415, D31355-416	EVACUATION SLIDES			
BATTERY POWER SUPPLY CHARGER ASSY						
162.	BPS7-2 BPS7-3	BPS7-2 (BOEING SCD S283T014-2) BPS7-3 (BOEING SCD S283T014-3)	Battery Power supply Charger assy	Radiant Power Corp.	25-65-02	Repair [A/C CMS]
163.	2012-1	2012-1	Charger Assy			
164.	2013-1 2013-1A	2013-1 2013-1A	Battery Assy			
ON-BOARD WHEELCHAIR						
165.	2218-20	4891417-03	ON-BOARD WHEELCHAIR	Franklin Products	Component Maintenance Manual January 1999	Repair [A/C CMS]
166.	2218-Series	2218-XX	ON-BOARD WHEELCHAIR	INNOVINT Aircraft Interior	25-20-00	Repair [A/C CMS]
FOOT REST AND SLIDING TABLE						
167.	D2511-Series D2512-Series D2514-Series F2512-Series	D2511113100400 D2511113100500 D2511168500000 D2511225800000 D2511411800000 F2511211600000 F2511223200000	Foot rest and Sliding table	Airbus Industries	25-13-15	Repair [A/C CMS]

Rating item: C6 Equipment / Repair

Item n°	Part number / Model series	Full part numbers / Models	Description	Manufacturer	SRM / ATA chapter	Work scope Level / Component maintenance shop
A/C Equipment / Repair						
A/C Airbus A320						
168.	D25286058000009	D25286058000009	FLAP ASSY- GUIDE ROD (LH)	AIRBUS	252000	Repair [A/C SRS]
169.	D25286058001009	D25286058001009	FLAP ASSY- GUIDE ROD (RH)	AIRBUS	252000	Repair [A/C SRS]
170.	D25286056028009	D25286056028009	LINING ASSY- DOOR (LH)	AIRBUS	252000	Repair [A/C SRS]
171.	D25286056029009	D25286056029009	LINING ASSY- DOOR (RH)	AIRBUS	252000	Repair [A/C SRS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 32 of 93

172.	D2528660602800	D2528660602800	LINING ASSY-SUPPORT ARM (LH)	AIRBUS	252000	Repair [A/C SRS]
173.	D2528660803000	D2528660803000	LINING ASSY-SUPPORT ARM (RH)	AIRBUS	252000	Repair [A/C SRS]
174.	D25286054008009	D25286054008009	LINING ASSY-DOOR (LH)	AIRBUS	252000	Repair [A/C SRS]
175.	D25286054009009	D25286054009009	LINING ASSY-DOOR (RH)	AIRBUS	252000	Repair [A/C SRS]
176.	D25286050008009	D25286050008009	PANEL ASSY-DOOR (LH)	AIRBUS	252000	Repair [A/C SRS]
177.	D25286050009009	D25286050009009	PANEL ASSY-DOOR (RH)	AIRBUS	252000	Repair [A/C SRS]
178.	A225400429-728	A225400429-728	DOOR ASSY-WASHBASIN	AIRBUS	254148	Repair [A/C SRS]
179.	S125400431-528	S125400431-528	DOOR ASSY-WASHBASIN	AIRBUS	254148	Repair [A/C SRS]

A/C Boeing B757

180.	416N2100	416N2100-723SP 416N2100-750SP 416N2100-729SP 416N2100-730SP 416N2100-725SP 416N2100-726SP 416N2100-713SP 416N2100-714SP	COVER ASSY	BOEING	250000	Repair [A/C SRS]
181.	D75D16001	D75D16001-111A D75D16011-111B D75D16011-211A D75D16011-211B D75D35002-111A D75D35002-111B D75D35001-111C	SHROUD ASSY TOILET	YOKOHAMA	250000	Repair [A/C SRS]

A/C Boeing B767

182.	416T2640-XXX	416T2640-30A 416T2640-29A	DOOR BUSTLE	BOEING	250000	Repair [A/C SRS]
------	--------------	------------------------------	-------------	--------	--------	---------------------

Rating item: C7 Engine - APU

Item nº	Part number / Model series	Full part numbers / Models	Description	Manufacturer	CMM / ATA chapter	Work scope Level / Component maintenance shop
Actuators Maintenance						
Pressure switch's Maintenance						
183.	21SN41-series	21SN41-42, 21SN41-52 21SN41-84	Pressure Switch	Eaton	80-21-03	Testing [A/C CMS]

Rating item: C8 Flight Controls

MOE ISSUE 4 REV.0 Part 1.9	PART-145 AMO Ref. EASA.145.0381	14.12.2017
---	--	-------------------



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 33 of 93

Item nº	Part number / Model series	Full part numbers / Models	Description	Manufacturer	CMM / ATA chapter	Work scope Level / Component maintenance shop
Fuse's Maintenance						
184.	2-7680 - series	2-7680-1, 2-7680-2 (S272U860-5)	Fuse Assembly	Triumph Actuation Systems - Yakima	27-32-02	Overhaul [A/C CMS]
Actuators Maintenance						
185.	D2727000700 - series	D2727000700200 D2727000700600	Centering Spring Rod - Yaw Damper	AIRBUS	27-26-41	Overhaul [A/C CMS]
186.	2-7681 - series	2-7681-1, 2-7681-2 (S272U860-7)	Fuse Assembly, Flow Rate	Triumph Actuation Systems - Yakima	27-32-03	Overhaul [A/C CMS]

Rating item: C8 Flight Controls / Repair

Item nº	Part number / Model series	Full part numbers / Models	Description	Manufacturer	SRM / ATA chapter	Work scope Level / Component maintenance shop
A/C Flight Controls / Repair						
A/C Airbus A320						
187.	D5528000100X	D55280001000, D55280001001 D55280001002, D55280001003 D55280001004, D55280001005 D55280001008, D55280001009 D55280001010, D55280001011 D55280001012, D55280001013	ELEVATOR	AIRBUS	552000	Repair [A/C SRS]
188.	D5528000200X	D55280002001, D55280002002 D55280002003	ELEVATOR	AIRBUS	552000	Repair [A/C SRS]
189.	D552800030XX	D55280003002, D55280003004 D55280003001, D55280003003 D55280003005, D55280003006 D55280003008, D55280003010 D55280003007, D55280003009 D55280003011, D55280003012 D55280003014, D55280003016 D55280003013, D55280003015 D55280003017, D55280003018 D55280003020, D55280003022 D55280003019, D55280003021 D55280003023, D55280003024 D55280003026, D55280003028 D55280003025, D55280003027 D55280003029, D55280003030 D55280003032, D55280003034 D55280003031, D55280003033 D55280003035, D55280003036 D55280003038, D55280003040 D55280003037, D55280003039 D55280003041, D55280003044 D55280003046, D55280003045 D55280003047	ELEVATOR	AIRBUS	552000	Repair [A/C SRS]
190.	D574601000XX	D57460100002, D57460100003 D57460100004, D57460100005 D57460100006, D57460100007 D57460100010, D57460100011	SLAT 1	AIRBUS	574221	Repair [A/C SRS]
191.	D574601680XX	D57460168000, D57460168001 D57460168002, D57460168003 D57460168004, D57460168005	SLAT 1	AIRBUS	574221	Repair



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 34 of 93

		D57460168006, D57460168007 D57460168008, D57460168009 D57460168010, D57460168011				[A/C SRS]
192.	D5746019800X	D57460198000, D57460198001 D57460198002, D57460198003	SLAT 1	AIRBUS	574221	Repair [A/C SRS]
193.	D57460677000X	D57460677000, D57460677001 D57460677002, D57460677003 D57460677004, D57460677005	SLAT 1	AIRBUS	574221	Repair [A/C SRS]
194.	D5746091000X	D57460910000, D57460910001 D57460910002, D57460910003 D57460910004, D57460910005	SLAT 1	AIRBUS	574221	Repair [A/C SRS]
195.	D574602000XX	D57460200000, D57460200001 D57460200002, D57460200003 D57460200004, D57460200005 D57460200006, D57460200007 D57460200010, D57460200011	SLAT 2	AIRBUS	574321	Repair [A/C SRS]
196.	D5746029800X	D57460298000 D57460298001	SLAT 2	AIRBUS	574321	Repair [A/C SRS]
197.	D574602780XX	D57460278000, D57460278001 D57460278002, D57460278003 D57460278004, D57460278005 D57460278006, D57460278007 D57460278008, D57460278009 D57460278010, D57460278011 D57460278012, D57460278013	SLAT 2	AIRBUS	574321	Repair [A/C SRS]
198.	D5746027700X	D57460277000, D57460277001 D57460277002, D57460277003	SLAT 2	AIRBUS	574321	Repair [A/C SRS]
199.	D5746092000X	D57460920000, D57460920001 D57460920002, D57460920003	SLAT 2	AIRBUS	574321	Repair [A/C SRS]
200.	D5746030000X	D57460300000, D57460300001 D57460300002, D57460300003 D57460300004, D57460300005 D57460300006, D57460300007	SLAT 3	AIRBUS	574421	Repair [A/C SRS]
201.	D5746039800X	D57460398000, D57460398001	SLAT 3	AIRBUS	574421	Repair [A/C SRS]
202.	D574603780XX	D57460378000, D57460378001 D57460378002, D57460378003 D57460378004, D57460378005 D57460378006, D57460378007 D57460378008, D57460378009 D57460378010, D57460378011	SLAT 3	AIRBUS	574421	Repair [A/C SRS]
203.	D5746037700X	D57460377000, D57460377001 D57460377002, D57460377003	SLAT 3	AIRBUS	574421	Repair [A/C SRS]
204.	D5746093000X	D57460930000, D57460930001 D57460930002, D57460930003 D57460930004, D57460930005	SLAT 3	AIRBUS	574421	Repair [A/C SRS]
205.	D5746040000X	D57460400000, D57460400001 D57460400002, D57460400003 D57460400004, D57460400005 D57460400006, D57460400007	SLAT 4	AIRBUS	574521	Repair [A/C SRS]
206.	D5746047700X	D57460477000, D57460477001 D57460477002, D57460477003	SLAT 4	AIRBUS	574521	Repair



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 35 of 93

						[A/C SRS]
207.	D574604780XX	D57460478001, D57460478002 D57460478003, D57460478004 D57460478005, D57460478006 D57460478007, D57460478008 D57460478009, D57460478010 D57460478011	SLAT 4	AIRBUS	574521	Repair [A/C SRS]
208.	D5746049800X	D57460498000 D57460498001	SLAT 4	AIRBUS	574521	Repair [A/C SRS]
209.	D5746094000X	D57460940000, D57460940001 D57460940002, D57460940003 D57460940004, D57460940005	SLAT 4	AIRBUS	574521	Repair [A/C SRS]
210.	D5746050000X	D57460500000, D57460500001 D57460500002, D57460500003 D57460500004, D57460500005 D57460500006, D57460500007	SLAT 5	AIRBUS	574621	Repair [A/C SRS]
211.	D5746057700X	D57460577000, D57460577001 D57460577002, D57460577003	SLAT 5	AIRBUS	574621	Repair [A/C SRS]
212.	D574605980XX	D57460598000, D57460598001 D57460598002, D57460598003 D57460598004, D57460598005 D57460598006, D57460598007 D57460598008, D57460598009 D57460598010, D57460598011	SLAT 5	AIRBUS	574621	Repair [A/C SRS]
213.	D5746095000X	D57460950000, D57460950001 D57460950002, D57460950003 D57460950004, D57460950005	SLAT 5	AIRBUS	574621	Repair [A/C SRS]
214.	D575706500XX00	D5757065000200 D5757065000400 D5757065000600 D5757065000800 D5757065001000 D5757065001400 D5757065001600 D5757065000300 D5757065000500 D5757065000700 D5757065000900 D5757065001100 D5757065001500 D5757065001700 D5757065001800 D5757065002000 D5757065000900 D5757065001900 D5757065002100 D5757065002200 D5757065002400 D5757065002600 D5757065002800 D5757065003000 D5757065002300 D5757065002500 D5757065002700 D5757065002900 D5757065003100 D5757065003200 D5757065003400 D5757065003600 D5757065003800 D5757065004000	FLAP ASSY- INBOARD	AIRBUS	575221	Repair [A/C SRS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 36 of 93

		D5757065004200 D5757065004400 D5757065004600 D5757065004800 D5757065005000 D5757065003300 D5757065003500 D5757065003700 D5757065003900 D5757065004100 D5757065004300 D5757065004500 D5757065004700 D5757065004900 D5757065005200 D5757065002800 D5757065005300 D5757065002900				
215.	D5757100800X00	D5757100800000 D5757100800100	FLAP ASSY- OUTBOARD	AIRBUS	575321	Repair [A/C SRS]
216.	D575742020XX00	D5757420200000 D5757420200200 D5757420200400 D5757420200600 D5757420200800 D5757420201000 D5757420201200 D5757420201400 D5757420201600 D5757420200100 D5757420200300 D5757420200500 D5757420200700 D5757420200900 D5757420201100	FLAP ASSY- OUTBOARD	AIRBUS	575321	Repair [A/C SRS]
217.	D575405010XX00 X	D5754050100400Z D5755805500000A D5754050100600Z D5754050100500Z D5755805500100A D5754050100700Z D5754050100600A D5754050100800A D5754050101000A D5754050100700A D5754050100900A D5754050101100A	FAIRING ASSY- FWD, FIXED, FLAP TRACK 2	AIRBUS	575512	Repair [A/C SRS]
218.	D5754050200XX XX	D5754050200051Z D5754050200251Z D5755805500600A D5754050200151Z D5754050200351Z D5754050200351Z D5754050200251A D5754050200451A D5754050200351A D5754050200551A	FAIRING ASSY- FWD, FIXED, F LAP TRACK 2	AIRBUS	575512	Repair [A/C SRS]
219.	D5755805500700 A	D5755805500700A	FAIRING ASSY- FWD, FIXED, F LAP TRACK 2	AIRBUS	575512	Repair [A/C SRS]
220.	D575510530XX00 X	D5755105300000Z D5755105300000A D5755105300200A	FAIRING ASSY- MOVABLE, FL	AIRBUS	575512	Repair



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 37 of 93

		D5755105300400A D5755105300600A D5755105300800A D5755105301000A D5755105301200A D5755105301400A	AP TRACK 2 (LH)			[A/C SRS]
221.	D575510530XX00 X	D5755105300100Z D5755105300100A D5755105300300A D5755105300500A D5755105300700A D5755105300900A D5755105301100A D5755105301300A D5755105301500A	FAIRING ASSY- MOVABLE,FL AP TRACK 2 (RH)	AIRBUS	575512	Repair [A/C SRS]
222.	D575406010XX00 X	D5754060100400Z D5754060100600A D5754060100800A D5754060101000A D5754060100700A D5754060100900A D5754060101100A D5754060100600Z D5754060100500Z D5754060100700Z	FAIRING ASSY- FWD, FIXED, F LAP TRACK 3	AIRBUS	575513	Repair [A/C SRS]
223.	D5755805500X00 A	D5755805500200A D5755805500300A	FAIRING ASSY- FWD, FIXED, F LAP TRACK 3	AIRBUS	575513	Repair [A/C SRS]
224.	D5754060200XX XX	D5754060200251Z D5754060200351Z D5754060200351Z D5754060200251A D5754060200451A D5754060200351A D5754060200551A	FAIRING ASSY- AFT, FIXED, FL AP TRACK 3	AIRBUS	575513	Repair [A/C SRS]
225.	D5755805500X00 A	D5755805500800A D5755805500900A	FAIRING ASSY- AFT, FIXED, FL AP TRACK 3	AIRBUS	575513	Repair [A/C SRS]
226.	D5755105400000 Z	D5755105400000Z D5755105400000A D5755105400200A D5755105400400A D5755105400600A D5755105400800A D5755105401000A D5755105401200A D5755105401400A	FAIRING ASSY- MOVABLE, FL AP TRACK 3 (LH)	AIRBUS	575513	Repair [A/C SRS]
227.	D575510540XX00 X	D5755105400100Z D5754061001300Z D5754061001500Z D5755105400300A D5755105400500A D5755105400700A D5755105400900A D5755105401100A D5755105401300A D5755105401500A	FAIRING ASSY- MOVABLE, FL AP TRACK 3 (RH)	AIRBUS	575513	Repair [A/C SRS]
228.	D575407010XX00 X	D5754070100400Z D5754070100600Z D5754070100500Z D5754070100700Z D5754070100600A D5754070100800A	FAIRING ASSY- FWD, FIXED, F LAP TRACK 4	AIRBUS	575514	Repair [A/C SRS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 38 of 93

		D5754070101000A D5754070100700A D5754070100900A D5754070101100A				
229.	D575580550XX00 A	D5755805500400A D5755805500500A	FAIRING ASSY- FWD, FIXED, F LAP TRACK 4	AIRBUS	575514	Repair [A/C SRS]
230.	D5754070200XX XX	D5754070200051Z D5754070200251Z D5754070200251Z D5754070200151Z D5754070200351Z D5754070200351Z D5754070200251A D5754070200451A D5754070200351A D5754070200551A	FAIRING ASSY- AFT, FIXED, FL AP TRACK 4	AIRBUS	575514	Repair [A/C SRS]
231.	D5755805501X00 A	D5755805501000A D5755805501100A	FAIRING ASSY- AFT, FIXED, FL AP TRACK 4	AIRBUS	575514	Repair [A/C SRS]
232.	D575510550XX00 X	D5755105500000A D5755105500000T D5755105500000Z D5755105500200A D5755105500400A D5755105500600A D5755105500800A D5755105501000A D5755105501200A D5755105501400A	FAIRING ASSY- MOVABLE, FL AP TRACK 4 (LH)	AIRBUS	575514	Repair [A/C SRS]
233.	D5754071001X00 X	D5754071001000H D5754071001000T D5754071001200H D5754071001200T	FAIRING ASSY- MOVABLE, FL AP TRACK 4 (LH)	AIRBUS	575514	Repair [A/C SRS]
234.	D575510550XX00 X	D5755105500100A D5755105500100T D5755105500100Z D5755105500300A D5755105500500A D5755105500700A D5755105500900A D5755105501100A D5755105501300A D5755105501500A	FAIRING ASSY- MOVABLE, FL AP TRACK 4 (RH)	AIRBUS	575514	Repair [A/C SRS]
235.	D5754071001X00 H	D5754071001100H D5754071001300H	FAIRING ASSY- MOVABLE, FL AP TRACK 4 (RH)	AIRBUS	575514	Repair [A/C SRS]
236.	D576400000XX00 X	D5764000000800Z D5764000000200Z D5764000000400Z D5764000000600Z D5764000000800A D5764000001000A D5764000001200A	AILERON ASSY (LH)	AIRBUS	576121	Repair [A/C SRS]
237.	D5765000000X00 A	D5765000000000A D5765000000200A D5765000000600A	AILERON ASSY (LH)	AIRBUS	576121	Repair [A/C SRS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 39 of 93

238.	D576400000XX00 X	D5764000000900Z D5764000000300Z D5764000000500Z D5764000000700Z D5764000000900A D5764000001100A D5764000001300A	AILERON ASSY (RH)	AIRBUS	576121	Repair [A/C SRS]
239.	D5765000000X00 A	D5765000000100A D5765000000300A D5765000000700A	AILERON ASSY (RH)	AIRBUS	576121	Repair [A/C SRS]
240.	D5775001700X00 X	D5775001700000Z D5775001700000A D5775001700200A D5775001700400A D5775001700600A	SPOILER ASSY-NO 1 (LH)	AIRBUS	577121	Repair [A/C SRS]
241.	D5775610100200 Z	D5775610100200Z	SPOILER ASSY-NO 1 (LH)	AIRBUS	577121	Repair [A/C SRS]
242.	D5775001700X00 X	D5775001700100Z D5775001700100A D5775001700300A D5775001700500A D5775001700700A	SPOILER ASSY-NO 1 (RH)	AIRBUS	577121	Repair [A/C SRS]
243.	D5775610100300 Z	D5775610100300Z	SPOILER ASSY-NO 1 (RH)	AIRBUS	577121	Repair [A/C SRS]
244.	D5775001900X00 X	D5775001900000Z D5775001900000A D5775001900200A D5775001900400A D5775001900600A	SPOILER ASSY-NO 2 (LH)	AIRBUS	577221	Repair [A/C SRS]
245.	D5775612200200 Z	D5775612200200Z	SPOILER ASSY-NO 2 (LH)	AIRBUS	577221	Repair [A/C SRS]
246.	D5775001900X00 X	D5775001900100Z D5775001900100A D5775001900300A D5775001900500A D5775001900700A	SPOILER ASSY-NO 2 (RH)	AIRBUS	577221	Repair [A/C SRS]
247.	D5775612200300 Z	D5775612200300Z	SPOILER ASSY-NO 2 (RH)	AIRBUS	577221	Repair [A/C SRS]
248.	D5775002000X00 X	D5775002000000Z D5775002000000A D5775002000200A D5775002000400A	SPOILER ASSY-NO 3 (LH)	AIRBUS	577321	Repair [A/C SRS]
249.	D5774503000600 Z	D5774503000600Z	SPOILER ASSY-NO 3 (LH)	AIRBUS	577321	Repair [A/C SRS]
250.	D5775000300000 Z	D5775000300000Z	SPOILER ASSY-NO 3 (LH)	AIRBUS	577321	Repair [A/C SRS]
251.	D5775002000X00 X	D5775002000100Z D5775002000100A D5775002000300A D5775002000500A	SPOILER ASSY-NO 3 (RH)	AIRBUS	577321	Repair [A/C SRS]
252.	D5774503000700 Z	D5774503000700Z	SPOILER ASSY-NO 3 (RH)	AIRBUS	577321	Repair [A/C SRS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 40 of 93

253.	D5775000300100Z	D5775000300100Z	SPOILER ASSY-NO 3 (RH)	AIRBUS	577321	Repair [A/C SRS]
254.	D5775002100000Z	D5775002100000Z	SPOILER ASSY-NO 4 (LH)	AIRBUS	577421	Repair [A/C SRS]
255.	D5774503200600X	D5774503200600 D5774503200600Z	SPOILER ASSY-NO 4 (LH)	AIRBUS	577421	Repair [A/C SRS]
256.	D5775000400000Z	D5775000400000Z	SPOILER ASSY-NO 4 (LH)	AIRBUS	577421	Repair [A/C SRS]
257.	D5775002100100Z	D5775002100100Z	SPOILER ASSY-NO 4 (RH)	AIRBUS	577421	Repair [A/C SRS]
258.	D5774503200700	D5774503200700 D5774503200700Z	SPOILER ASSY-NO 4 (RH)	AIRBUS	577421	Repair [A/C SRS]
259.	D5775000400100Z	D5775000400100Z	SPOILER ASSY-NO 4 (RH)	AIRBUS	577421	Repair [A/C SRS]
260.	D5775002200X00X	D5775002200000Z D5775002200000A D5775002200200A D5775002200400A	SPOILER ASSY-NO 5 (LH)	AIRBUS	577521	Repair [A/C SRS]
261.	D5774503401600Z	D5774503401600Z	SPOILER ASSY-NO 5 (LH)	AIRBUS	577521	Repair [A/C SRS]
262.	D5775000500000Z	D5775000500000Z	SPOILER ASSY-NO 5 (LH)	AIRBUS	577521	Repair [A/C SRS]
263.	D5775002200X00X	D5775002200100Z D5775002200100A D5775002200300A D5775002200500A	SPOILER ASSY-NO 5 (RH)	AIRBUS	577521	Repair [A/C SRS]
264.	D5774503401700Z	D5774503401700Z	SPOILER ASSY-NO 5 (RH)	AIRBUS	577521	Repair [A/C SRS]
265.	D5775000500100Z	D5775000500100Z	SPOILER ASSY-NO 5 (RH)	AIRBUS	577521	Repair [A/C SRS]
A/C BOEING B737NG						
266.	183A0000	183A0000-1, 183A0000-3 183A0000-9, 183A0000-11 183A0000-13, 183A0000-15	ELEVATOR INSTL LH	BOEING	552000	Repair [A/C SRS]
267.	183A0000	183A0000-2, 183A0000-4 183A0000-10, 183A0000-12 183A0000-14, 183A0000-16	ELEVATOR INSTL RH	BOEING	552000	Repair [A/C SRS]
268.	183A0107	183A0107-1 183A0107-5	ELEVATOR ASSY LH	BOEING	552000	Repair [A/C SRS]
269.	183A0107	183A0107-2 183A0107-6	ELEVATOR ASSY RH	BOEING	552000	Repair [A/C SRS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 41 of 93

270.	186A1001	186A1001-3, 186A1001-7 186A1001-15, 186A1001-23	LEADING EDGE ASSY HS LH	BOEING	551052	Repair [A/C SRS]
271.	186A1001	186A1001-4, 186A1001-8 186A1001-16, 186A1001-24	LEADING EDGE ASSY HS RH	BOEING	551052	Repair [A/C SRS]
272.	113A3001	113A3001-3, 113A3001-5 113A3001-7, 113A3001-9 113A3001-11, 113A3001-13 113A3001-15, 113A3001-17 113A3001-19, 113A3001-21 113A3001-23, 113A3001-25	FLAP INSTL TE (OUTBD LH)	BOEING	575200	Repair [A/C SRS]
273.	113A3001	113A3001-4, 113A3001-6 113A3001-8, 113A3001-10 113A3001-12, 113A3001-14 113A3001-16, 113A3001-18 113A3001-20, 113A3001-22 113A3001-24, 113A3001-26	FLAP INSTL TE (OUTBD RH)	BOEING	575200	Repair [A/C SRS]
274.	113A2001	113A2001-1, 113A2001-3 113A2001-5, 113A2001-7 113A2001-9, 113A2001-11 113A2001-13, 113A2001-15	FLAP INSTL (INBD LH)	BOEING	575200	Repair [A/C SRS]
275.	113A2001	113A2001-2, 113A2001-4 113A2001-6, 113A2001-8 113A2001-10, 113A2001-12 113A2001-14, 113A2001-16	FLAP INSTL (INBD RH)	BOEING	575200	Repair [A/C SRS]
276.	113A7001	113A7001-1, 113A7001-3 113A7001-5, 113A7001-7 113A7001-9	AILERON INSTL LH	BOEING	576000	Repair [A/C SRS]
277.	113A7001	113A7001-2, 113A7001-4 113A7001-6, 113A7001-8 113A7001-10	AILERON INSTL RH	BOEING	576000	Repair [A/C SRS]
278.	113A4600	113A4600-1, 113A4600-3 113A4600-5, 113A4600-7	SPOILER ASSY #6 INBD LH	BOEING	577000	Repair [A/C SRS]
279.	113A4600	113A4600-2, 113A4600-4 113A4600-6, 113A4600-8	SPOILER ASSY #6 INBD RH	BOEING	577000	Repair [A/C SRS]
A/C BOEING B757						
280.	149N7410	149N7410-403 149N7410-404	UNDERWING FAIRING	BOEING	575300	Repair [A/C SRS]
281.	113N17XX	113N1714, 113N1719 113N1734, 113N1739 113N1753, 113N1761 113N1719, 113N1761	FAIRING	BOEING	575300	Repair [A/C SRS]
A/C BOEING B767						
282.	113T1861	113T1861	FAIRING	BOEING	575300	Repair [A/C SRS]
283.	113T1871	113T1871	FAIRING	BOEING	575300	Repair [A/C SRS]
284.	113T1852	113T1852	FAIRING	BOEING	575300	Repair [A/C SRS]
285.	113T1862	113T1862	FAIRING	BOEING	575300	



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 42 of 93

						Repair [A/C SRS]
286.	113T1872	113T1872	FAIRING	BOEING	575300	Repair [A/C SRS]
287.	113T1711	113T1711	FAIRING	BOEING	575300	Repair [A/C SRS]
288.	113T1721	113T1721	FAIRING	BOEING	575300	Repair [A/C SRS]
289.	113T1771	113T1771	FAIRING	BOEING	575300	Repair [A/C SRS]

Rating item: C12 Hydraulic Power

Item n°	Part number / Model series	Full part numbers / Models	Description	Manufacturer	CMM / ATA chapter	Work scope Level / Component maintenance shop
Hydraulic Valves' Maintenance						
290.	C82LL0010	C82LL0010	Drain Valve	Goodrich	29-11-13	Repair [A/C CMS]
291.	EATON Model No: PV3-240-10 PV3-240-10A PV3-240-10C PV3-240-10D Part Number: 623977, 887111, 887673, 3031863-001	EATON Model No: PV3-240-10 PV3-240-10A PV3-240-10C PV3-240-10D Part Number: 623977, 887111, 887673, 3031863-001	Variable Displacement Hydraulic Pump	EATON Corporation	29-11-34	All maintenance and overhaul excluding "Repair" section items No 3, 8, 11, 12, 14-17 [A/C CMS]
292.	Model No: AP15V-027 AP15V-027-01 Parker Part No: 4205400 4205401	Model No: AP15V-027 AP15V-027-01 Parker Part No: 4205400 4205401	Variable Delivery Hydraulic Pump	Parker Hannifin Corporation	29-11-33	All maintenance including repair [A/C CMS]

Rating item: C13 Indicating / Recording Systems

Item n°	Part number / Model series	Full part numbers / Models	Description	Manufacturer	CMM / ATA chapter	Work scope Level / Component maintenance shop
A/C Cockpit panels maintenance						

Rating item: C14 Landing Gear

Item n°	Part number / Model series	Full part numbers / Models	Description	Manufacturer	CMM / ATA chapter	Work scope Level / Component maintenance shop
Wheel and Brake maintenance						
293.	C20195162	C20195162 C20195162A	MLG Wheel Assembly	Messier- Bugatti- Dowty	32-47-46	Overhaul [A/C CMS]
294.	3-1530-series	3-1530, 3-1530-1	Main Wheel	Goodrich	32-41-20	Tire change



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 43 of 93

			Assembly			[A/C CMS]
295.	3-1531-series	3-1531, 3-1531-1 3-1531-2, 3-1531-3	NLG Wheel Assembly	Goodrich	32-41-13	Overhaul [A/C CMS]
296.	3-1558	3-1558	MLG Wheel Assembly	Goodrich	32-40-50	Overhaul [A/C CMS]
297.	2609801-1	2609801-1	Main Wheel Assembly	Honeywell	32-40-11	Overhaul [A/C CMS]
298.	2607825-series	2607825-1 2607825-2	Nose Wheel Assembly	Honeywell	32-40-10	Overhaul [A/C CMS]
299.	2606671-series	2606671-1 2606671-2 2606671-3	Main Wheel Assembly	Honeywell	32-40-09	Overhaul [A/C CMS]
300.	C20509000	C20509000	MLG Wheel Assembly	Messier-Bugatti-Dowty	32-49-51	Overhaul [A/C CMS]
301.	C20626200	C20626200	MLG Wheel Assembly	Messier-Bugatti-Dowty	32-49-83	Overhaul [A/C CMS]
302.	C20637000 C20637100	C20637000 C20637100	NLG Wheel Assembly	Safran Landings Systems	32-49-82	Overhaul [A/C CMS]
303.	3-1428	3-1422 3-1427 3-1428	Main Wheel Assembly	Goodrich	32-40-22	Overhaul [A/C CMS]
304.	3-1423-series	3-1423-1 3-1423-2	NLG Wheel Assembly	Goodrich	32-40-24	Overhaul [A/C CMS]
305.	2612311	2612311-1	Main Wheel Assembly	Honeywell	32-40-14	Overhaul [A/C CMS]
306.	C20500100	C20500100	Main Wheel Assembly	Messier-Bugatti and Goodrich	32-42-15	Overhaul [A/C CMS]
307.	C202255XX	C20225508, C20225509 C20225510	Carbon Brake	SAFRAN	32-47-61	Overhaul [A/C CMS]
308.	C2078000X	C20780000, C20780001 C20780002	Carbon Brake	SAFRAN	32-48-21	Overhaul [A/C CMS]
309.	2-1587-series	2-1587-1	MLG Brake Assembly	Goodrich	32-40-48	Overhaul [A/C CMS]
310.	2606672-series	2606672-1, 2606672-2 2606672-3, 2606672-4	Main Brake Assembly	Honeywell	32-40-08	Overhaul [A/C CMS]
311.	C20508000	C20508000	Carbon Brake Assembly	Messier-Bugatti-Dowty	32-49-50	Overhaul [A/C CMS]
312.	C20633000	C20633000	Carbon Brake Assembly	Messier-Bugatti-Dowty	32-49-80	Overhaul [A/C CMS]
313.	2612312-1	2612312-1	Main Brake Assembly	Honeywell	32-40-15	Overhaul [A/C CMS]
314.	2-1457 Series	2-1457; 2-1457-1; 2-1457-2	MLG Brake Assembly	Goodrich	32-40-26	Overhaul [A/C CMS]
315.	90000581-series	90000581 90000581WT 90000581-1 90000581-1WT 90000581-1WTA 90000581-1WTB 90000581-1WTC 90000581-1WTD 90000581-1WTE 90000581-1WTF	Nose Wheel Assembly	Meggitt Aircraft Braking Systems	32-49-19	Overhaul [A/C CMS]


**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 44 of 93

316.	90000582-series	90000582 90000582WT 90000582WTA 90000582WTB 90000582WTC 90000582WTD 90000582-1 90000582-1WT 90000582-1WTA 90000582-1WTB 90000582-1WTC 90000582-1WTD	Main Wheel Assembly	Meggitt Aircraft Braking Systems	32-49-21	Overhaul [A/C CMS]
317.	90000583-series	90000583-1 90000583-2 90000583-3 90000583-5 90000583-6 90000583-1PR 90000583-2PR; 90000583-3PR 90000583-5PR; 90000583-6PR	Brake Assembly	Meggitt Aircraft Braking Systems	32-49-23	Overhaul [A/C CMS]

Fuses Maintenance

318.	n/a	6272-1 (10-61245-24) 6273-1 (10-61245-17) 6273-5 (10-61245-23)	Hydraulic Fuse	Pneudraulics, Inc	32-40-05	Overhaul [A/C CMS]
319.	2-8020 - series	2-8020-1 (S274A100-1) 2-8020-2 (S274A100-2) 2-8020-3 (S274A100-3) 2-8020-5 (S274A100-5) 2-8020-6 (S274A100-6) 2-8020-11 (10-62204-11) 2-8020-12 (10-62204-12) 2-8020-13 (10-62204-13) 2-8020-14 (10-62204-14) 2-8020-15 (10-62204-15) 2-8020-16 (10-62204-16) 2-8020-18 (S273N203-4) 2-8020-24 (10-62204-24) 2-8020-25 (S274A100-11) 2-8020-26 (S274A100-12) 2-8020-27 (S274A100-13) 2-8020-28 (S274A100-15) 2-8020-29 (S274A100-16)	Fuse Assembly	GE Aviation	32-31-04	Overhaul [A/C CMS]
320.	2-8041-1 (10-62204-17)	2-8041-1 (10-62204-17)	Fuse Assembly	Triumph Actuation Systems - Yakima	32-40-18	Overhaul [A/C CMS]
321.	2-7735-1 (10-62204-5)	2-7735-1 (10-62204-5)	Fuse Assembly Quantity Measuring	Triumph Actuation Systems - Yakima	32-40-13	Overhaul [A/C CMS]

Thermocouple maintenance

322.	C2022900 - series	C20229000 C20229001	Thermocouple	Messier-Bugatti-Dowty	32-47-21	Overhaul [A/C CMS]
------	-------------------	------------------------	--------------	-----------------------	----------	-----------------------

Rating item: C15 Oxygen

Item nº	Part number / Model series	Full part numbers / Models	Description	Manufacturer	CMM / ATA chapter	Work scope Level / Component maintenance shop
Oxygen Masks Maintenance						
323.	MC10-series	MC10-02-01, MC10-02-02 MC10-02-03, MC10-02-04 MC10-02-05, MC10-02-06 MC10-02-07, MC10-02-10 MC10-02-22, MC10-02-50	Crew Oxygen Mask Regulator	Zodiac Intertechnique	35-13-63	Testing and Repair [A/C CMS]



	MC10-02-54, MC10-02-55 MC10-02-69, MC10-02-102 MC10-02-104, MC10-02-105 MC10-02-106, MC10-02-107 MC10-02-108, MC10-02-109 MC10-02-112, MC10-02-115 MC10-02-116, MC10-02-117 MC10-02-121, MC10-02-155 MC10-02-169, MC10-02-170 MC10-02-171, MC10-04-01 MC10-04-02, MC10-04-07 MC10-04-21, MC10-04-22 MC10-04-27, MC10-04-77 MC10-04-101, MC10-04-102 MC10-04-105, MC10-04-107 MC10-04-109, MC10-04-110 MC10-04-111, MC10-04-112 MC10-04-115, MC10-04-116 MC10-04-121, MC10-04-122 MC10-04-127, MC10-04-157 MC10-04-159, MC10-04-177 MC10-05-04, MC10-05-100 MC10-05-101, MC10-05-102 MC10-05-104, MC10-05-124 MC10-05-152, MC10-06-00 MC10-06-01, MC10-06-03 MC10-06-20, MC10-06-21 MC10-06-23, MC10-06-100 MC10-06-101, MC10-06-102 MC10-06-104, MC10-06-105 MC10-06-106, MC10-06-120 MC10-06-121, MC10-06-124 MC10-06-125, MC10-06-126 MC10-08-00, MC10-08-01 MC10-08-02, MC10-08-05 MC10-08-09, MC10-08-13 MC10-08-25, MC10-08-100 MC10-08-102, MC10-08-103 MC10-08-104, MC10-08-106 MC10-08-107, MC10-08-108 MC10-08-109, MC10-08-110 MC10-08-111, MC10-08-112 MC10-08-120, MC10-08-123 MC10-08-124, MC10-08-126 MC10-08-127, MC10-08-128 MC10-08-209, MC10-09-00 MC10-09-01, MC10-10-100 MC10-10-101, MC10-10-102 MC10-10-103, MC10-10-104 MC10-12-100, MC10-12-101 MC10-12-150, MC10-12-151 MC10-13-02, MC10-13-03 MC10-13-04, MC10-13-05 MC10-13-102, MC10-13-103 MC10-13-104, MC10-13-114 MC10-13-150, MC10-14-00 MC10-14-01, MC10-14-02 MC10-14-20, MC10-14-21 MC10-14-22, MC10-14-100 MC10-14-101, MC10-14-102 MC10-14-103, MC10-14-104 MC10-14-120, MC10-14-121 MC10-14-122, MC10-14-123 MC10-14-124, MC10-15-01 MC10-15-02, MC10-15-03 MC10-15-04, MC10-15-05 MC10-15-07, MC10-15-09				
--	---	--	--	--	--



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 46 of 93

		MC10-15-10, MC10-15-11 MC10-15-12, MC10-15-13 MC10-15-17, MC10-15-18 MC10-15-101, MC10-15-102 MC10-15-104, MC10-15-105 MC10-15-107, MC10-15-108 MC10-15-109, MC10-15-113 MC10-15-114, MC10-15-115 MC10-15-116, MC10-15-117 MC10-15-118, MC10-15-119 MC10-15-120, MC10-15-121 MC10-15-122, MC10-15-151 MC10-15-152, MC10-15-155 MC10-15-157, MC10-15-158 MC10-15-159, MC10-15-166 MC10-15-167, MC10-15-168 MC10-15-170, MC10-15-171 MC10-15-176, MC10-16-100 MC10-16-101, MC10-16-103 MC10-16-104, MC10-16-105 MC10-16-150, MC10-16-151 MC10-16-152, MC10-16-153 MC10-17-00, MC10-17-101 MC10-19-00, MC10-19-01 MC10-19-02, MC10-19-101 MC10-19-102, MC10-19-103 MC10-19-151, MC10-20-00 MC10-22-00, MC10-22-01 MC10-22-100, MC10-22-101 MC10-25-00, MC10-25-01 MC10-25-04, MC10-25-101 MC10-25-102, MC10-25-103 MC10-25-104, MC10-25-105 MC10-25-106, MC10-25-107 MC10-25-108, MC10-25-124 MC10-25-154, MC10-25-158 MC10-25-204, MC10-32-101 MC10-32-102, MC10-32-103 MC10-35-101, MC10-35-102				
324.	MF10-series	MF10-02-01, MF10-02-02, MF10-02-03, MF10-02-04, MF10-02-05, MF10-02-06, MF10-02-08, MF10-02-10, MF10-02-11, MF10-02-12, MF10-02-13, MF10-02-14, MF10-02-20, MF10-02-21, MF10-03-01, MF10-03-02, MF10-03-03, MF10-03-04, MF10-03-05, MF10-03-08, MF10-03-10, MF10-03-11, MF10-03-12, MF10-03-14, MF10-03-15, MF10-04-01, MF10-04-02, MF10-04-05, MF10-04-06, MF10-04-07, MF10-05-01, MF10-05-02, MF10-05-03, MF10-05-04, MF10-05-05, MF10-05-07, MF10-05-08, MF10-05-11, MF10-05-12, MF10-05-14, MF10-05-15, MF10-08-01, MF10-08-02, MF10-09-01, MF10-10-00, MF10-10-01, MF10-30-01, MF10-30-02, MF10-30-03, MF10-30-13	Full face quick donning mask regulator	Zodiac Aerotechnics	35-13-61	Testing and Repair [A/C CMS]
325.	MF20-series	MF20-001, MF20-002 MF20-003, MF20-004 MF20-005, MF20-006	Full face quick donning mask	Zodiac Aerotechnics	35-13-60	Testing and Repair



		MF20-007, MF20-010 MF20-013, MF20-028 MF20-029, MF20-030 MF20-107, MF20-108 MF20-501, MF20-502 MF20-503, MF20-504 MF20-506, MF20-507 MF20-508, MF20-509 MF20-510, MF20-511 MF20-512, MF20-513 MF20-514, MF20-515 MF20-516, MF20-517 MF20-518, MF20-519 MF20-520, MF20-524 MF20-527, MF20-528 MF20-529, MF20-530 MF20-531, MF20-532 MF20-534, MF20-536 MF20-537, MF20-539 MF20-540, MF20-541 MF20-542, MF20-543 MF20-544, MF20-546 MF20-547, MF20-548 MF20-549, MF20-550 MF20-551, MF20-554 MF20-556, MF20-575 MF20-576	regulator			[A/C CMS]
326.	174095-series	174095-MA, 174095-MB 174095-MC, 174095-MD 174095-ME, 174095-MF 174095-MG, 174095-MH 174095-MJ, 174095-MK 174095-ML, 174095-MM 174095-M1, 174095-M2 174095-M3, 174095-M4 174095-M5, 174095-M6 174095-M7, 174095-M8 174095-M9, 174095-1E 174095-12, 174095-35, 174095-48 174095-51, 174095-52 174095-54, 174095-57 174095-58, 174095-59 174095-60, 174095-61 174095-62, 174095-66 174095-73, 174095-74 174095-76, 174095-87 174095-96, 174095-97 174095-98 174095-801, 174095-802 174095-803, 174095-804 174095-805, 174095-806 174095-807, 174095-808 174095-809	Passenger Oxygen mask Assembly	B/E Aerospace Inc.	35-24-04	Repacking [A/C CMS]
327.	174097-series	174097-01, 174097-04 174097-05, 174097-11 174097-12, 174097-17 174097-24, 174097-25 174097-27, 174097-28 174097-29, 174097-30 174097-31, 174097-32 174097-33, 174097-34 174097-40, 174097-47 174097-48, 174097-51 174097-52, 174097-53 174097-54, 174097-55 174097-56, 174097-57	Passenger Oxygen mask Assembly	B/E Aerospace Inc.	35-24-04	Repacking [A/C CMS]

**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 48 of 93

		174097-58, 174097-59 174097-71, 174097-72 174097-73, 174097-74 174097-75, 174097-76 174097-80, 174097-83 174097-85, 174097-86 174097-88, 174097-89 174097-801, 174097-802 174097-803, 174097-804 174097-805, 174097-806 174097-807, 174097-808 174097-809				
328.	289-601-series	289-601-066-1, 289-601-066-2 289-601-10, 289-601-11 289-601-11-1, 289-601-12 289-601-12-1, 289-601-13 289-601-13-1 289-601-14 289-601-14-1 289-601-15 289-601-16 BOEING LB PN BWM7002-505 289-601-17 BOEING LB PN BWM7002-507 289-601-17-1 289-601-18 CANADAIR PN 900-002-071-01 289-601-2 BOEING LB PN BWM7002-503 289-601-202 BOEING LB PN BWM7002-511 289-601-203 289-601-204 289-601-205 BOEING LB PN BWM7002-509 289-601-206 289-601-206-1 289-601-228-8 289-601-228-9 289-601-229 289-601-230 289-601-232 BOEING LB PN BWM7002-513 289-601-233 BOEING LB PN BWM7002-515 289-601-234 BOEING LB PN BWM7002-521 289-601-235 EROS PN 441279 289-601-239 RAYTHEON PN 114-560028-1 289-601-240 289-601-241 289-601-242 289-601-243 289-601-244 289-601-245 289-601-246 289-601-247 289-601-248 289-601-248-1 289-601-249 EROS PN MW3801 289-601-25 PPP PN 200201 289-601-250 289-601-251 289-601-252 289-601-253 289-601-254 289-601-255 289-601-330-1 289-601-333 289-601-333-1 289-601-338 BOEING PN 417T4205-69 289-601-338-1 BOEING PN 417T4205-169 289-601-339 BOEING PN 417T4205-70 289-601-339-1 BOEING PN 417T4205-170 289-601-34 289-601-340 289-601-340-1 289-601-341	Passenger Oxygen Mask	ZODIAC AEROSPACE	35-22-26	Inspection / Testing / Repacking [A/C CMS]



BOEING PN 417T4205-71 289-601-341-1 BOEING PN 417T4205-171 289-601-341-2 BOEING PN 417T4205-197 289-601-342 289-601-342-1 289-601-343 289-601-343-1 289-601-344 BOEING PN 417T4205-72 289-601-344-1 BOEING PN 417T4205-172 289-601-345 BOEING PN 417T4205-73 289-601-345-1 BOEING PN 417T4205-173 289-601-346 289-601-35 289-601-397 BOEING PN 417T4205-153 289-601-399 BOEING PN 417T4205-180 289-601-4 289-601-40 BOEING PN 417T4205-203 289-601-400 BOEING PN 10-60137-152 289-601-401 BOEING PN 10-60137-153 289-601-402 BOEING PN 10-60137-154 289-601-403 BOEING PN 10-60137-155 289-601-404 BOEING PN 10-60137-156 289-601-405 BOEING PN 10-60137-157 289-601-406 BOEING PN 10-60137-158 289-601-407 BOEING PN 10-60137-159 289-601-408 BOEING PN 10-60137-160 289-601-409 BOEING PN 10-60137-161 289-601-41 BOEING PN 417T4205-204 289-601-410 BOEING PN 10-60137-162 289-601-411 BOEING PN 10-60137-163 289-601-412 BOEING PN 10-60137-164 289-601-414 BOEING PN 10-60137-165 289-601-42 BOEING PN 417T4205-223 289-601-433-01 289-601-434 289-601-441-1 289-601-453-1 289-601-453-2 289-601-724-26A EROS PN MW39-26 289-601-724-27A EROS PN MW39-27 289-601-724-28A EROS PN MW39-28 289-601-724-29A EROS PN MW39-29 289-601-724-2A EROS PN MW39-02				
--	--	--	--	--



	289-601-724-30A EROS PN MW39-30 289-601-724-31A EROS PN MW39-31 289-601-724-32A EROS PN MW39-32 289-601-724-33A EROS PN MW39-33 289-601-724-34A EROS PN MW39-34 289-601-724-35A EROS PN MW39-35 289-601-724-36A EROS PN MW39-36 289-601-724-37A EROS PN MW39-37 289-601-724-38A EROS PN MW39-38 289-601-724-39A EROS PN MW39-01 289-601-724-3A EROS PN MW39-03 289-601-724-40A EROS PN MW39-40 289-601-724-41A EROS PN MW39-41 289-601-724-42A EROS PN MW39-42 289-601-724-43A EROS PN MW39-43 289-601-724-44A 289-601-724-45A 289-601-724-46A 289-601-724-47A 289-601-766 BOEING PN 10-60137-287 289-601-767 BOEING PN 10-60137-198 289-601-781 BOEING PN 10-60137-283 289-601-782 BOEING PN 10-60137-284 289-601-783 BOEING PN 10-60137-285 289-601-784 BOEING PN 10-60137-286 289-601-785 BOEING PN 10-60137-288 289-601-786 BOEING PN 10-60137-289 289-601-8 CANADAIIR PN 900-002-071-03 289-601-801 BOEING PN 10-60137-184 289-601-803 BOEING PN 10-60137-186 289-601-804 BOEING PN 10-60137-190 289-601-806 BOEING PN 10-60137-193 289-601-806-1 BOEING PN 417T4205-93 289-601-810 BOEING PN 417T4205-161 289-601-812 BOEING PN 417T4205-162 289-601-812-1				
--	--	--	--	--	--



	BOEING PN 417T4205-98 289-601-814 BOEING PN 417T4205-116 289-601-816 BOEING PN 417T4205-163 289-601-818 BOEING PN 417T4205-164 289-601-822 BOEING PN 417T4205-166 289-601-825 BOEING PN 417T4205-196 289-601-856 BOEING PN 10-60137-100 289-601-924-12A 289-601-924-13A 289-601-924-14A 289-601-924-15A 289-601-924-16A 289-601-924-17A 289-601-924-18A 289-601-924-19A 289-601-924-1A 289-601-924-20A 289-601-924-21A 289-601-924-22A 289-601-924-23A 289-601-924-24A 289-601-924-25A 289-601-924-26A 289-601-924-27A 289-601-924-28A 289-601-924-29A 289-601-924-2A 289-601-924-30A 289-601-924-31A 289-601-924-32A 289-601-924-33A 289-601-924-34A 289-601-924-35A 289-601-924-36A 289-601-924-37A 289-601-924-38A 289-601-924-39A 289-601-924-3A 289-601-924-40A 289-601-924-41A 289-601-924-42A 289-601-L108 LOCKHEED PN 671970-109 289-601-L110 LOCKHEED PN 671970-115 289-601-L111 LOCKHEED PN 671970-113 289-601-L112 289-664 802165-00 802165-02 802266-02 802266-03 802896-02 802896-03 803201-00 803201-01 803201-03 803201-05 803201-07 289-601-207 289-601-208 289-601-208-1 289-601-208-2 289-601-21 289-601-210 289-601-211 289-601-211-1 289-601-211-2 289-601-211-3 289-601-212 BOEING LB PN BWM7002-517				
--	---	--	--	--	--



289-601-212-1	289-601-213
289-601-213-1	289-601-213-2
289-601-214	
BOEING LB PN BWM7002-523	
289-601-214-1	289-601-215
289-601-216	289-601-216-1
289-601-217	289-601-218
BOEING LB PN BWM7002-519	
289-601-218-1	289-601-256
K-G PN 26795-002	
289-601-257	
K-G PN 48531-127	
289-601-258	289-601-259
289-601-26	289-601-27
289-601-274	
BOEING PN 417T4205-101	
289-601-276	
BOEING PN 417T4205-102	
289-601-278	
BOEING PN 417T4205-103	
289-601-28	289-601-280
BOEING PN 417T4205-104	
289-601-282	
BOEING PN 417T4205-105	
289-601-284	
BOEING PN 417T4205-117	
289-601-289	
BOEING PN 417T4205-128	
289-601-29	289-601-291
BOEING PN 417T4205-129	
289-601-293	
BOEING PN 417T4205-130	
289-601-295	
BOEING PN 417T4205-138	
289-601-296	
BOEING PN 417T4205-139	
289-601-298	
BOEING PN 417T4205-140	
289-601-299	
BOEING PN 417T4205-141	
289-601-352	
BOEING PN 417T4205-74	
289-601-352-1	
BOEING PN 417T4205-174	
289-601-3	289-601-30
289-601-302	289-601-302-1
289-601-351	289-601-351-1
289-601-301	289-601-301-1
289-601-353	289-601-353-1
289-601-354	289-601-355
289-601-356	289-601-357
289-601-358	289-601-359
289-601-360	289-601-361
289-601-361-1	289-601-362
289-601-362-1	289-601-37
BOEING PN 417T4205-200	
289-601-375	
BOEING PN 417T4205-75	
289-601-375-1	
BOEING PN 417T4205-175	
289-601-376	
BOEING PN 417T4205-76	
289-601-376-1	
BOEING PN 417T4205-176	
289-601-377	
BOEING PN 417T4205-77	
289-601-453-3	289-601-453-4



	289-601-5 BOEING LB PN BWM7002-1 289-601-50 289-601-6 289-601-6-1 289-601-7 289-601-700 BOEING PN 10-60137-120 289-601-701 BOEING PN 10-60137-121 289-601-702 BOEING PN 10-60137-122 289-601-703 BOEING PN 10-60137-123 289-601-704 BOEING PN 10-60137-124 289-601-705 BOEING PN 10-60137-125 289-601-706 BOEING PN 10-60137-126 289-601-707 BOEING PN 10-60137-127 289-601-708 BOEING PN 10-60137-128 289-601-709 BOEING PN 10-60137-129 289-601-710 BOEING PN 10-60137-130 289-601-711 BOEING PN 10-60137-131 289-601-712 BOEING PN 10-60137-132 289-601-713 BOEING PN 10-60137-133 289-601-714 BOEING PN 10-60137-134 289-601-715 BOEING PN 10-60137-135 289-601-716 BOEING PN 10-60137-136 289-601-717 BOEING PN 10-60137-137 289-601-724-48A 289-601-724-4A EROS PN MW39-04 289-601-724-5A EROS PN MW39-05 289-601-724-6A EROS PN MW39-06 289-601-724-7A EROS PN MW39-07 289-601-724-8A EROS PN MW39-08 289-601-724-9A EROS PN MW39-019 289-601-725 289-601-726 BOEING PN 10-60137-166 289-601-727 BOEING PN 10-60137-167 289-601-728 BOEING PN 10-60137-168 289-601-729 BOEING PN 10-60137-169 289-601-730 BOEING PN 10-60137-170 289-601-731 BOEING PN 10-60137-171 289-601-732 BOEING PN 10-60137-172				
--	--	--	--	--	--



289-601-733 BOEING PN 10-60137-173 289-601-734 BOEING PN 10-60137-174 289-601-735 BOEING PN 10-60137-175 289-601-736 BOEING PN 10-60137-176 289-601-737 BOEING PN 10-60137-177 289-601-738 BOEING PN 10-60137-178 289-601-739 BOEING PN 10-60137-179 289-601-740 BOEING PN 10-60137-180 289-601-741 BOEING PN 10-60137-181 289-601-857 BOEING PN 10-60137-101 289-601-858 BOEING PN 10-60137-102 289-601-859 BOEING PN 10-60137-103 289-601-860 BOEING PN 10-60137-104 289-601-861 BOEING PN 10-60137-105 289-601-862 BOEING PN 10-60137-106 289-601-863 BOEING PN 10-60137-107 289-601-864 BOEING PN 10-60137-108 289-601-865 BOEING PN 10-60137-109 289-601-866 BOEING PN 10-60137-110 289-601-867 BOEING PN 10-60137-111 289-601-868 BOEING PN 10-60137-112 289-601-869 BOEING PN 10-60137-113 289-601-871 BOEING PN 10-60137-114 289-601-872 BOEING PN 10-60137-115 289-601-873 BOEING PN 10-60137-116 289-601-874 BOEING PN 10-60137-117 289-601-875 BOEING PN 10-60137-118 289-601-876 BOEING PN 10-60137-33 289-601-877 BOEING PN 10-60137-119 289-601-878 NSN 1660-01-285-2424 289-601-879 BOEING PN 10-60137-189 289-601-880 289-601-924-43A 289-601-924-44A 289-601-924-45A 289-601-924-46A				
---	--	--	--	--



289-601-924-47A	
289-601-924-48A	
289-601-924-49A	
289-601-924-4A	
289-601-924-50A	
289-601-924-51A	
289-601-924-52A	
289-601-924-53A	
289-601-924-54A	
289-601-924-55A	
289-601-924-56A	
289-601-924-57A	
289-601-924-58A	
289-601-924-59A	
289-601-924-5A	
289-601-924-60A	
289-601-924-61A	
289-601-924-62A	
289-601-924-63A	
289-601-924-64A	
289-601-924-65A	
289-601-924-66A	
289-601-924-67A	
289-601-924-68A	
289-601-924-69A	
289-601-924-6A	
289-601-924-70A	
289-601-924-71A	
289-601-924-72A	
289-601-924-73A	
803201-10	803201-11
803201-13	803201-15
803201-17	803201-20
803203-01	803204-00
803204-01	803204-02
803204-03	289-601-219
289-601-22	289-601-221
289-601-222	289-601-222-1
289-601-223	289-601-223-1
289-601-224	289-601-224-1
289-601-224-2	289-601-225
289-601-226	289-601-227
289-601-228	289-601-228-1
289-601-228-10	
289-601-228-11	
289-601-228-2	289-601-228-3
289-601-228-4	289-601-228-5
289-601-228-6	289-601-228-7
289-601-303	289-601-303-1
289-601-304	289-601-304-1
289-601-305	289-601-305-1
289-601-306	
BOEING PN 417T4205-222	
289-601-308	289-601-310-01
289-601-317	289-601-317-1
289-601-318	289-601-318-1
289-601-319	289-601-319-1
289-601-32	289-601-320
289-601-320-1	289-601-321
289-601-322	289-601-328
289-601-328-1	289-601-329
289-601-329-1	289-601-330
289-601-377-1	
BOEING PN 417T4205-177	
289-601-378	
BOEING PN 417T4205-78	
289-601-379	



BOEING PN 417T4205-79
289-601-379-1
BOEING PN 417T4205-179
289-601-38
BOEING PN 417T4205-201
289-601-381
BOEING PN 417T4205-81
289-601-381-1
BOEING PN 417T4205-181
289-601-382
BOEING PN 417T4205-82
289-601-382-1
BOEING PN 417T4205-182
289-601-383
BOEING PN 417T4205-83
289-601-383-1
BOEING PN 417T4205-183
289-601-384
BOEING PN 417T4205-91
289-601-384-1
BOEING PN 417T4205-191
289-601-385
BOEING PN 417T4205-142
289-601-385-1
BOEING PN 417T4205-198
289-601-387
BOEING PN 417T4205-143
289-601-387-1
BOEING PN 417T4205-199
289-601-389
BOEING PN 417T4205-144
289-601-39
BOEING PN 417T4205-202
289-601-390
BOEING PN 417T4205-145
289-601-392
BOEING PN 417T4205-167
289-601-394
BOEING PN 417T4205-151
289-601-395
BOEING PN 417T4205-152
289-601-718
BOEING PN 10-60137-138
289-601-719
BOEING PN 10-60137-139
289-601-720
BOEING PN 10-60137-140
289-601-721
BOEING PN 10-60137-145
289-601-722
289-601-723
289-601-724-10A
EROS PN MW39-10
289-601-724-11A
EROS PN MW39-11
289-601-724-12A
EROS PN MW39-12
289-601-724-13A
EROS PN MW39-13
289-601-724-14A
EROS PN MW39-14
289-601-724-15A
EROS PN MW39-15
289-601-724-16A
EROS PN MW39-16
289-601-724-17A
EROS PN MW39-17



	289-601-724-18A EROS PN MW39-18 289-601-724-19A EROS PN MW39-19 289-601-724-1A EROS PN MW39-01 289-601-724-20A EROS PN MW39-20 289-601-724-21A EROS PN MW39-21 289-601-724-22A EROS PN MW39-22 289-601-724-23A EROS PN MW39-23 289-601-724-24A EROS PN MW39-24 289-601-724-25A EROS PN MW39-25 289-601-742 BOEING PN 10-60137-182 289-601-743 BOEING PN 10-60137-266 289-601-744 BOEING PN 10-60137-267 289-601-745 BOEING PN 10-60137-268 289-601-746 BOEING PN 10-60137-269 289-601-747 BOEING PN 10-60137-270 289-601-748 BOEING PN 10-60137-271 289-601-749 BOEING PN 10-60137-272 289-601-750 BOEING PN 10-60137-273 289-601-751 BOEING PN 10-60137-274 289-601-752 BOEING PN 10-60137-275 289-601-753 BOEING PN 10-60137-276 289-601-754 BOEING PN 10-60137-277 289-601-755 BOEING PN 10-60137-278 289-601-756 BOEING PN 10-60137-279 289-601-757 BOEING PN 10-60137-280 289-601-758 BOEING PN 10-60137-281 289-601-759 BOEING PN 10-60137-282 289-601-760 BOEING PN 10-60137-183 289-601-761 BOEING PN 10-60137-184 289-601-762 BOEING PN 10-60137-185 289-601-763 BOEING PN 10-60137-186 289-601-764 BOEING PN 10-60137-187 289-601-765 BOEING PN 10-60137-188 289-601-881				
--	--	--	--	--	--



	BOEING PN 10-60137-190 289-601-882 BOEING PN 10-60137-191 289-601-883 BOEING PN 10-60137-192 289-601-884 BOEING PN 10-60137-193 289-601-885 BOEING PN 10-60137-194 289-601-886 BOEING PN 10-60137-195 289-601-887 BOEING PN 10-60137-196 289-601-888 BOEING PN 10-60137-197 289-601-900 289-601-901-01 289-601-901-02 289-601-901-03 289-601-903-01 BOEING 17B2N8001-503 289-601-903-02 BOEING 17B2N8001-505 289-601-903-03 BOEING 17B2N8001-507 289-601-924-100 289-601-924-101 289-601-924-102 289-601-924-103 289-601-924-104 289-601-924-105 289-601-924-10A 289-601-924-11A 289-601-924-74A 289-601-924-75A 289-601-924-76A 289-601-924-77A 289-601-924-78A 289-601-924-79A 289-601-924-7A 289-601-924-80A 289-601-924-81A 289-601-924-82A 289-601-924-83A 289-601-924-84A 289-601-924-85A 289-601-924-86A 289-601-924-87A 289-601-924-88A 289-601-924-89A 289-601-924-8A 289-601-924-90A 289-601-924-91A 289-601-924-92A 289-601-924-93A 289-601-924-94A 289-601-924-95A 289-601-924-96A 289-601-924-97A 289-601-924-98A 289-601-924-99A 289-601-924-9A 289-601AF NSN 1660-00-382-9434 289-601AF2 NSN 1660-00-158-4626 289-601-L105				
--	---	--	--	--	--



289-601-L106
LOCKHEED PN 671970-105
289-601-L107
LOCKHEED PN 671970-107
803204-04 803204-10
803204-11 803204-12
803204-13 803204-14
803447-01 803589-01
289-601-066-1
289-601-066-2
289-601-10 289-601-11
289-601-11-1 289-601-12
289-601-12-1 289-601-13
289-601-13-1 289-601-14
289-601-14-1 289-601-15
289-601-16
BOEING LB PN BWM7002-505
289-601-17
BOEING LB PN BWM7002-507
289-601-203 289-601-204
289-601-205
BOEING LB PN BWM7002-509
289-601-206 289-601-206-1
289-601-228-8 289-601-228-9
289-601-229 289-601-230
289-601-232
BOEING LB PN BWM7002-513
289-601-233
BOEING LB PN BWM7002-515
289-601-234
BOEING LB PN BWM7002-521
289-601-235
EROS PN 441279
289-601-239
RAYTHEON PN 114-560028-1
289-601-240 289-601-241
289-601-242 289-601-243
289-601-244 289-601-245
289-601-246 289-601-247
289-601-248 289-601-248-1
289-601-249
EROS PN MW3801
289-601-25
PPP PN 200201
289-601-250 289-601-251
289-601-252 289-601-253
289-601-254 289-601-255
289-601-330-1 289-601-333
289-601-333-1 289-601-338
BOEING PN 417T4205-69
289-601-338-1
BOEING PN 417T4205-169
289-601-339
BOEING PN 417T4205-70
289-601-339-1
BOEING PN 417T4205-170
289-601-34 289-601-340
289-601-340-1 289-601-341
BOEING PN 417T4205-71
289-601-341-1
BOEING PN 417T4205-171
289-601-341-2
BOEING PN 417T4205-197
289-601-342 289-601-342-1
289-601-343 289-601-343-1
289-601-344
BOEING PN 417T4205-72



289-601-344-1
BOEING PN 417T4205-172
289-601-345
BOEING PN 417T4205-73
289-601-345-1
BOEING PN 417T4205-173
289-601-346 289-601-35
289-601-397
BOEING PN 417T4205-153
289-601-399
BOEING PN 417T4205-180
289-601-4 289-601-40
BOEING PN 417T4205-203
289-601-400
BOEING PN 10-60137-152
289-601-401
BOEING PN 10-60137-153
289-601-402
BOEING PN 10-60137-154
289-601-403
BOEING PN 10-60137-155
289-601-404
BOEING PN 10-60137-156
289-601-405
BOEING PN 10-60137-157
289-601-406
BOEING PN 10-60137-158
289-601-407
BOEING PN 10-60137-159
289-601-408
BOEING PN 10-60137-160
289-601-409
BOEING PN 10-60137-161
289-601-41
BOEING PN 417T4205-204
289-601-410
BOEING PN 10-60137-162
289-601-411
BOEING PN 10-60137-163
289-601-412
BOEING PN 10-60137-164
289-601-414
BOEING PN 10-60137-165
289-601-42
BOEING PN 417T4205-223
289-601-433-01 289-601-434
289-601-441-1 289-601-453-1
289-601-453-2
289-601-724-26A
EROS PN MW39-26
289-601-724-27A
EROS PN MW39-27
289-601-724-28A
EROS PN MW39-28
289-601-724-29A
EROS PN MW39-29
289-601-724-2A
EROS PN MW39-02
289-601-724-30A
EROS PN MW39-30
289-601-724-31A
EROS PN MW39-31
289-601-724-32A
EROS PN MW39-32
289-601-724-33A
EROS PN MW39-33
289-601-724-34A



	EROS PN MW39-34 289-601-724-35A EROS PN MW39-35 289-601-724-36A EROS PN MW39-36 289-601-724-37A EROS PN MW39-37 289-601-724-38A EROS PN MW39-38 289-601-724-39A EROS PN MW39-01 289-601-724-3A EROS PN MW39-03 289-601-724-40A EROS PN MW39-40 289-601-724-41A EROS PN MW39-41 289-601-724-42A EROS PN MW39-42 289-601-724-43A EROS PN MW39-43 289-601-724-44A 289-601-724-45A 289-601-724-46A 289-601-724-47A 289-601-766 BOEING PN 10-60137-287 289-601-767 BOEING PN 10-60137-198 289-601-781 BOEING PN 10-60137-283 289-601-782 BOEING PN 10-60137-284 289-601-783 BOEING PN 10-60137-285 289-601-784 BOEING PN 10-60137-286 289-601-785 BOEING PN 10-60137-288 289-601-786 BOEING PN 10-60137-289 289-601-8 CANADAIR PN 900-002-071-03 289-601-801 BOEING PN 10-60137-184 289-601-803 BOEING PN 10-60137-186 289-601-804 BOEING PN 10-60137-190 289-601-806 BOEING PN 10-60137-193 289-601-806-1 BOEING PN 417T4205-93 289-601-810 BOEING PN 417T4205-161 289-601-812 BOEING PN 417T4205-162 289-601-812-1 BOEING PN 417T4205-98 289-601-814 BOEING PN 417T4205-116 289-601-816 BOEING PN 417T4205-163 289-601-818 BOEING PN 417T4205-164 289-601-822 BOEING PN 417T4205-166				
--	---	--	--	--	--



289-601-825				
BOEING PN 417T4205-196				
289-601-856				
BOEING PN 10-60137-100				
289-601-924-12A				
289-601-924-13A				
289-601-924-14A				
289-601-924-15A				
289-601-924-16A				
289-601-924-17A				
289-601-924-18A				
289-601-924-19A				
289-601-924-1A				
289-601-924-20A				
289-601-924-21A				
289-601-924-22A				
289-601-924-23A				
289-601-924-24A				
289-601-924-25A				
289-601-924-26A				
289-601-924-27A				
289-601-924-28A				
289-601-924-29A				
289-601-924-2A				
289-601-924-30A				
289-601-924-31A				
289-601-924-32A				
289-601-924-33A				
289-601-924-34A				
289-601-924-35A				
289-601-924-36A				
289-601-924-37A				
289-601-924-38A				
289-601-924-39A				
289-601-924-3A				
289-601-924-40A				
289-601-924-41A				
289-601-924-42A				
289-601-L108				
LOCKHEED PN 671970-109				
289-601-L110				
LOCKHEED PN 671970-115				
289-601-L111				
LOCKHEED PN 671970-113				
289-601-L112 289-664				
802165-00 802165-02				
802266-02 802266-03				
802896-02 802896-03				
803201-00 803201-01				
803201-03 803201-05				
803201-07 289-601-207				
289-601-208 289-601-208-1				
289-601-208-2 289-601-21				
289-601-210 289-601-211				
289-601-211-1 289-601-211-2				
289-601-211-3 289-601-212				
BOEING LB PN BWM7002-517				
289-601-212-1 289-601-213				
289-601-213-1 289-601-213-2				
289-601-214				
BOEING LB PN BWM7002-523				
289-601-214-1 289-601-215				
289-601-216 289-601-216-1				
289-601-217 289-601-218				
BOEING LB PN BWM7002-519				
289-601-218-1 289-601-256				
K-G PN 26795-002				



	289-601-257 K-G PN 48531-127 289-601-258 289-601-259 289-601-26 289-601-27 289-601-274 BOEING PN 417T4205-101 289-601-276 BOEING PN 417T4205-102 289-601-278 BOEING PN 417T4205-103 289-601-28 289-601-280 BOEING PN 417T4205-104 289-601-282 BOEING PN 417T4205-105 289-601-284 BOEING PN 417T4205-117 289-601-289 BOEING PN 417T4205-128 289-601-29 289-601-291 BOEING PN 417T4205-129 289-601-293 BOEING PN 417T4205-130 289-601-295 BOEING PN 417T4205-138 289-601-296 BOEING PN 417T4205-139 289-601-298 BOEING PN 417T4205-140 289-601-299 BOEING PN 417T4205-141 289-601-352 BOEING PN 417T4205-74 289-601-352-1 BOEING PN 417T4205-174 289-601-3 289-601-30 289-601-302 289-601-302-1 289-601-351 289-601-351-1 289-601-301 289-601-301-1 289-601-353 289-601-353-1 289-601-354 289-601-355 289-601-356 289-601-357 289-601-358 289-601-359 289-601-360 289-601-361 289-601-361-1 289-601-362 289-601-362-1 289-601-37 BOEING PN 417T4205-200 289-601-375 BOEING PN 417T4205-75 289-601-375-1 BOEING PN 417T4205-175 289-601-376 BOEING PN 417T4205-76 289-601-376-1 BOEING PN 417T4205-176 289-601-377 BOEING PN 417T4205-77 289-601-453-3 289-601-453-4 289-601-5 BOEING LB PN BWM7002-1 289-601-50 289-601-6 289-601-6-1 289-601-7 289-601-700 BOEING PN 10-60137-120 289-601-701 BOEING PN 10-60137-121 289-601-702				
--	--	--	--	--	--



	BOEING PN 10-60137-122 289-601-703 BOEING PN 10-60137-123 289-601-704 BOEING PN 10-60137-124 289-601-705 BOEING PN 10-60137-125 289-601-706 BOEING PN 10-60137-126 289-601-707 BOEING PN 10-60137-127 289-601-708 BOEING PN 10-60137-128 289-601-709 BOEING PN 10-60137-129 289-601-710 BOEING PN 10-60137-130 289-601-711 BOEING PN 10-60137-131 289-601-712 BOEING PN 10-60137-132 289-601-713 BOEING PN 10-60137-133 289-601-714 BOEING PN 10-60137-134 289-601-715 BOEING PN 10-60137-135 289-601-716 BOEING PN 10-60137-136 289-601-717 BOEING PN 10-60137-137 289-601-724-48A 289-601-724-4A EROS PN MW39-04 289-601-724-5A EROS PN MW39-05 289-601-724-6A EROS PN MW39-06 289-601-724-7A EROS PN MW39-07 289-601-724-8A EROS PN MW39-08 289-601-724-9A EROS PN MW39-019 289-601-725 289-601-726 BOEING PN 10-60137-166 289-601-727 BOEING PN 10-60137-167 289-601-728 BOEING PN 10-60137-168 289-601-729 BOEING PN 10-60137-169 289-601-730 BOEING PN 10-60137-170 289-601-731 BOEING PN 10-60137-171 289-601-732 BOEING PN 10-60137-172 289-601-733 BOEING PN 10-60137-173 289-601-734 BOEING PN 10-60137-174 289-601-735 BOEING PN 10-60137-175 289-601-736 BOEING PN 10-60137-176 289-601-737				
--	---	--	--	--	--



	BOEING PN 10-60137-177 289-601-738 BOEING PN 10-60137-178 289-601-739 BOEING PN 10-60137-179 289-601-740 BOEING PN 10-60137-180 289-601-741 BOEING PN 10-60137-181 289-601-857 BOEING PN 10-60137-101 289-601-858 BOEING PN 10-60137-102 289-601-859 BOEING PN 10-60137-103 289-601-860 BOEING PN 10-60137-104 289-601-861 BOEING PN 10-60137-105 289-601-862 BOEING PN 10-60137-106 289-601-863 BOEING PN 10-60137-107 289-601-864 BOEING PN 10-60137-108 289-601-865 BOEING PN 10-60137-109 289-601-866 BOEING PN 10-60137-110 289-601-867 BOEING PN 10-60137-111 289-601-868 BOEING PN 10-60137-112 289-601-869 BOEING PN 10-60137-113 289-601-871 BOEING PN 10-60137-114 289-601-872 BOEING PN 10-60137-115 289-601-873 BOEING PN 10-60137-116 289-601-874 BOEING PN 10-60137-117 289-601-875 BOEING PN 10-60137-118 289-601-876 BOEING PN 10-60137-33 289-601-877 BOEING PN 10-60137-119 289-601-878 NSN 1660-01-285-2424 289-601-879 BOEING PN 10-60137-189 289-601-880 289-601-924-43A 289-601-924-44A 289-601-924-45A 289-601-924-46A 289-601-924-47A 289-601-924-48A 289-601-924-49A 289-601-924-4A 289-601-924-50A 289-601-924-51A 289-601-924-52A 289-601-924-53A 289-601-924-54A				
--	--	--	--	--	--



289-601-924-55A				
289-601-924-56A				
289-601-924-57A				
289-601-924-58A				
289-601-924-59A				
289-601-924-5A				
289-601-924-60A				
289-601-924-61A				
289-601-924-62A				
289-601-924-63A				
289-601-924-64A				
289-601-924-65A				
289-601-924-66A				
289-601-924-67A				
289-601-924-68A				
289-601-924-69A				
289-601-924-6A				
289-601-924-70A				
289-601-924-71A				
289-601-924-72A				
289-601-924-73A				
803201-10	803201-11			
803201-13	803201-15			
803201-17	803201-20			
803203-01	803204-00			
803204-01	803204-02			
803204-03	289-601-219			
289-601-22	289-601-221			
289-601-222	289-601-222-1			
289-601-223	289-601-223-1			
289-601-224	289-601-224-1			
289-601-224-2	289-601-225			
289-601-226	289-601-227			
289-601-228	289-601-228-1			
289-601-228-10				
289-601-228-11				
289-601-228-2	289-601-228-3			
289-601-228-4	289-601-228-5			
289-601-228-6	289-601-228-7			
289-601-303	289-601-303-1			
289-601-304	289-601-304-1			
289-601-305	289-601-305-1			
289-601-306				
BOEING PN 417T4205-222				
289-601-308	289-601-310-01			
289-601-317	289-601-317-1			
289-601-318	289-601-318-1			
289-601-319	289-601-319-1			
289-601-32	289-601-320			
289-601-320-1	289-601-321			
289-601-322	289-601-328			
289-601-328-1	289-601-329			
289-601-329-1	289-601-330			
289-601-377-1				
BOEING PN 417T4205-177				
289-601-378				
BOEING PN 417T4205-78				
289-601-379				
BOEING PN 417T4205-79				
289-601-379-1				
BOEING PN 417T4205-179				
289-601-38				
BOEING PN 417T4205-201				
289-601-381				
BOEING PN 417T4205-81				
289-601-381-1				
BOEING PN 417T4205-181				



	289-601-382 BOEING PN 417T4205-82 289-601-382-1 BOEING PN 417T4205-182 289-601-383 BOEING PN 417T4205-83 289-601-383-1 BOEING PN 417T4205-183 289-601-384 BOEING PN 417T4205-91 289-601-384-1 BOEING PN 417T4205-191 289-601-385 BOEING PN 417T4205-142 289-601-385-1 BOEING PN 417T4205-198 289-601-387 BOEING PN 417T4205-143 289-601-387-1 BOEING PN 417T4205-199 289-601-389 BOEING PN 417T4205-144 289-601-39 BOEING PN 417T4205-202 289-601-390 BOEING PN 417T4205-145 289-601-392 BOEING PN 417T4205-167 289-601-394 BOEING PN 417T4205-151 289-601-395 BOEING PN 417T4205-152 289-601-718 BOEING PN 10-60137-138 289-601-719 BOEING PN 10-60137-139 289-601-720 BOEING PN 10-60137-140 289-601-721 BOEING PN 10-60137-145 289-601-722 289-601-723 289-601-724-10A EROS PN MW39-10 289-601-724-11A EROS PN MW39-11 289-601-724-12A EROS PN MW39-12 289-601-724-13A EROS PN MW39-13 289-601-724-14A EROS PN MW39-14 289-601-724-15A EROS PN MW39-15 289-601-724-16A EROS PN MW39-16 289-601-724-17A EROS PN MW39-17 289-601-724-18A EROS PN MW39-18 289-601-724-19A EROS PN MW39-19 289-601-724-1A EROS PN MW39-01 289-601-724-20A EROS PN MW39-20 289-601-724-21A EROS PN MW39-21				
--	--	--	--	--	--



	289-601-724-22A EROS PN MW39-22 289-601-724-23A EROS PN MW39-23 289-601-724-24A EROS PN MW39-24 289-601-724-25A EROS PN MW39-25 289-601-742 BOEING PN 10-60137-182 289-601-743 BOEING PN 10-60137-266 289-601-744 BOEING PN 10-60137-267 289-601-745 BOEING PN 10-60137-268 289-601-746 BOEING PN 10-60137-269 289-601-747 BOEING PN 10-60137-270 289-601-748 BOEING PN 10-60137-271 289-601-749 BOEING PN 10-60137-272 289-601-750 BOEING PN 10-60137-273 289-601-751 BOEING PN 10-60137-274 289-601-752 BOEING PN 10-60137-275 289-601-753 BOEING PN 10-60137-276 289-601-754 BOEING PN 10-60137-277 289-601-755 BOEING PN 10-60137-278 289-601-756 BOEING PN 10-60137-279 289-601-757 BOEING PN 10-60137-280 289-601-758 BOEING PN 10-60137-281 289-601-759 BOEING PN 10-60137-282 289-601-760 BOEING PN 10-60137-183 289-601-761 BOEING PN 10-60137-184 289-601-762 BOEING PN 10-60137-185 289-601-763 BOEING PN 10-60137-186 289-601-764 BOEING PN 10-60137-187 289-601-765 BOEING PN 10-60137-188 289-601-881 BOEING PN 10-60137-190 289-601-882 BOEING PN 10-60137-191 289-601-883 BOEING PN 10-60137-192 289-601-884 BOEING PN 10-60137-193 289-601-885 BOEING PN 10-60137-194 289-601-886				
--	--	--	--	--	--



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 69 of 93

		BOEING PN 10-60137-195 289-601-887 BOEING PN 10-60137-196 289-601-888 BOEING PN 10-60137-197 289-601-900 289-601-901-01 289-601-901-02 289-601-901-03 289-601-903-01 BOEING 17B2N8001-503 289-601-903-02 BOEING 17B2N8001-505 289-601-903-03 BOEING 17B2N8001-507 289-601-924-100 289-601-924-101 289-601-924-102 289-601-924-103 289-601-924-104 289-601-924-105 289-601-924-10A 289-601-924-11A 289-601-924-74A 289-601-924-75A 289-601-924-76A 289-601-924-77A 289-601-924-78A 289-601-924-79A 289-601-924-7A 289-601-924-80A 289-601-924-81A 289-601-924-82A 289-601-924-83A 289-601-924-84A 289-601-924-85A 289-601-924-86A 289-601-924-87A 289-601-924-88A 289-601-924-89A 289-601-924-8A 289-601-924-90A 289-601-924-91A 289-601-924-92A 289-601-924-93A 289-601-924-94A 289-601-924-95A 289-601-924-96A 289-601-924-97A 289-601-924-98A 289-601-924-99A 289-601-924-9A 289-601AF NSN 1660-00-382-9434 289-601AF2 NSN 1660-00-158-4626 289-601-L105 289-601-L106 LOCKHEED PN 671970-105 289-601-L107 LOCKHEED PN 671970-107 803204-04 803204-10 803204-11 803204-12 803204-13 803204-14 803447-01 803589-01				
329.	174692-N7, 174682-N7, 174692-N9	174692-N7, 174682-N7, 174692-N9	Fullface Crew Mask	B/E Aerospace	35-11-23	Functional Testing and Repair;



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 70 of 93

			Assembly	Inc.		Excepting Repair of demand Regulator assembly [A/C CMS]
Cylinders Maintenance						
330.	891000-series	891311-00, 891311-11 891311-14, 891311-19 891311-31, 891311-23 891411-00, 891411-14 891411-17, 891411-19 891411-31, 891511-00 891511-11, 891511-14 891511-31, 891111-14 891211-14	Stationary Cylinder and Valve Assembly	AVOX SYSTEMS INC.	35-28-91	Overhaul [A/C CMS]
331.	9700-series	9700-A1A-BF20B 9700-A1A-BF23A 9700-A1A-BF23B 9700-A1A-B20A 9700-A1A-YY0N 9700-B1X-BBF25A 9700-C1A-BB23A 9700-C1A-BF20A 9700-C1A-BF20B 9700-C1A-BF20D 9700-C1A-BF23A 9700-C1A-BF23AM 9700-C1A-BF23B 9700-C1A-BF23C 9700-C1A-BF23D 9700-C1A-B23AN 9700-C1A-F20D 9700-C1A-F23A 9700-C1A-F23AM 9700-C1A-F23AN 9700-C1A-F23BN 9700-C1A-YY0N 9700-C1A-YY0S 9700-C1A-Y0N 9700-C1B-BF23D 9700-C1C-BF23A 9700-C2C-F20D 9700-C3C-BF20D 9700-D1A-BBF20B 9700-D1A-BBF23A 9700-F1A-BF23AM 9700-F1A-BF23AN 9700-FAB-F23BN 9700-F1A-BY23AN 9700-F1A-YYY0N 9700-C1A-FF23A 9700-F1A-F23AKN 9700-G2A-BF10A 9700-G2A-BF10B 9700-G2A-BF10D 9700-G2A-BF20A 9700-G2A-BF20B 9700-G2A-BF20D 9700-G2A-BF23A 9700-G2A-BF23B 9700-G2A-BF23D 9700-G2A-F10AN 9700-G2A-F10D 9700-G2A-F20AN 9700-G2A-F20D 9700-G2A-F23AN 9700-G2A-F23D	Portable Cylinder Assembly	AVOX SYSTEMS INC.	35-31-55	Overhaul [A/C CMS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 71 of 93

		9700-H2A-BF10BN 9700-H2A-BF20BN 9700-H2A-BF23BN 9700-G2A-BF25A 9700-G2A-FF25B 9700-G2X-Y0N				
332.	9800-series	9800-1C1A-E20A 9800-1C1A-E20B 9800-1C1A-E23B 9800-1C1A-F20A 9800-1C1A-F20B 9800-1C1A-F23A 9800-1C1A-X0N 9800-1C1A-X0X 9800-1D1A-BF23A 9800-1D1A-F23AN 9800-2C1A-E20A 9800-2C1A-E20B 9800-2C1A-E20C 9800-2C1A-E20D 9800-2C1A-E23A 9800-2C1A-E23B 9800-2C1A-F23A 9800-2C1A-F23D 9800-2C1A-X0M 9800-2C1A-X0X 9800-2D1A-BF20B 9800-2D1A-BF23A 9800-2D1A-E23AM 9800-2D1A-F20BM 9800-2D1A-F23AM 9800-2D1A-F23AN 9800-2D1A-F23BM 9800-9C1A-E23A 9800-9C1A-X0X 9800-9D1A-F23AM 9800-1D1A-F-23AM 9800-8C1B-F23A	Portable Cylinder Assembly	AVOX SYSTEMS INC.	35-31-55	Overhaul [A/C CMS]
333.	803668-01 807434-01	803668-01 807434-01	Portable Cylinder Assembly	AVOX SYSTEMS INC.	35-31-55	Overhaul [A/C CMS]
334.	5500-series	5500-A1A-AB23A 5500-A1A-AE20B 5500-A1A-A15A 5500-A1A-A15D 5500-A1A-A23A 5500-A1A-BB20A 5500-A1A-BB23A 5500-A1A-BB25A 5500-A1A-BC30A 5500-A1A-BE20A 5500-A1A-BE20B 5500-A1A-BF10A 5500-A1A-BF20A 5500-A1A-BF20B 5500-A1A-BF23A 5500-A1A-BF23B 5500-A1A-BF23D 5500-A1A-BF25A 5500-A1A-BF25B 5500-A1A-BF30A 5500-A1A-BF30B 5500-A1A-B15A 5500-A1A-B20A 5500-A1A-C30B 5500-A1A-EE23A	Portable Cylinder Assembly	AVOX SYSTEMS INC.	35-32-18	Overhaul [A/C CMS]



	5500-A1A-E20A 5500-A1A-E20B 5500-A1A-E20BK 5500-A1A-F20A 5500-A1A-F20B 5500-A1A-F20D 5500-A1A-F23A 5500-A1A-F25A 5500-A1A-F25AN 5500-A1A-X0K 5500-A1A-YY0E 5500-A1B-F23A 5500-A1M-AA15B 5500-A1N-BF23A 5500-A1Q-B30AD 5500-A1Q-B30D 5500-A1Q-B30DA 5500-A1R-EE25A 5500-A1S-B20A 5500-A1S-CC30A 5500-A1T-BF20B 5500-A1U-BF23A 5500-A1U-BF25A 5500-A1U-EE25A 5500-A1U-F30AN 5500-A1V-BF20B 5500-A1V-BF23B 5500-A1V-BF25B 5500-A1V-F20BM 5500-A1W-BF23A 5500-A1W-BF25A 5500-A1W-BF30A 5500-A1X-BF20B 5500-A1X-FF23A 5500-A1Y-BF20B 5500-A3A-BF23A 5500-A5A-BG20B 5500-A6A-BF23A 5500-A6A-BF23B 5500-A6A-BG20B 5500-A6A-F20B 5500-A6P-FF23A 5500-A6S-B30A 5500-A6U-E30A 5500-A6W-BB15A 5500-A6W-BB23A 5500-A6W-BB25A 5500-A6W-FF23A 5500-A6W-F30AP 5500-A9A-B30A 5500-A9S-AC25A 5500-A9S-BF30A 5500-A9S-G30A 5500-A9W-EE25A 5500-A9X-F23A 5500-A1A-AE20B 5500-A1A-A15D 5500-A1A-A23A 5500-A1A-BB20A 5500-A1A-BF20A 5500-A1A-BF30B 5500-A1A-EE23A 5500-A1A-E20BK 5500-A1A-G20B 5500-A1A-Y0N 5500-A1P-BF23A 5500-A1S-B15A				
--	---	--	--	--	--



	5500-A1U-F25A 5500-A1W-BF15A 5500-A6W-FF15A 5500-B1A-BE20B 5500-B1A-BF20A 5500-B1A-BF20B 5500-B1A-BF20D 5500-B1A-BF23A 5500-B1A-BF23B 5500-B1A-BF25A 5500-B1A-B30A 5500-B1A-CF23A 5500-B1A-CF25A 5500-B1A-FF20A 5500-B1A-F20D 5500-B1A-F23A 5500-B1A-F30A 5500-B1A-YY0E 5500-B1A-Y0P 5500-B1S-B20A 5500-B1S-B20AP 5500-B1U-BF23A 5500-B1V-BE20B 5500-B1V-BF20B 5500-B1W-BF10A 5500-B1W-BF20A 5500-B1X-YY0E 5500-B1X-Y0E 5500-B3B-F25A 5500-B6C-BF25A 5500-B6U-BF25A 5500-B6U-F30AN 5500-B1A-C20A 5500-B1A-E20A 5500-B6A-BF23B 5500-B6A-F23B 5500-B6X-X0K 5500-B1A-BF30A 5500-C1A-BB20B 5500-C1A-BF20A 5500-C1A-BF20B 5500-C1A-BF20D 5500-C1A-BF23A 5500-C1A-BF23B 5500-C1A-BF23D 5500-C1A-BF30A 5500-C1A-BG23A 5500-C1A-B23A 5500-C1A-EG23A 5500-C1A-EY20BM 5500-C1A-E20BN 5500-C1A-E23AN 5500-C1A-FF20A 5500-C1A-FF23A 5500-C1A-FG23A 5500-C1A-FH23A 5500-C1A-FY30BN 5500-C1A-F20B 5500-C1A-F23A 5500-C1A-F23AP 5500-C1A-F25A 5500-C1A-X0K 5500-C1A-YY0E 5500-C1A-YY0EE 5500-C1A-YY0N 5500-C1A-Y0E 5500-C1A-Y0EE				
--	---	--	--	--	--



	5500-C1A-Y0N 5500-C1B-BF23D 5500-C1B-E25A 5500-C1N-BF23A 5500-C1S-BF20A 5500-C1S-BY20AE 5500-C1S-B20AE 5500-C1S-B20AP 5500-C1S-F23A 5500-C1T-BF20B 5500-C1T-F20BM 5500-C1U-BF23A 5500-C1U-BF25A 5500-C1U-BF30A 5500-C1U-B23AN 5500-C1U-B25A 5500-C1U-FF23A 5500-C1U-F20AN 5500-C1U-F23A 5500-C1U-F30AN 5500-C1V-FG20B 5500-C1V-FY30AN 5500-C1V-FY30BN 5500-C1V-F20BM 5500-C1V-F30AN 5500-C1V-F30BN 5500-C1W-BF15A 5500-C1W-BF23A 5500-C1W-BF30A 5500-C1X-BF20B 5500-C1X-Y0N 5500-C1Y-BF20B 5500-C6A-BF15A 5500-C6A-BF20B 5500-C6A-BF23A 5500-C6A-BF23B 5500-C6A-BF23D 5500-C6A-BF25A 5500-C6A-BG30B 5500-C6A-EF20A 5500-C6A-F20A 5500-C6A-F20AR 5500-C6A-F23AE 5500-C6A-F30A 5500-C6A-F30AE 5500-C6A-F30AN 5500-C6A-G30AN 5500-C6A-YY0N 5500-C6A-Y0N 5500-C6E-BF23D 5500-C6R-BF23D 5500-C6T-G20B 5500-C6U-BF30A 5500-C6U-F23AP 5500-C6U-F30AN 5500-C6W-FF23A 5500-C6X-BF23D 5500-C9A-BF20A 5500-C9A-BF20B 5500-C9A-FF10A 5500-C9S-F30A 5500-C9U-F30AN 5500-C9U-H20A 5500-C9W-FF10A 5500-C9W-Y0E 5500-C9X-BB20A 5500-C1A-F20BN				
--	---	--	--	--	--



5500-C1A-F23AK	
5500-C1A-Y0EN	
5500-C1A-Y0P	
5500-C1S-B23A	
5500-C1V-G30BN	
5500-C1W-FF20A	
5500-C1W-FF30A	5500-C6A
5500-C6A-BF20A	
5500-C9A-E30A	
5500-D1A-BF23A	
5500-D1A-E20A	
5500-D1A-E25A	
5500-D1A-F23A	
5500-D1A-YY0E	
5500-D1A-YY0P	
5500-D1A-Y0E	
5500-D1A-Y0N	
5500-D1P-CC20A	
5500-D1W-BB15A	
5500-D1X-Y0E	
5500-D1X-Y0N	
5500-D6A-YY0E	
5500-D6A-YY0N	
5500-D6A-Y0E	
5500-D6P-BF25A	
5500-D6X-HH30A	
5500-D1A-Y0P	
5500-D1W-BF23A	5500-D6A
5500-D6A-Y0N	
5500-F1X-FH20A	
5500-F6A-BB30A	
5500-G1A-B23A	
5500-G1A-F20A	
5500-G1W-EE30A	
5500-J1A-ABE20B	
5500-J1A-BBF20A	
5500-J1A-BBF20B	
5500-J1A-BBF23A	
5500-J1A-BEG20B	
5500-J1A-BFL23A	
5500-L1W-BBF23A	
5500-L6C-BBF23A	
5500-L6C-BBF25A	
5500-L6U-BBF25A	
5500-L6W-BBF25A	
5500-L6W-BEF23A	
5500-L6W-FF23AP	
5500-M1A-BBB20B	
5500-M1A-BH23A	
5500-M1A-BH23AN	
5500-M1A-FFF25A	
5500-M1A-LLL30A	
5500-M1A-X0K	
5500-M1W-BF23AM	
5500-M6W-BBF10A	
5500-M6W-FF23AN	
5500-M6W-FF23AP	
5500-P6U-EEE20A	
5500-S6X-YY0E	
5500-S6X-YY0N	
5500-S9X-YYY0E	
5500-S9X-YY0E	
5500-F6A-Y0N	
5500-G1A-BB20A	
5500-G1A-Y0N	
5500-G1A-Y0P	5500-R6A
5500-S1X-BBF10A	



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 76 of 93

		5500-S6X-BBF10A 5500-N6S-BF10A 5500-Q6X-BF10A 5500-Q6X-BF23A 5500-Q6X-YY0E 5500-Q6X-F5AM 5500-Q6X-H10AM 5500-T2A-CC30B 5500-T2A-YY0N 5500-T2A-Y0E 5500-T2A-Y0N 5500-T2A-Y0T 5500-T2W-BF25AN 5500-T2W-FF30A 5500-V2X 5500-W2A-BF25AN 5500-W2W-BF25AN				
335.	5600-series	5600-1B1A-E20B 5600-1B1A-F23A 5600-1C1A-B20A 5600-1C1A-B20B 5600-1C1A-B23A 5600-1C1A-E20A 5600-1C1A-E20B 5600-1C1A-E20D 5600-1C1A-E23A 5600-1C1A-E23B 5600-1C1A-F20A 5600-1C1A-F20B 5600-1C1A-F23A 5600-1C1A-F23B 5600-1C1A-F25A 5600-1C1A-X0K 5600-1C1A-X0M 5600-1C1A-Y0M 5600-1C1B-X0K 5600-1C1B-X0M 5600-1C1B-Y0M 5600-1C6A-E20A 5600-1C6A-F23A 5600-1C6A-F23B 5600-1C6A-X0K 5600-1D1A-F23A 5600-1D1A-F30A 5600-1D6A-E20A 5600-1G1A-F20A 5600-1M1A-F20BM 5600-2A1A-B23B 5600-2A1A-F23A 5600-2B1A-E20A 5600-2B1A-F20A 5600-2B1A-Y0E 5600-2C1A-B20B 5600-2C1A-C20A 5600-2C1A-E20A 5600-2C1A-E20B 5600-2C1A-E20C 5600-2C1A-E20D 5600-2C1A-E23A 5600-2C1A-E23B 5600-2C1A-F20A 5600-2C1A-F30A 5600-2C1A-G25A 5600-2C1A-X0K 5600-2C1A-X0M 5600-2C1A-Y0M 5600-2C1A-Y0N 5600-2C1B-X0K	Portable Cylinder Assembly	AVOX SYSTEMS INC.	35-32-18	Overhaul [A/C CMS]



	5600-2C5A-E20B 5600-2C6A-B23A 5600-2C6A-F23A 5600-2C6A-X0K 5600-2C9F-X0K 5600-2D1A-X0K 5600-2D1B-X0K 5600-2G1A-B20B 5600-2J1A-BF23A 5600-2M1A-BF23A 5600-2M1A-BG23A 5600-1A1A-X0K 5600-1B1A-X0K 5600-1C1A-BF23A 5600-1C9A-F30A 5600-1C9F-F30A 5600-1M1A-BF23A 5600-2C1A-B23A 5600-2C1A-F23A 5600-2C1A-F23D 5600-2C5A-X0K 5600-8B6A-X0K 5600-8B9A-X0K 5600-8C1A-F23A 5600-8C1A-X0K 5600-8C1B-F23A 5600-8C6A-F23A 5600-8C6A-X0K 5600-8D1A-X0K 5600-8D1A-Y0N 5600-8G2A-X0K 5600-8G6A-X0K 5600-9C1A-F20A 5600-9C1A-F20B 5600-9C1A-F23A 5600-9C1A-X0K 5600-9C1A-Y0E 5600-9C1A-Y0N 5600-9C6A-X0K 5600-9C6A-Y0K 5600-9C9A-F10A 5600-9D1A-E20B 5600-9D1A-E30A 5600-9D1A-F23A 5600-9D1A-G30A 5600-9D1A-X0K 5600-9D1A-Y0N 5600-9D1B-X0K 5600-9D9A-X0K 5600-9G1A-X0K 5600-9J6A-F30AN 5600-9M1A-HH20A 5600-9M6A-BF30A 5600-9M6A-FF30A 5600-9M6A-F30AE 5600-9M6A-F30AN 5600-9M9F-F30AN 5600-9P1A-Y0EN 5600-9P6A-F30AN 5600-9A1A-B25A 5600-9A1A-X0K 5600-9B2A-X0K 5600-9B6A-X0K 5600-9C1B-X0K 5600-9C1C-BF23A 5600-9C9A-F30A 5600-9D6A-B5A				
--	--	--	--	--	--



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 78 of 93

		5600-9D6A-X0K 5600-9D6A-Y0E 5600-9L6C-BF25A 5600-9M1A-F23AM 5600-9M1A-G20BN 5600-9T1A-F25A 5600-9C1A-E25A				
336.	801307 series	801307-00, 801307-01 801307-02, 801307-03 801307-04, 801307-05 801307-06, 801307-07 801307-08, 801307-09 801307-10, 801307-11 801307-20, 801307-21 801307-22, 801307-23 801307-24, 801307-25	Cylinder and Valve Assemblies	AVOX SYSTEMS INC.	35-23-07	Overhaul [A/C CMS]
337.	897 series	89710015, 89713015 89715050, 89718015 89718050, 89720050 89721022, 89723015 89726022, 89726050 89726077, 89728040 89730050, 89730077 89790022, 89790050 89793015, 89793050 89793077, 89794015 89794040, 89794050 89794077, 89795050 89796015, 89796077 89798015, 89798022 89798050, 89798077 89799015, 89799050	Cylinder and Valve Assembly	AVOX SYSTEMS INC.	35-21-93	Overhaul [A/C CMS]
338.	3552-series	3552AAAAAACXCD 3552AAADAACXCD 3552AAAEAAACXCD 3552AAAWAACXCD 3552AAAXAACXCD 3552AAAYAACXCD 3552BAAAAACXCD 3552BAADAACXCD 3552BAAWAACXCD 3552BAAXAACXCD 3552BAAYAACXCD 3552CAAAAACXCD 3552CAADAACXCD 3552CAAWAACXCD 3552CAAXAACXCD 3552CAAYAACXCD	Portable Oxygen Cylinder Assembly	AVOX SYSTEMS INC.	35-35-52	Overhaul [A/C CMS]
339.	4441013-series 4441111-series	4441013-050 4441111-050; -077; -115	Oxygen Cylinder Assembly	B/E Aerospace, Inc.	35-22-03	All maintenance including repair [A/C CMS]

Rating item: C18 Protection ice/rain/fire

Item n°	Part number / Model series	Full part numbers / Models	Description	Manufacturer	CMM / ATA chapter	Work scope Level / Component maintenance shop
A/C Fire Extinguishers Maintenance						
340.	898052	898052	Portable Fire Extinguisher (Halon)	Kidde Aerospace	26-21-39	Overhaul [A/C CMS]
341.	74 -series	74-00,74-20 74-21,76-00	Portable Fire Extinguisher	TOTAL Feuerschutz	26-24-05	Overhaul

MOE
ISSUE 4 REV.0
Part 1.9

PART-145 AMO Ref. EASA.145.0381

14.12.2017



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 79 of 93

			(Halon) 1/1,2/2,5 AIR TOTAL	Gmbh		[A/C CMS]
342.	34100005-1	34100005-1	378 CUBIC INCH FIRE EXTINGUISHER	PACIFIC SCIENTIFIC HTL/KIN- TECH DIVISION	26-20-04	Overhaul [A/C CMS]
343.	34600012- series	34600012-22, 34600012-24 34600012-25, 34600012-27 34600013-21, 34600013-23 34600013-26	630 CUBIC INCH FIRE EXTINGUISHERS	PACIFIC SCIENTIFIC HTL/KIN- TECH DIVISION	26-22-21	Overhaul [A/C CMS]
344.	17343-116- 825F	17343-116-825F	Aircraft Overheat Detector	FENWAL Safety Systems	26-14-07	Overhaul [A/C CMS]
345.	33600005- series	33600005-1 33600005-3	224 CUBIC INCH FIRE EXTINGUISHERS	PACIFIC SCIENTIFIC HTL/KIN- TECH DIVISION	26-20-03	Overhaul [A/C CMS]
346.	34600016 34600017 34600025-1	34600016 34600017 34600025-1	630 AND 800 CUBIC INCH FIRE EXTINGUISHERS	PACIFIC SCIENTIFIC HTL/KIN- TECH DIVISION	26-20-06	Overhaul [A/C CMS]
347.	33700002 33700005 33700006-1	33700002 33700005 33700006-1	224 CUBIC INCH FIRE EXTINGUISHERS	PACIFIC SCIENTIFIC HTL/KIN- TECH DIVISION	26-22-30	Overhaul [A/C CMS]

Rating item: C19 Windows / Repair

Item n°	Part number / Model series	Full part numbers / Models	Description	Manufacturer	SRM / ATA chapter	Work scope Level / Component maintenance shop
A/C Windows / Repair						
A/C Boeing B737						
348.	140N2138-X	140N2138-1 140N2138-2	PANE	BOEING	56-21-00	Repair (polishing) [A/C SRS]
349.	65-45791-X	65-45791-2 65-45791-4 65-45791-1	PANE	BOEING	56-21-00	Repair (polishing) [A/C SRS]

Rating item: C20 Structural

A/C Repair of A/C parts						
Item n°	Part number / Model series	Full part numbers / Models	Description	Manufacturer	SRM / ATA chapter	Work scope Level / Component maintenance shop
A/C Airbus A-320 FAMILY						
350.	D533717440 XX	D53371744000, D53371744002 D53371744004, D53371744006 D53371744008, D53371744010 D53371744012, D53371744014 D53371744016, D53371744018 D53371744020, D53371744026 D53371744022, D53371744028 D53371744030	FAIRING, ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
351.	D533717470 XX	D53371747000, D53371747002 D53371747004, D53371747006	FAIRING, ASSY	AIRBUS	53-35-11	Repair [A/C SRS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 80 of 93

		D53371747008, D53371747010				
352.	D533717300 XX	D53371730002, D53371730004 D53371730006, D53371730008 D53371730010, D53371730012 D53371730050, D53371730052 D53371730054, D53371730056	FAIRING, ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
353.	D533717150 XX	D53371715000, D53371715004 D53371715006, D53371715010 D53371715012, D53371715014 D53371715050, D53371715054 D53371715052, D53371715058 D53371715056, D53371715062 D53371715064, D53371715066	FAIRING, ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
354.	D533717400 XX	D53371740000, D53371740002 D53371740004, D53371740006 D53371740010, D53371740008 D53371740012, D53371740014 D53371740050, D53371740052 D53371740054	FAIRING, ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
355.	D533717050 XX	D53371705000, D53371705004 D53371705006, D53371705008 D53371705010, D53371705014 D53371705016, D53371705050 D53371705054, D53371705052 D53371705058, D53371705056 D53371705062, D53371705064 D53371705066	FAIRING, ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
356.	D533717000 XX	D53371700000, D53371700002 D53371700004, D53371700050 D53371700052, D53371700054 D53371700056	FAIRING, ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
357.	D533717170 XX	D53371717000, D53371717002 D53371717004, D53371717006 D53371717008, D53371717010 D53371717012, D53371717016 D53371717014, D53371717020 D53371717018, D53371717024 D53371717026, D53371717028	DOOR, ACCESS RH ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
358.	D533717070 XX	D53371707000, D53371707002 D53371707004, D53371707006 D53371707008, D53371707010 D53371707012, D53371707016 D53371707014, D53371707020 D53371707018, D53371707024 D53371707026, D53371707028	DOOR, ACCESS LH ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
359.	D533717320 XX	D53371732000, D53371732002 D53371732004, D53371732006 D53371732008, D53371732010 D53371732012, D53371732014 D53371732016	PANEL, BLOWOUT ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
360.	D533717420 XX	D53371742000, D53371742002 D53371742004, D53371742006 D53371742008, D53371742010 D53371742014, D53371742012 D53371742018, D53371742016 D53371742022, D53371742004 D53371742026	DOOR, ACCESS ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
361.	D533716320 OX	D53371632004 D53371632005	FAIRING, ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
362.	D533750100 XX	D53375010000, D53375010001 D53375010002, D53375010003 D53375010004, D53375010005 D53375010006, D53375010007 D53375010008, D53375010009 D53375010010, D53375010011	FAIRING, ASSY	AIRBUS	53-35-11	Repair [A/C SRS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 81 of 93

		D53375010012, D53375010013				
363.	D533717650 OX	D53371765000, D53371765002 D53371765004, D53371765006 D53371765050, D53371765052	FAIRING, FR42-FR43 RH ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
364.	D533717640 XX	D53371764000, D53371764004 D53371764054, D53371764056	FAIRING, FR42-FR43 RH ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
365.	D533717860 XX	D53371786000, D53371786001 D53371786002, D53371786003 D53371786004, D53371786005 D53371786006, D53371786007 D53371786008, D53371786009 D53371786010, D53371786011 D53371786012, D53371786013 D53371786014, D53371786015	FAIRING, UPPER FR45 ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
366.	D533717750 XX	D53371775000, D53371775002 D53371775004, D53371775006 D53371775008, D53371775050	FAIRING, FR45-FR47 RH ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
367.	D533717770 XX	D53371777000, D53371777004 D53371777052, D53371777054 D53371777056, D53371777058	FAIRING, FR45-FR47 RH ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
368.	D533717700 XX	D53371770000, D53371770002 D53371770004, D53371770006 D53371770008, D53371770050 D53371770052, D53371770054 D53371770056, D53371770058	FAIRING, FR45-FR47 LH ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
369.	D533717720 OX	D53371772000 D53371772004	FAIRING, FR45-FR47 LH ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
370.	D533717620 XX	D53371762000, D53371762002 D53371762004, D53371762006 D53371762050, D53371762052	FAIRING, FR42 LH ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
371.	D533717560 XX	D53371756000, D53371756004 D53371756054, D53371756056	FAIRING, FR42 LH ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
372.	D533717600 XX	D53371760000, D53371760002 D53371760004, D53371760006 D53371760050, D53371760052 D53371760054, D53371760056	FAIRING, FR42-FR43 LH ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
373.	D533717580 OX	D53371758000, D53371758004	FAIRING, FR42-FR43 LH ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
374.	D533718000 XX	D53371800006, D53371800050 D53371800052, D53371800054	FAIRING, FR44-FR4 ASSY	AIRBUS	53-35-11	Repair [A/C SRS]
375.	D546101220 00X0	D5461012200000 D5461012200040	PANEL ASSY 413AL, 423AL	AIRBUS	54-52-11	Repair [A/C SRS]
376.	D546305250 XX00	D5463052500100 D5463052501600	PANEL ASSY PAINTED 414AR, 424AR	AIRBUS	53-35-11	Repair [A/C SRS]
377.	D546305260 XX00	D5463052600200 D5463052603200	PANEL ASSY PAINTED (LH) 413CL	AIRBUS	53-35-11	Repair [A/C SRS]
378.	D546305260 0300	D5463052600300 D5463052603300	PANEL ASSY- PAINTED (RH)424CR	AIRBUS	53-35-11	Repair [A/C SRS]
379.	D546101860 0200	D5461018600200	COVER (LH) 413DL	AIRBUS	53-35-11	Repair [A/C SRS]
380.	D546101860 0300	D5461018600300	COVER (RH) 423DL	AIRBUS	53-35-11	Repair [A/C SRS]

381.	D546186700 0200	D5461867000200	COVER (LH) 413DT	AIRBUS	53-35-11	Repair [A/C SRS]
382.	D546186700 0300	D5461867000300	COVER (RH) 423DT	AIRBUS	53-35-11	Repair [A/C SRS]
383.	D545303220 X000	D5453032200000 D5453032203000	FILLET ASSY- OUTER,PAINTED (LH) 471AL	AIRBUS	54-53-11	Repair [A/C SRS]
384.	D545304260 0000	D5453042600000	FILLET ASSY- OUTER,PAINTED (LH) 471AL	AIRBUS	54-53-11	Repair [A/C SRS]
385.	D545303220 X100	D5453032200100 D5453032203100	FILLET ASSY OUTER,PAINT (RH) 482AR	AIRBUS	54-53-11	Repair [A/C SRS]
386.	D545304260 0100	D5453042600100	FILLET ASSY- OUTER,PAINTED (RH) 482AR	AIRBUS	54-53-11	Repair [A/C SRS]
387.	D545303750 X000	D5453037500000 D5453037503000	FILLET ASSY- INNER,PAINTED (LH) 472AR	AIRBUS	54-53-11	Repair [A/C SRS]
388.	D545302120 0200	D5453021200200	FILLET ASSY- INNER,PAINTED (LH) 472AR	AIRBUS	54-53-11	Repair [A/C SRS]
389.	D545303750 0100	D5453037500100	FILLET ASSY- INNER,PAINTED (RH)	AIRBUS	54-53-11	Repair [A/C SRS]
390.	D545302120 0300	D5453021200300	FILLET ASSY- INNER,PAINTED (RH)	AIRBUS	54-53-11	Repair [A/C SRS]
391.	D545185130 0000	D5451851300000 D5451851300200 D5451851300400	PANEL ASSY (LH) 471BL	AIRBUS	54-53-11	Repair [A/C SRS]
392.	D545185020 0200	D5451850200200	PANEL ASSY (LH) 471BL	AIRBUS	54-53-11	Repair [A/C SRS]
393.	D545185130 0X00	D5451851300100 D5451851300300	FILLET ASSY- OUTER (RH) 481BR	AIRBUS	54-53-11	Repair [A/C SRS]
394.	D545185020 0300	D5451850200300	FILLET ASSY- OUTER (RH) 481BR	AIRBUS	54-53-11	Repair [A/C SRS]
395.	D545185140 0X00	D5451851400000 D5451851400200	FILLET ASSY- INNER (LH) 471BR	AIRBUS	54-53-11	Repair [A/C SRS]
396.	D545185030 0200	D5451850300200	FILLET ASSY- INNER (LH) 471BR	AIRBUS	54-53-11	Repair [A/C SRS]
397.	D545303700 XX61	D5453037000461 D5453037003661 D5453037000561 D5453037003761	FILLETS INSTL- PYLON-TO- WING	AIRBUS	54-53-11	Repair [A/C SRS]
398.	D545303790 X000	D5453037900000 D5453037903000	FILLET ASSY- OUTER,PAINTED (LH) 471CL	AIRBUS	54-53-11	Repair [A/C SRS]
399.	D545302150 0400	D5453021500400	FILLET ASSY- OUTER,PAINTED (LH) 471CL	AIRBUS	54-53-11	Repair [A/C SRS]
400.	D545303790 X100	D5453037900100 D5453037903100	FILLET ASSY- OUTER,PAINTED (RH) 482CR	AIRBUS	54-53-11	Repair [A/C SRS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 83 of 93

401.	D545302150 0500	D5453021500500	FILLET ASSY- OUTER,PAINTED (RH) 482CR	AIRBUS	54-53-11	Repair [A/C SRS]
402.	D545304200 0X61	D5453042000461 D5453042000661 D5453042000561 D5453042000761	FILLETS INSTL- PYLON-TO- WING	AIRBUS	54-53-11	Repair [A/C SRS]
403.	D545185180 0X00	D5451851800000 D5451851800200	FILLET ASSY- OUTER (LH) 471DL	AIRBUS	54-53-11	Repair [A/C SRS]
404.	D545185070 0200	D5451850700200	FILLET ASSY- OUTER (LH) 471DL	AIRBUS	54-53-11	Repair [A/C SRS]
405.	D545185180 0X00	D5451851800100 D5451851800300 D5451851800500	FILLET ASSY- OUTER (RH) 481DR	AIRBUS	54-53-11	Repair [A/C SRS]
406.	D545185070 0300	D5451850700300	FILLET ASSY- OUTER (RH) 481DR	AIRBUS	54-53-11	Repair [A/C SRS]
407.	D545185190 0X00	D5451851900000 D5451850800200	FILLET ASSY- OUTER (LH) 475BL	AIRBUS	54-53-11	Repair [A/C SRS]
408.	D545303770 XX00	D5453037700000 D5453037703000 D5453037703200	FILLET ASSY- BLOWOUT OUTER (LH) 471BL	AIRBUS	54-53-11	Repair [A/C SRS]
409.	D545301690 0400	D5453016900400	FILLET ASSY- BLOWOUT OUTER (LH) 471BL	AIRBUS	54-53-11	Repair [A/C SRS]
410.	D545303770 XX00	D5453037700100 D5453037703100 D5453037703300	PANEL ASSY (RH) 482BR	AIRBUS	54-53-11	Repair [A/C SRS]
411.	D545301690 0500	D5453016900500	FILLET ASSY- BLOWOUT, OUTER 482BR	AIRBUS	54-53-11	Repair [A/C SRS]
412.	D000103900 00XX	D00010390000BQ D0001039000051 D0001039000055 D0001039000057 D00010390000AG D00010390000AK D00010390000AP D00010390000AW D00010390000BG D00010390000BH D00010390000BS	FAIRING ASSY- MOVABLE, LH	AIRBUS	54-55-11	Repair [A/C SRS]
413.	D000103900 01XX	D00010390001BQ D0001039000151 D0001039000155 D0001039000157 D00010390001AG D00010390001AK D00010390001AP D00010390001AW D00010390001BG D00010390001BH D00010390001BS	FAIRING ASSY- AFT MOVABLE (RH)	AIRBUS	54-55-11	Repair [A/C SRS]
414.	D545100020 00XX	D54510002000AM D5451000200051 D5451000200053	FAIRING ASSY- MOVABLE, (LH)	AIRBUS	54-55-11	Repair [A/C SRS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 84 of 93

		D5451000200055 D5451000200057 D5451000200059 D54510002000AK D54510002000AL D54510002000AP D54510002000AX D54510002000AT D54510002000AR D54510002000AV D54510002000AY D54510002000BA				
415.	D545100020 01XX	D54510002001AM D5451000200151 D5451000200153 D5451000200155 D5451000200157 D5451000200159 D54510002001AK D54510002001AL D54510002001AP D54510002001AT D54510002001AR D54510002001AV D54510002001AY D54510002001BA	FAIRING ASSY- MOVABLE, (RH)	AIRBUS	54-55-11	Repair [A/C SRS]
416.	D545100820 01XX	D5451008200100 D5451008200151	FAIRING ASSY- LOWER 473AR, 483AR	AIRBUS	54-56-11	Repair [A/C SRS]
417.	D545101500 0100	D5451015000100	FAIRING ASSY- LOWER 473AR, 483AR	AIRBUS	54-56-11	Repair [A/C SRS]
418.	D545100820 00XX	D5451008200000 D5451008200051	FAIRING ASSY- LOWER 473AL, 483AL	AIRBUS	54-56-11	Repair [A/C SRS]
419.	D545101500 0000	D5451015000000	FAIRING ASSY- LOWER 473AL, 483AL	AIRBUS	54-56-11	Repair [A/C SRS]
420.	D572513600 0251	D5725136000251	DOOR ASSY	AIRBUS	57-27-05	Repair [A/C SRS]
421.	D572514820 00XX	D5725148200000 D5725148200051 D5725148200052	DOOR ASSY 540BB, 540CB, 640 BB, 640CB	AIRBUS	57-27-05	Repair [A/C SRS]
422.	D573568210 0000	D5735682100000	PANEL - TE UPR (LH)	AIRBUS	57-31-23	Repair [A/C SRS]
423.	D573568210 0100	D5735682100100	PANEL - TE UPR (RH)	AIRBUS	57-31-23	Repair [A/C SRS]
424.	D573568230 0000	D5735682300000	PANEL - TE LWR (LH)	AIRBUS	57-31-23	Repair [A/C SRS]
425.	D573568230 0100	D5735682300100	PANEL - TE LWR (RH)	AIRBUS	57-31-23	Repair [A/C SRS]
426.	D574435810 XX00X	D5744358101600Z D5744358100800Z D5744358101200A D5744358101600A	PANEL ASSY- ACCESS,NO 1 (LH) 521AB	AIRBUS	57-41-05	Repair [A/C SRS]
427.	D574435810 XX00X	D5744358101700Z D5744358100900Z D5744358101300A D5744358101700A	PANEL ASSY- ACCESS,NO 1 (RH) 621AB	AIRBUS	57-41-05	Repair [A/C SRS]
428.	D574435820 2X00X	D5744358202000Z D5744358202000A D5744358202600A	PANEL ASSY- ACCESS, BLOW	AIRBUS	57-41-05	Repair [A/C SRS]


**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 85 of 93

		D5744358202800A	OFF,NO 2 (LH) 521CB			
429.	D574435820 2X00X	D5744358202100Z D5744358202100A D5744358202700A D5744358202900A	PANEL ASSY- ACCESS,BLOW OFF, NO 2 (RH) 621CB	AIRBUS	57-41-05	Repair [A/C SRS]
430.	D574435830 XX00X	D5744358302000Z D5744358301200A D5744358302000A D5744358302600A D5744358302800A	PANEL ASSY- ACCESS,BLOW OFF, NO 3 (LH) 521EB	AIRBUS	57-41-05	Repair [A/C SRS]
431.	D574435830 XX00X	D5744358302100Z D5744358301300A D5744358302100A D5744358302700A D5744358302900A	PANEL ASSY- ACCESS,BLOW OFF,NO 3 621EB	AIRBUS	57-41-05	Repair [A/C SRS]
432.	D574435850 XX00X	D5744358502000Z D5744358501200Z D5744358501600Z D5744358502000A D5744358502600A D5744358502800A	PANEL ASSY- ACCESS,BLOW OFF, NO 5 (LH) 522CB	AIRBUS	57-41-05	Repair [A/C SRS]
433.	D574435850 XX00X	D5744358502100Z D5744358501300Z D5744358501700Z D5744358502100A D5744358502700A D5744358502900A	PANEL ASSY- ACCESS,BLOW OFF, NO 5 (RH) 622CB	AIRBUS	57-41-05	Repair [A/C SRS]
434.	D574435870 XX00X	D5744358702000Z D5744358700800 D5744358700800Z D5744358701600Z D5744358702000A D5744358702600A D5744358702800A	PANEL ASSY- ACCESS,BLOW OFF, NO 7 (LH) 522LB	AIRBUS	57-41-05	Repair [A/C SRS]
435.	D574435870 XX00X	D5744358702100Z D5744358700900 D5744358700900Z D5744358701700Z D5744358702100A D5744358702700A	PANEL ASSY- ACCESS,BLOW OFF, NO 7 622LB	AIRBUS	57-41-05	Repair [A/C SRS]
436.	D574435880 XX00X	D5744358802000Z D5744358800800 D5744358800800Z D5744358801600Z D5744358802000A D5744358802600A D5744358802800A	PANEL ASSY- ACCESS,BLOW OFF, NO 8 522NB	AIRBUS	57-41-05	Repair [A/C SRS]
437.	D53132010000	D53132010000	NOSE RADOME	AIRBUS	53-15-11	Repair [A/C SRS]
438.	D53110477000 0X	D5311047700003 D5311047700004 D5311047700005 D5311047700007	NOSE RADOME	AIRBUS	53-15-11	Repair [A/C SRS]
Item n°	Part number / Model series	Full part numbers / Models	Description	Manufacturer	Ref. of the SRM-ROHR (CFM56-5A)	Work scope Level / Component maintenance shop
439.	238-series 642-series	238-0101-501 238-0101-503 238-0101-505 238-2101-501 238-2101-503 238-2101-505 642-1000-501 642-1000-505	INLET COWL	Goodrich	54-10-00	Repair [A/C SRS]
440.	238-series	238-0301-501 238-0301-519 238-0301-503 238-0301-521	FAN COWL	Goodrich	54-20-00	Repair



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 86 of 93

		238-0301-505 238-0301-523 238-0301-507 238-0301-525 238-0301-509 238-0301-527 238-0301-511 238-0301-529 238-0301-513 238-0301-531 238-0301-515 238-0301-533 238-0301-517 238-0301-535				[A/C SRS]
441.	238-series	238-1105 238-1106	FAN THRUST REVERSER DOOR ASSEMBLY	Goodrich	54-30-00	Repair [A/C SRS]
Item n°	Part number / Model series	Full part numbers / Models	Description	Manufacturer	Ref. of the SRM-ROHR (CFM56-5B)	Work scope Level / Component maintenance shop
442.	642-series	642-1000-501 642-1000-505	INLET COWL	Goodrich	54-10-00	Repair [A/C SRS]
443.	642-series	642-3001-503 642-3001-505 642-3001-507 642-3001-509 642-3001-511 642-3001-513 642M3001-503 642M3001-505 642-3002-503 642-3002-519 642-3002-505 642-3002-521 642-3002-507 642-3002-523 642-3002-509 642-3002-525 642-3002-511 642-3002-513 642-3002-517 642-3002-515 642M3002-503 642M3002-505 642M3002-507 642M3002-509	FAN COWL	Goodrich	54-20-00	Repair [A/C SRS]
444.	642-series	642-3801 642-3802	FAN THRUST REVERSER DOOR ASSEMBLY	Goodrich	54-30-00	Repair [A/C SRS]
A/C BOEING B737NG						
445.	315A2101	315A2101-41 315A2101-146	THRUST REVERSER INNER WALL	BOEING	54-30-01	Repair [A/C SRS]
446.	315A2102	315A2102-41 315A2102-146	THRUST REVERSER INNER WALL	BOEING	54-30-01	Repair [A/C SRS]
447.	314-2200	314-2200-3 314-2200-15	FAN COWL ASSY L/H (L/H ENG)	BOEING	54-20-01	Repair [A/C SRS]
448.	314-2200	314-2200-11 314-2200-17	FAN COWL ASSY R/H (L/H ENG)	BOEING	54-20-01	Repair [A/C SRS]
449.	314-2200	314-2200-5, 314-2200-16 314-2200-20, 314-2200-21	FAN COWL ASSY L/H (R/H ENG)	BOEING	54-20-01	Repair [A/C SRS]
450.	314-2200	314-2200-12 314-2200-18	FAN COWL ASSY R/H (R/H ENG)	BOEING	54-20-01	Repair [A/C SRS]
451.	314-2200	314-2200-1, 314-2200-13 314-2200-22	FAN COWL ASSY - LH	BOEING	54-20-01	Repair [A/C SRS]
452.	314-2200	314-2200-10 314-2200-14	FAN COWL ASSY - RH	BOEING	54-20-01	Repair [A/C SRS]
453.	314-2100	314-2100-2, 314-2100-3 314-2100-4	INLET COWL	BOEING	54-10-01	Repair [A/C SRS]
454.	284A0801	284A0801-3, 284A0801-7 284A0801-11, 284A0801-16 284A0801-17B	RADOME INSTL	BOEING	53-10-72	Repair [A/C SRS]



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 87 of 93

455.	284A1801	284A1801-3 284A1801-4	RADOME INSTL	BOEING	53-10-72	Repair [A/C SRS]
456.	1001002	1001002-1A, 1001002-1C 1001002-2A, 1001002-2B 1001002-5B, 1001002-6B 1001002-7B, 1001002-8B 1001002-7D, 1001002-8 1001002-107, 1001002-119	RADOME INSTL	BOEING	53-10-72	Repair [A/C SRS]
457.	1001737	1001737	RADOME INSTL	BOEING	53-10-72	Repair [A/C SRS]
A/C BOEING B767						
458.	141T0070-XX	141T0070-5	RADOME	BOEING	53-10-00	Repair [A/C SRS]
459.	284T0052-XX	284T0052-17, 284T0052-21 284T0052-24, 284T0052-28 284T0052-29, 284T0052-30 284T0052-33, 284T0052-35 284T0052-39	RADOME	BOEING	53-10-00	Repair [A/C SRS]
460.	149T7122-XX	149T7122-49, 149T7122-25 149T7122-29, 149T7122-25 149T7122Y49	PANEL ASSY- 191AL	BOEING	53-30-70	Repair [A/C SRS]
461.	149T7122-XX	149T7122-26, 149T7122-30 149T7122-68	PANEL ASSY- 192AR	BOEING	53-30-70	Repair [A/C SRS]
462.	149T7123-XX	149T7123-3 149T7123-41	PANEL ASSY- 191CL	BOEING	53-30-70	Repair [A/C SRS]
463.	149T7123-XX	149T7123-4 149T7123-42	PANEL ASSY- 191CR	BOEING	53-30-70	Repair [A/C SRS]
464.	149T7123-XX	149T7123-7 149T7123-47 149T7123-53	PANEL ASSY- 191EL	BOEING	53-30-70	Repair [A/C SRS]
465.	149T7123-XX	149T7123-8 149T7123-48	PANEL ASSY- 191EL	BOEING	53-30-70	Repair [A/C SRS]
466.	149T7123-XX	149T7123-8 149T7123-48 149T7123-54	PANEL ASSY- 192ER	BOEING	53-30-70	Repair [A/C SRS]
467.	149T7124-XX	149T7124-7 149T7124-25 149T7124-45	ACCESS PANEL 193DL	BOEING	53-30-70	Repair [A/C SRS]
468.	149T7124-XX	149T7124-8 149T7124-26 149T7124-46	ACCESS PANEL 194DR	BOEING	53-30-70	Repair [A/C SRS]
469.	149T7261-XX	149T7261-2 149T7261-7	ACCESS PANEL 193LL	BOEING	53-30-70	Repair [A/C SRS]
470.	149T7450-XX	149T7450-19, 149T7450-24 149T7450-25, 149T7450-37	ACCESS PANEL 193JL	BOEING	53-30-70	Repair [A/C SRS]
471.	149T7215-XX	149T7215-3	ACCESS PANEL 193RL	BOEING	53-30-70	Repair [A/C SRS]
472.	149T7257-XX	149T7257-4 149T7257-14	ACCESS PANEL 194HR	BOEING	53-30-70	Repair [A/C SRS]
473.	149T7255-XX	149T7255-3 149T7255-36	ACCESS PANEL 194NR	BOEING	53-30-70	Repair [A/C SRS]
474.	149T7215-XX	149T7215-4	ACCESS PANEL 194PR	BOEING	53-30-70	Repair [A/C SRS]
475.	313T3360-XX	313T3360-1, 313T3360-89 313T3360-2, 313T3360-90 313T3360-73, 313T3360-125 313T3360-127, 313T3360-153 313T3360-161, 313T3360-183 313T3360-199, 313T3360-3	TRAILING EDGE ASSY	BOEING	53-30-70	Repair [A/C SRS]



		313T3360-74, 313T3360-126 313T3360-128, 313T3360-153 313T3360-154, 313T3360-162 313T3360-184, 313T3360-200 313T3360-4				
--	--	---	--	--	--	--

Repair of A/C parts on basis of REPAIR MANUAL – Repair Methods
(without issuing of CRS, - under Serviceable tag only)
Shop – performer is A/C Repair Shop [A/C SRS]

<i>Item n°</i>	<i>ATA</i>	<i>ATA Sub Chapter Repairs' manuals</i>	<i>Description of repair's technology</i>	<i>Kind of the A/C Repairs</i>
1.	51	SRM 51-21-11	Application of Protective Treatment	Repair of Metal structure parts
2.	51	AMM 51-00-50 SRM 51-22-00	Corrosion Prevention	Repair of Metal structure parts
3.	51	SRM 51-25-00	Heat Treatment	Repair of Metal structure parts
4.	51	SRM 51-26-00	Forming	Repair of Metal structure parts
5.	51	SRM 51-26-10 SRM 51-26-11	Bending	Repair of Metal structure parts
6.	51	SRM 51-24-00 SRM 51-26-12 SRM 51-26-20	Joggling	Repair of Metal structure parts
7.	51	SRM 51-27-11	Cutting and Machining	Repair of Metal structure parts
8.	51	SRM 51-27-12	Cutting and Machining	Repair of Glare structure parts
9.	51	SRM 51-20-07 SRM 51-27-21	Cutting and Machining	Repair of Composite structure parts
10.	51	SRM 51-29-00 SRM 51-29-11	Flap Peening	Repair of Metal structure parts
11.	51	SRM 51-20-06	Shot Peening	Repair of Metal structure parts
12.	51	SRM 51-42-11 SRM 51-40-02	Fastener Installation and Removal	Repair of Metal structure parts
13.	51	SRM 51-42-12	Fastener Installation and Removal	Repair of Glare structure parts
14.	51	SRM 51-42-21	Fastener Installation and Removal	Repair of Composite structure parts
15.	51	SRM 51-40-08 SRM 51-46-11	Countersinking	Repair of Metal structure parts
16.	51	SRM 51-46-13	Countersinking	Repair of Glare structure parts
17.	51	SRM 51-46-21	Countersinking	Repair of Composite structure parts
18.	51	SRM 51-48-00	Cold expansion of fastener holes	Repair of Metal structure parts
19.	51	SRM 51-71-15	Filling of Existing Countersinks	Repair of Metal structure parts
20.	51	SRM 51-46-12	Spot Facing Procedure	Repair of Metal structure parts
21.	51	SRM 51-72-00	Restoration of Pneumatic parts	Repair of Pneumatics' parts
22.	51	SRM 51-72-11	Replacement of Structural Components	Repair of Metal structure parts Repair of Composite structure parts
23.	51	SRM 51-72-12	Replacement of Bushes	Repair of Metal structure parts
24.	51	SRM 51-73-00	Rectification of Minor Damage	Repair of Metal structure parts Repair of Composite structure parts
25.	51	SRM 51-73-11	Rectification of Negligible Damage	Repair of Metal structure parts Repair of Composite structure parts
26.	51	SRM 51-73-12	Installation of a freeze plug	Repair of Metal structure parts
27.	51	SRM 51-74-00	Removal of corrosion	Repair of Metal structure parts
28.	51	AMM 51-21-72	Primer - Cleaning/Painting	Repair of Metal structure parts Repair of Composite structure parts
29.	51	AMM 51-21-81	Abrasion Resistant Teflon Finish - Cleaning/Painting	Repair of Metal structure parts Repair of Composite structure parts



30.		AMM 51-27-00	Polishing	Repair of Metal structure parts
31.	51	SRM 51-75-11 AMM 51-21-11	Paint Removal	Repair of Metal structure parts Repair of Composite structure parts
32.	51	SRM 51-75-12 AMM 51-21-72 AMM 51-21-99	Restoration of Paint Coating	Repair of Metal structure parts Repair of Composite structure parts
33.	51	SRM 51-20-05 SRM 51-21-51 SRM 51-73-00 SRM 51-76-11	Remove and restoration of sealing	Repair of Metal structure parts Repair of Composite structure parts
34.	51	SRM 51-76-12	Remove and restoration of Fuel Tank Sealing	Repair of Metal structure parts
35.	51	SRM 51-77-12	Repair of Solid laminate skin	Repair of Composite structure parts
36.	51	SRM 51-77-13	Repair of Sandwich Structures	Repair of Metal structure parts Repair of Composite structure parts
Item n°	ATA	ATA Sub Chapter	Description of A/C parts	Kind of the A/C Repairs
37.	25	AMM 25-00-00 AMM 25-10-00 AMM 25-13-00 AMM 25-20-00 AMM 25-01-12 AMM 25-21-39 AMM 25-11-00	<u>Cabin Equipment/Furnishings:</u> 1. Overhead stowage compartments; 2. Sidewall linings and ceiling panels; 3. Door linings; 4. Door frame linings; 5. Flight compartment panels.	– Crushed-Core and Sandwich Panel Repair; – Decorative Surface Repair; – Decorative Tedlar Cover removal / installation; – Decorative film repair / replacement; – Repair for Nomex Honeycomb Sandwich Panels with a Decorative Tedlar Cover; – Repair for Tedlar Covers of Aluminum Laminates; – Perforated Panel Repair; – Repair for Polycarbonate (Lexan), Ultem, and Declar Plastics; – Urethane Foam Repair; – Paint coat repair.
38.	25	AMM 25-50-00 AMM 25-55-00 AMM 25-51-00 AMM 25-51-30 AMM 25-52-00 AMM 25-52-01 AMM 25-52-60 AMM 25-52-00 AMM 25-52-10 AMM 25-52-11	<u>Cargo Compartment:</u> 1. Floor panels in passenger cabin; 2. Floor panels in FWD, AFT and Bulk cargo compartments; 3. Sidewall panels in FWD, AFT and Bulk cargo compartments; 4. Ceiling panels in FWD, AFT and Bulk cargo compartments; 5. Decompression panels.	– Composite repair of solid laminate panels; – Composite repair of sandwich panels; – Metal sheet repair of solid laminate panels; – Metal sheet repair of sandwich panels.
39.	52	SRM 52-00-00 SRM 52-10-00 SRM 52-11-00 SRM 52-13-00 SRM 52-20-00 SRM 52-30-00 SRM 52-40-00 SRM 52-60-00 SRM 52-80-00 SRM 52-90-00	<u>Doors:</u> 1. Forward passenger/crew door; 2. Aft passenger/crew door; 3. Passenger compartment emergency exit; 4. Forward cargo compartment door; 5. Aft cargo compartment door; 6. Bulk cargo compartment door;	– Metal skin repair of parts described in ATA subchapter 52; – Metal Repair of parts described in ATA subchapter 52; – Composite skin repair of parts described in ATA subchapter 52; – Composite Repair of parts described in ATA subchapter 52.



		SRM 52-10-01 SRM 52-10-02 SRM 52-20-01 SRM 52-20-02 SRM 52-30-01 SRM 52-30-02 SRM 52-40-01 SRM 52-40-02 SRM 52-40-70 SRM 52-60-01 SRM 52-60-02 SRM 52-80-02 SRM 52-80-70 SRM 52-80-90 SRM 52-12-00 SRM 52-43-00 SRM 52-44-00 SRM 52-45-00 SRM 52-51-00	7. Access doors; 8. Avionic compartment doors; 9. Access fairings-APU exhaust; 10. APU access doors; 11. FWD and AFT tail cone doors; 12. Service doors; 13. Lavatory service doors-FWD and AFT; 14. External power receptacle door; 15. Portable water service door; 16. Access door-fuel panel; 17. Entrance stairs door; 18. Main landing gear doors; 19. FWD and AFT nose gear doors; 20. Overpressure release APU compartment door.	
40.	53	SRM 53-00-00 SRM 53-02-00 SRM 53-00-00 SRM 53-10-00 SRM 53-20-00 SRM 53-30-00 SRM 53-40-00 SRM 53-50-00 SRM 53-60-00 SRM 53-70-00 SRM 53-80-00 SRM 53-10-01 SRM 53-30-01 SRM 53-60-01 SRM 53-80-01 SRM 53-91-00 SRM 53-97-00 SRM 53-10-72 AMM 53-52-00	<u>Fuselage:</u> 1. Nose FWD fuselage; 2. Forward fuselage; 3. Center fuselage; 4. Rear fuselage; 5. Cone/Rear fuselage; 6. Fuselage section 41; 7. Fuselage section 43; 8. Fuselage section 45; 9. Fuselage section 46; 10. Fuselage section 48.	– Metal skin repair of parts described in ATA subchapter 53; – Metal Repair of parts described in ATA subchapter 53; – Composite skin repair of parts described in ATA subchapter 53; – Composite Repair of parts described in ATA subchapter 53; – Fabrication of elements or/and whole floor panel on basis of 145.A.42(c) regulation in case of inexpediency of any kind of repair (ref. Sibir Technics FCCL actual revision).
41.	54	SRM 54-00-00 SRM 54-10-00 SRM 54-20-00 SRM 54-30-00 SRM 54-30-01 SRM 54-30-02 SRM 54-30-70 SRM 54-30-90 SRM 54-40-00 SRM 54-50-00 SRM 54-56-00 SRM 54-11-00 SRM 54-12-00 SRM 54-21-00 SRM 54-22-00 SRM 54-32-00	<u>Nacelles/Pylons:</u> 1. Pylon panels; 2. Pylon box; 3. Pylon Spars; 4. Pylon Ribs; 5. Pylon-to-wing attach fittings; 6. Pylon-to-engine attach fittings; 7. Pylon doors; 8. FWD fairing; 9. Skin panels and doors; 10. Cantilever structure; 11. Junction boxes; 12. Pylon frame; 13. AFT fixed fairing; 14. Fittings; 15. AFT movable fairing; 16. Lower fairing; 17. Fillets; 18. Inlet cowl skin;	– Metal repair of parts described in ATA subchapter 54; – Composite repair of parts described in ATA subchapter 54; – Acoustic panels repair of parts described in ATA subchapter 54.



			19. Inlet cowl structure; 20. Inlet cowl auxiliary structure; 21. Fan cowl skin; 22. Fan cowl structure; 23. Fan cowl attachment fittings; 24. Fan cowl auxiliary structure; 25. Fan duct cowl and thrust reverser skin; 26. Fan duct cowl and thrust reverser structure; 27. Fan duct cowl and thrust reverser attachment fittings; 28. Thrust reverser skin; 29. Thrust reverser structure; 30. Core cowl skin; 31. Core cowl structure; 32. Core cowl attachment fittings; 33. Primary exhaust skin; 34. Integrated nozzle assembly; 35. Strut skin; 36. Strut structure; 37. Strut fairing skin; 38. Strut fairing structure; 39. Strut attachment fittings.	
42.	55	AMM 55-12-02 AMM 55-32-03 SRM 55-00-00 SRM 55-10-00 SRM 55-20-00 SRM 55-30-00 SRM 55-40-00 SRM 55-11-00 SRM 55-12-00 SRM 55-31-00 SRM 55-34-00	<u>Stabilizers:</u> 1. Trimmable horizontal stabilizer spar box; 2. Trimmable horizontal stabilizer skin plates; 3. Trimmable horizontal stabilizer ribs; 4. Trimmable horizontal stabilizer spars; 5. Trimmable horizontal stabilizer leading edge; 6. Trimmable horizontal stabilizer trailing edge; 7. Trimmable horizontal stabilizer tips; 8. Trimmable horizontal stabilizer apron; 9. Trimmable horizontal stabilizer attach fittings; 10. Elevator spar box; 11. Elevator skin plates; 12. Elevator spar; 13. Elevator trailing edge; 14. Elevator leading edge; 15. Elevator leading edge access panels; 16. Elevator leading edge ribs; 17. Elevator outboard tip and inboard end; 18. Elevator attach fittings; 19. Vertical stabilizer spar box; 20. Vertical stabilizer ribs; 21. Vertical stabilizer leading edge; 22. Vertical stabilizer trailing edge; 23. Vertical stabilizer attach fittings; 24. Rudder main structure; 25. Rudder spars; 26. Rudder tip; 27. Rudder attach fittings.	– Metal repair of parts described in ATA subchapter 55; – Composite repair of parts described in ATA subchapter 55.
43.	56	AMM 56-11-11 AMM 56-11-21 AMM 56-21-00	<u>Windows:</u>	Repair of window described in ATA subchapter 56.



		SRM 56-00-00	1. Flight compartment window structure;	
		SRM 56-20-00	2. Cabin Window structure;	
		SRM 56-30-00	3. Door window structure.	
44.	57	AMM 57-41-01 SRM 57-00-00 SRM 57-10-00 SRM 57-20-00 SRM 57-30-00 SRM 57-40-00 SRM 57-50-00 SRM 57-60-00 SRM 57-70-00 SRM 57-41-01 SRM 57-42-01 SRM 57-43-01 SRM 57-51-01 SRM 57-53-01 SRM 57-12-00 SRM 57-13-00 SRM 57-14-00 SRM 57-24-00 SRM 57-43-00 SRM 57-52-00 SRM 57-53-00 SRM 57-54-00 SRM 57-61-00 SRM 57-71-00	Wings: 1. Center wing main structure; 2. Center wing skins and plating; 3. Center wing ribs; 4. Center wing stringers and stiffeners; 5. Center wing beams; 6. Center wing spars; 7. Center wing fittings; 8. Center wing access covers; 9. Outer wing main structure; 10. Outer wing skins and plating; 11. Outer wing ribs; 12. Outer wing stringers and stiffeners; 13. Outer wing beams; 14. Outer wing spars; 15. Outer wing fittings; 16. Outer wing access covers; 17. Outer wing attachments; 18. Wing access panels; 19. Wing tip structure; 20. Wing tip fence; 21. Sharklet; 22. Leading edge and leading edge devices; 23. Leading edge skin and plating; 24. Leading edge ribs; 25. Leading edge stringers and stiffeners; 26. Leading edge spars; 27. Leading edge access covers and panels; 28. Slats structure; 29. Inboard and outboard flap skin; 30. Inboard and outboard flap structure; 31. Flap fairings skin; 32. Aileron structure; 33. Spoilers structure.	– Metal repair of parts described in ATA subchapter 57; – Composite repair of parts described in ATA subchapter 57.
45.	72	AMM 72-20-00 AMM 72-24-00 AMM 72-54-00 AMM 72-56-00 AMM 72-00-00 AMM 72-21-00 AMM 72-23-00	Engine: 1. HPC rotor blades 2. Fan and booster assembly 3. Fan blade 4. Splitter fairing and stage 1 booster vane assembly 5. Fan frame assembly 6. Fan inlet case assembly 7. Turbine frame assembly	– Spinner cones repair; – Fan blades repair; – Splitter fairing and stage 1 booster vane assembly; – Aft acoustic panels repair; – Fan frame repair; – Fan inlet case repair; – Turbine frame repair.

Soft Furnishing Cabin Interior Sewing Workshop capabilities

Item n°	Description complete set	Description items	Manufacturer	CMM / ATA chapter	Work scope Level / Soft Furnishing Cabin Interior Sewing Workshop
1.	Seats' Cover Set from original manufacturers for Customer A/C fleet	i. Cover Backrest (Back) ii. Cover Bottom iii. Cover Headrest	The original manufacturers / vendors are mentioned by actual IPL (CMM) of	25	a. Restored repair based on actual CMM / approved Job Card



**SIBIR
TECHNICS**

A/C Component Maintenance.
Internal No of doc. is HC.ST2-QSME1/1/9, ref. M.O.E. §§1.9, 1.11.2
Component Capability List

Rev. #51
of 05 / 07 / 2019
page 93 of 93

	based on actual CMMs	iv. Cover Padding v. Cover Shroud vi. Cover Pocket	Seat model		
2.	Curtains' (soft dividers) Set from original manufacturers for Customer A/C fleet based on actual AMMs	i. Curtain ii. Strap	The original manufacturers / vendors are mentioned by actual IPC (AMM) of A/C type	25	a. Restored repair based on actual AMM / approved Job Card b. Fabrication on basis of 145.A.42(c) regulation in case of inexpediency of sewing and any other kind of repair (ref. Sibir Technics FCCL actual revision).
3.	Floor carpets set from original manufacturers for Customer A/C fleet based on actual AMMs	i. A/C Cabin Floor carpets	The original manufacturers / vendors are mentioned by actual IPC (AMM) of A/C type		a. Fabrication of elements or/and whole floor carpets set on basis of 145.A.42(c) regulation in case of inexpediency of sewing and any other kind of repair (ref. Sibir Technics FCCL actual revision).
4.	Bag from original manufacturers for Customer A/C fleet based on actual IPC (AMM)	DEMO Bag i. Life vest Bag ii. Extension Belts iii. Bag	The original manufacturers / vendors are mentioned by actual IPC (AMM) of A/C type	25	a. Restored repair based on actual IPC / approved Job Card

Approved by the Sibir Technics AMO Quality Assurance Manager,

Yuri Khordikov

05-July-2019